



FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

GIA

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB382S

Ref. No : TAX/08/18/2052

Reg. Date : 08/09/2014

Vehicle Type : TAXI

Make : TOYOTA PRIUS

Model : PRIUS

Name of Driver : ABDUL JALEEL BIN KADER

MYDIN

Type of Accident : SIDE SWIPE

Date / Time of Accident : 12/08/2018 05:30:00 PM

Accident Reported Date / Time: 13/08/2018 12:00:00 AM

Surveyor is Required? : Yes

Survey by :

Vehicle is Towed Back? : No

Towed Back Date/Time :

Replacement Vehicle issued? : No

Accident Repair Job Card No : 000024097508

Special Instruction to ARC, if any :

DROVE IN / SLF3845K

Prepared Date : 13/08/2018 12:03:11 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36U405748503 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC Adjusted by Surveyor, if applicable

Total Labout Charges : 845.00 0.00

Total Spray Painting Charges : 1,314.00 0.00

 Total Material Charges
 : 3,528.82
 3,528.82

 Other Charges
 : 580.00
 0.00

 Other Charges
 : 580.00
 0.00

 TOTAL
 : 6,267.82
 0.00

 Lum Sum Total
 : 6,250.00
 0.00

 No. of Repair Days
 : 5.00 4.00
 0.00

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 13/08/2018 05:31:32 PM 01/01/1900 12:00:00 AM

7

Prepared / Adjusted Date

Remarks :

Prepared Date : 13/08/2018 05:31:25 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : 0.00 Prepared Date : 8/13/2018 5:31:49 PM

TAX/08/18/2052 Page:

2

Part 1 - Labour Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|----------------------------|--------------------|-------------------------------------|
| TO REPAIR RH FRONT PORTION | 845.00 | 0.00 |
| Total Labour | 845.00 700 | 0.00 |

Part 2 - Spray Painting & Panel Beating Related Works

| 378.00 200 | 0.00 | | |
|------------|--------|--|--|
| 200 | 0.00 | | |
| | 0.00 | | |
| | 0.00 | | |
| | 270-00 | | |

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION | 80.00 50 | 0.00 |
| TO APPLY RUST-PROOFING ON AFFECTED AREA | 100.00 50 | 0.00 |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING | 120.00 60 | 0.00 |
| TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE) | 120.00 | 0.00 |
| TO REPLACE SUNDRY PARTS | 100.00 × 11 | 0.00 |
| TO WASH AND VACUUM | 60.00 × 11 | 0.00 |
| Total Other Costs | 580.00 | 0.00 |

NAZ LKK 15/8/18 1130 L/S 4 DAYS AMES REPORT PHOTO LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock No | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommen d | Surveyor Approved | Photos Attached |
|-----------------------------|---------|----------|------------------------------|-----|--------------------|--------------|---------------------|----------------------|----------------------|--------------------|
| 52119- 47930 | | 6505517 | BUMPER FRT | 1 | 482.00 | 25.00 | 361.50 | Replace | Replace | No XR |
| 52115- 47040 | | 6505515 | BUMPER SUPPORT F/RH | 1 | 76.40 | 25.00 | 57.30 | Replace | Replace | No 7 |
| 81511- 47050 | | | LENS & BODY, FR TURN RH | 1 | 511.80 | 10.00 | 460.62 | Replace | Replace | No X SV |
| 81130- 47500 | | 6505437 | HEAD LAMP RH | 1 | 945.20 | 10.00 | 850.68 | Replace | Replace | No / |
| 53801- 47050 | | 6505557 | FENDER FRT/RH | 1 | 723.40 | 25.00 | 542.55 | Replace | Replace | No XR |
| 75374- 47051 | | | NAME PLATE (HYBRID) | 1 | 51.90 | 25.00 | 38.92 | Replace | Replace | No Ne |
| 53875- 47030 | | 6505553 | FENDER LINER FRT/RH | 1 | 171.70 | 25.00 | 128.77 | Replace | Replace | No ? |
| | | 6503707 | TYRE | 1 | 126.74 | 0.00 | 126.74 | Replace | Replace | No XAO |
| 12611 17140 Frt) | | 6505658 | WHEEL DISC. FRONT | 1 | 1,484.20 | 25.00 | 1,113.15 | Replace | Replace | No XR |
| 37001- 47070 | | 6505528 | DOOR FRT/RH | 1 | 894.40 | 25.00 | 670.80 | Replace | Replace | No XR |
| | | | STICKER DECAL SMRT (DOOR) | 1 | 60.00 | 0.00 | 60.00 | Replace | Replace | No /vel |
| | | Т | OTAL MATERIALS | | | | | 4,411.04 | 4,411.03 | |
| TOTAL MATERIALS(Discounted) | | | | | | | | 3,528.82 | 3,528.82 | |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor | LT Check |
|----------------|-------------------------------|-----------|-----|--------------------|--------------|------------------|-----------|----------|-------------|
| | TOTAL SUPPLEMENTARY MATERIALS | | | | | | | | |

TAX/08/18/2052