



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TPVehicle No. : SLH1864HMake & Model : HONDA GRACE 1.5 DX HYBRIDYear of Manufacture : 2016Chassis No. : GM41104615Ins Company : AIG VS AXAEngine No. : LEB5254629Excess : -Policy No. : -Date of Accident : 15.08.2018Time of Accident : 13:15

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimate**

Case Owner : \_\_\_\_\_

Signature : \_\_\_\_\_

**Parts (a) Cost / List Price Items** \$ 1,571.10Plus/Less 20% \$ 314.22Total of Cost / List \$ 1,256.88(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ -**Total Parts Cost (Appendix A)** \$ 1,256.88**Labour (Appendix B)** \$ 1,140.00**Total Repair Cost** \$ 2,396.88

Contact No

**Frt Counter Operation**

63837103 – Patrick Tia

63837730 - Brenda Ng

63837466 – Rohani

[braddell\\_cr@sparkcarcare.com](mailto:braddell_cr@sparkcarcare.com)**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

[braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : \_\_\_\_\_

Company : \_\_\_\_\_

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLH1864H Case Owner : 0

Make & Model : HONDA GRACE 1.5 DX HY Year Manufacture : 2016

Chassis No : GM41104615 Engine No : LEB5254629

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Bonnet	1		\$ 920.80			
2	Bonnet insulator clips	5		\$ 19.50			
3	Bonnet lock	1		\$ 86.90			
4	Front grille	1		\$ 150.40			
5	Front grille chrome garnish	1		\$ 180.90			
6	Front grille chrome moulding	1		\$ 125.00			
7	Front grille badge	1		\$ 27.10			
8	Front grille top garnish	1		\$ 29.30			
9	Front grille top garnish clips	8		\$ 31.20			
10	0	1					
11	0	1					
12	0	1					
13	0	1					
14	0	1					
15	0	1					
16	0	1					
17	0	1					
18	0	1					
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	1					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Make & Model : NDA GRACE 1.5 DX HYBRID	Year of Manufacture : 2016
----------------------------------------	----------------------------

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*