

CT AUTO PTE LTD

160 Sin Ming Drive, #02-14, Sin Ming AutoCity, Singapore 575722
 Tel: 62666727 Fax: 62666358 Email: admin@ctauto.com.sg
 Business Registration No. 201420132H
 GST Registration No. 201420132H

ESTIMATE

Date: 16/8/2018
 DOA: 16/8/2018

Vehicle No: SJW5158G

Make & Model: Chevrolet Cruze 1.6L A

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear R/H Tail Lamp	\$ 443.00	✓
2	1	Rear R/H Tail Lamp Lower Retainer	\$ 66.90	X
3	1	Rear End Lower Panel	\$ 473.00	X
4	1	Rear R/H Fender Inner Side Shield	\$ 115.60	X
5	1	Rear Bumper Assy	\$ 901.00	✓
6	1	Rear R/H Bumper Bracket	\$ 24.70	X
7	1	Rear Bumper R/H Side Retainer	\$ 48.80	X
8	1	Rear Bumper R/H Reinforcement	\$ 318.90	X
9	1	Rear Exhaust Assy	\$ 948.10	X
10	2	Rear Exhaust Mtg	\$ 85.60	X
			\$ 3,425.60	
		Less 10%	\$ 342.56	
			\$ 3,083.04	
		<u>Special Nett Items</u>		
1		Sundries	\$ 50.00	X
2	1	Rear R/H Tail Lamp Sealant	\$ 50.00	200ml
3	1 set	Rear R/H Tail Lamp Clips	\$ 50.00	250ml
4	1	Rear End Lower Panel Sealant	\$ 120.00	X
5	1 set	Rear R/H Fender Inner Shield Clips	\$ 50.00	X
6	1 set	Rear Bumper Clips	\$ 50.00	✓
7	1 set	Rear Reverse Camera	\$ 380.00	X
			\$ 750.00	
		Total parts	\$ 3,833.04	
S/N	Labour Description		Amount	Amount
1	Labour for panel beating, cut, weld, straighten rear affected area and replace damaged parts.		\$ 800.00	300l
2	To putty and spray painting rear portion.		\$ 600.00	400l
3	To check rear lighting and wiring.		\$ 80.00	20l
4	To apply anti rust proofing to rear affected area.		\$ 250.00	X
5	To remove and install rear parking sensor.		\$ 150.00	50l
	Total labour :		\$ 1,880.00	
	Total parts :		\$ 3,833.04	
	Total labour :		\$ 1,880.00	
	Total repair cost : (Before GST)		\$ 5,713.04	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Withheld
 Resurvey After Paint
 2 days
 1.31.2018 @?