

CT AUTO PTE LTD

160 Sin Ming Drive, #02-14, Sin Ming AutoCity, Singapore 575722
Tel: 62666727 Fax: 62666358 Email: admin@ctauto.com.sg
Business Registration No. 201420132H
GST Registration No. 201420132H

ESTIMATE

Date: 16/8/2018

DOA: 16/8/2018

Vehicle No: SJW5158G

Make & Model: Chevrolet Cruze 1.6L A

1	1	Rear R/H Tail Lamp	405.00	cm	\$	443.00	✓
2	1	Rear R/H Tail Lamp Lower Retainer		cm	\$	66.90	X
3	1	Rear End Lower Panel		cm	\$	473.00	X
4	1	Rear R/H Fender Inner Side Shield		cm	\$	115.60	X
5	1	Rear Bumper Assy	806.40	cm / Bm	\$	901.00	✓
6	1	Rear R/H Bumper Bracket		cm	\$	24.70	X
7	1	Rear Bumper R/H Side Retainer		cm	\$	48.80	X
8	1	Rear Bumper R/H Reinforcement		cm	\$	318.90	X
9	1	Rear Exhaust Assy		cm	\$	948.10	X
10	2	Rear Exhaust Mtg		cm	\$	85.60	X
					\$	3,425.60	
Less 10%					\$	342.56	
					\$	3,083.04	

Special Nett Items

1		Sundries		cm	\$	50.00	X
2	1	Rear R/H Tail Lamp Sealant		cm	\$	50.00	20cm
3	1 set	Rear R/H Tail Lamp Clips		cm	\$	50.00	25cm
4	1	Rear End Lower Panel Sealant		cm	\$	120.00	X
5	1 set	Rear R/H Fender Inner Shield Clips		cm	\$	50.00	X
6	1 set	Rear Bumper Clips		cm	\$	50.00	✓
7	1 set	Rear Reverse Camera		cm	\$	380.00	X
					\$	750.00	
Total parts					\$	3,833.04	

S/N	Labour Description	Amount	Amount
1	Labour for panel beating, cut, weld, straighten rear affected area and replace damaged parts.	\$ 800.00	300
2	To putty and spray painting rear portion.	\$ 600.00	400
3	To check rear lighting and wiring.	\$ 80.00	20
4	To apply anti rust proofing to rear affected area.	\$ 250.00	X
5	To remove and install rear parking sensor.	\$ 150.00	50
Total labour :		\$ 1,880.00	
Total parts :		\$ 3,833.04	
Total labour :		\$ 1,880.00	
Total repair cost : (Before GST)		\$ 5,713.04	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Notified
Resurvey After Paint
2 days
16/8/2018 by 87550-W