



Accident Photo



Accident Photo



Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
6 Raffles Quay #18-00 Singapore 048580  
Tel (65) 6224 0010 Fax (65) 6224 0030  
Operating Hours: Monday to Friday, 09:00 - 17:00  
UIN: S66550020G / GST Reg. No.: M400017735

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MPA118074124 Vehicle Registration No: SLC 234 J  
Name (as shown in NRIC): Song Zhi wei NRIC/FIN/Passport No: S7887237 C  
(\* Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address: \_\_\_\_\_ Singapore( )  
Contact (Tel): \_\_\_\_\_ Mobile No.: 93890921  
Email Address: \_\_\_\_\_  
Date of Accident: 6/6/2018 Time of Accident: 18:40 hrs  
Place of Accident: Bukit Timah Road  
Insurance Company: UOI

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To change claim type from 'Third Party'  
to 'Own Damage' claims

Policyholder / Driver's Signature  
Date:

Reporting Centre Personnel's Signature  
Name: Chang Chee Sing  
NRIC/FIN No.: 62248170W  
Date: 19/6/18

# UOI

MEMBER OF THE UOB GROUP

United Overseas Insurance Limited  
3 Anson Road  
#28-01 Springleaf Tower  
Singapore 079909  
Tel (65) 6222 7733  
Fax (65) 6327 3869 / 6327 3870  
Email: ContactUs@uoi.com.sg  
uoi.com.sg  
Co. Reg. No. 197100152R

## Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

**ORIGINAL**

<b>CERTIFICATE NO.</b>	DHOM120034311800	<b>Excess:</b>	\$1500/-OTHERS \$3000/-APPL TO <25 YRS & OR <3YRS EXP \$100/-WINDSCREEN DAMAGE CLAIM \$750/-NAMED DRIVERS - OPTION 2
<b>Type of Cover</b>	COMPREHENSIVE		
<b>Vehicle Number</b>	SLC234J		
<b>Name of Insured</b>	SONG ZHIWEI		
<b>Restricted Driver(s)</b>	NOT APPLICABLE		

**Period of Insurance** 13 May 2018 to 28 April 2019  
**Hire Purchase** UNITED OVERSEAS BANK LIMITED

**Engine#** CHZ077391  
**Chassis#** WAUZZZ8X9GB083376

PRIVATE CAR - INDIVIDUAL OWNERSHIP [MX 1]  
AUTHORISED DRIVER

- (1) The Insured
- (2) Any other person who is driving on the Insured's order or with his permission
- (3) In the event of the death of the Insured
  - (a) any member of the Insured's family or a paid driver who has been driving the car during the lifetime of the Insured and permission to drive had not been withdrawn prior to the death of Insured and
  - (b) any other person who has been given permission to drive the vehicle prior to the death and such permission had not been withdrawn by the Insured

### LIMITATIONS AS TO USE

Use only for social domestic and pleasure purposes and for the Insured's business

### THE POLICY DOES NOT COVER

Use for hire or reward or racing pace-making reliability trial or speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purposes in connection with the Motor Trade  
The carriage of passengers pursuant to car pooling arrangements and payments or any of them made by the passengers thereunder towards the running expenses of any vehicle described in the Schedule shall not be deemed to constitute use for hire or reward

Provided that the person is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

\*Limitation rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles(Third-Party Risks and Compensation) Act (Chapter 189) and part Iv of the Road Transport Act, 1987 (Malaysia).

UNITED OVERSEAS INSURANCE LTD



For the Company

FCABM Date : 17/04/2018

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

7887237C

SONG ZHIWEI

Birth Date: 08 Mar 1978  
Issue Date: 12 May 2015

002426203C

SG 50




REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7887237C



Name

SONG ZHIWEI

宋志伟

Race  
CHINESE

Date of birth  
08-03-1978

Sex  
M

Country/Place of birth  
CHINA

6723

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg

EFFECTIVE DATE

12 May 2015



NP 428A



5833042

NRIC No: S7887237C



Date of issue  
27-11-2017

Address  
APT BLK 627 SENJA ROAD  
#07-174  
SINGAPORE 670627

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183  
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0667/2018/CCS  
Date : 21-Jun-18

Vehicle not IN workshop. Kindly arrange for survey.

## United Overseas Insurance Limited

3 Anson Road  
#28-01 Springleaf Tower  
Singapore 079909

Attn: Motor Claims Dept  
Tel: 6222 7739 - Fax 6327 3869

Owner's Name : Mr. Song ZhiWei  
Address : Blk 627 Senja Road  
#07-174  
Singapore 670627  
Telephone : HP +65 93890921  
Type of Claim : Own Damage Claims  
Policy No. : DHOM120034311800  
Vehicle No : **SLC 234 J**  
Model Code : Audi A1 SB 1.0 TFSI S TRONIC  
Model / Year : Apr-16  
Engine No : CHZ077391  
Chassis No : WAUZZZ8X9GB083376  
Mileage :  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 6-Jun-18  
Place of Accident : Bukit Timah Road

Tanjilun 97495749  
WP'  
24/7/18 @ 1730

5 days.

Revert

Ex: to be advise.

  
23/8/18

\* Resurvey before paint  
& check item  
sure / manufacture.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLC 234 J.

S/n	Nature of Jobs		Estimated Charges
1	To remove and transfer rear parking aid. Check function	S/N \$	280.00 ✓
2	To dismantle and renew rear bumper. Repair rhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$	1,200.00 900.
3	To respray rear bumper, rhs rear fender and rhs rear door.	\$	2,100.00 1800.
4	To renew rhs rear rim with tyre, carry out wheel alignment.	S/N \$	280.00 ✓
5	To carry out diagnostic checks.	S/N \$	192.00 ✓
<b>TOTAL LABOUR CHARGES</b>			<b>: \$ 4,052.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLC 234 J.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 1,281.00	dl ✓
2	FIXING PARTS FOR REAR BUMPER	\$ 64.00	✓ 43.70 new
3	REAR BUMPER SPOILER	\$ 366.00	out ✓
4	REAR GUIDE - RH	\$ 42.00	X nn
5	REAR LIGHT REFLECTOR - RH	\$ 26.00	X nn
6	REAR RIM - RH	\$ 645.00	out ✓
7	REAR TYRE - RH	PRICE TBC	parts out ✓ 340.
8	SUNDRIES	\$ 200.00	✓ 36.20 new
<b>TOTAL SPARE PARTS CHARGES</b>		<b>\$ 2,624.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 4,052.00</b>	
<b>GRAND TOTAL</b>		<b>\$ 6,676.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

7016x

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd



Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0667/2018/CCS  
**Date** : 21-Jun-18

Vehicle not IN workshop. Kindly arrange for survey.

## United Overseas Insurance Limited

3 Anson Road  
#28-01 Springleaf Tower  
Singapore 079909

*Hi Taufikh  
5 days - ok - jb - 8 Aug 19*

**Attn: Motor Claims Dept**  
**Tel: 6222 7739 - Fax 6327 3869**

**Owner's Name** : Mr. Song ZhiWei  
**Address** : Blk 627 Senja Road  
#07-174  
Singapore 670627  
**Telephone** : HP +65 93890921  
**Type of Claim** : Own Damage Claims  
**Policy No.** : DHOM120034311800  
**Vehicle No** : **SLC 234 J**  
**Model Code** : Audi A1 SB 1.0 TFSI S TRONIC  
**Model / Year** : Apr-16  
**Engine No** : CHZ077391  
**Chassis No** : WAUZZZ8X9GB083376  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 6-Jun-18  
**Place of Accident** : Bukit Timah Road

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLC 234 J.

S/n	Nature of Jobs	Estimated Charges	
1	To remove and transfer rear parking aid. Check function	S/N \$ 280.00	\$ 280.00
2	To dismantle and renew rear bumper. Repair rhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00	\$ 900.00
3	To respray rear bumper, rhs rear fender and rhs rear door.	\$ 2,100.00	\$ 1,800.00
4	To renew rhs rear rim with tyre, carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
5	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 4,052.00</b>	<b>\$ 3,452.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLC 234 J.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 1,281.00	\$ 1,281.00
2	FIXING PARTS FOR REAR BUMPER	\$ 64.00	\$ 43.70
3	REAR BUMPER SPOILER	\$ 366.00	\$ 366.00
4	REAR GUIDE - RH	\$ 42.00	
5	REAR LIGHT REFLECTOR - RH	\$ 26.00	
6	REAR RIM - RH	\$ 645.00	\$ 645.00
7	REAR TYRE - RH	\$ 340.00	\$ 340.00
9	SUNDRIES	\$ 200.00	\$ 36.20
	<b>TOTAL SPARE PARTS CHARGES</b>	<b>\$ 2,964.00</b>	<b>\$ 2,711.90</b>
	<b>TOTAL LABOUR CHARGES</b>	<b>\$ 4,052.00</b>	<b>\$ 3,452.00</b>
	<b>GRAND TOTAL</b>	<b>\$ 7,016.00</b>	<b>\$ 6,163.90</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI18015183/T1cd3s2

3 ANSON ROAD #28-01  
SPRINGLEAF TOWER SINGAPORE 079909

Date : 06-09-2019



Code : UOI2

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLC 234J
Policy No.	DHOM120034311800	Coverage (\$)	0.00
Claim No.	M12D08241807	Excess (\$)	750.00
Assign From	JENNY LEW	Assign Date	21/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	AUDI A1	c.c	999
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WAUZZZ8X9GB083376	Colour	GREY
Odometer	46173	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R16	CONTINENTAL	6 mm
L/H Front Tyre	215/45 R16	CONTINENTAL	6 mm
R/H Rear Tyre	215/45 R16	CONTINENTAL	6 mm
L/H Rear Tyre	215/45 R16	CONTINENTAL	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	06/06/2018	Inspection Date	11/06/2018
Survey held at	24 BENOI SECTOR		
Repairer	PREMIUM AUTOMOBILES PTE LTD		

## 5a. Remarks

A)THE MARKET VALUE IS S\$73,000.00(EST. AVERAGE)  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 234J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER (SN)	DEFORMED	1,281.00	1,281.00
1	FIXING PARTS FOR REAR BUMPER (SN)	NECESSARY	64.00	43.70
1	REAR BUMPER SPOILER (SN)	CUT	366.00	366.00
1	REAR GUIDE - RH (SN)	NOT NECESSARY	42.00	-
1	REAR LIGHT REFLECTOR - RH (SN)	NOT NECESSARY	26.00	-
1	REAR RIM - RH (SN)	CUT	645.00	645.00
1	REAR TYRE - RH (SN)	CUT	340.00	340.00
1	SUNDRIES (SN)	NECESSARY	200.00	36.20
			2,964.00	2,711.90
<b>LABOUR</b>				
	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.		280.00	280.00
	TO DISMANTLE AND RENEW REAR BUMPER. REPAIR RHS REAR FENDER. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		1,200.00	900.00
	T RESPRAY REAR BUMPER, RHS REAR FENDER AND RHS REAR DOOR.		2,100.00	1,800.00
	TO RENEW RHS REAR RIM WITH TYRE, CARRY OUT WHEEL ALIGNMENT.		280.00	280.00
	TO CARRY OUT DIAGNOSTIC CHECKS.		192.00	192.00
			4,052.00	3,452.00
<b>GRAND TOTAL</b>			<b>7,016.00</b>	<b>6,163.90</b>
<b>RECOMMENDED COST REPAIRS</b>				<b>6,163.90</b>
<b>LESS EXCESS</b>				<b>-750.00</b>
<b>NETT LIABILITY</b>				<b>5,413.90</b>

Report Ref No. CS/UO18015183/T1cd3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.