

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Aug-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6015 H

1 pc	Bonnet ✓		\$	979.00
1 pc	Bonnet insulator ✕		\$	219.00
1 pc	Bonnet lock ✕		\$	36.00
1 pc	Bonnet lifter ✕		\$	70.00
1 pc	Bonnet lock base ✕		\$	13.00
1 pc	Bonnet hinge o/s & n/s @ \$23.00 ✕ <i>hgs</i>		\$	46.00
1 pc	Bonnet weatherstrip ✕		\$	58.00
1 pc	Bonnet lock cover ✕		\$	15.00
1 pc	Bonnet cable long ✕		\$	25.00
1 pc	Bonnet cable short ✕		\$	15.00
1 pc	Bonnet grille ✓		\$	385.00
1 pc	Support panel ✓		\$	645.00
1 pc	Front bumper ✓		\$	531.00
1 pc	Front bumper emblem ✓		\$	44.00
1 pc	Front bumper centre grille ✓		\$	174.00
1 pc	Front bumper lower stiffer ✕		\$	134.00
1 pc	Front bumper tow hook cover ✕		\$	14.00
1 pc	Front bumper lip ✕		\$	52.00
1 pc	Front bumper inner sponge ✕		\$	110.00
1 pc	Front bumper upper reinforcement ?		\$	40.00
1 pc	Front bumper reinforcement ✓		\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>n/s ✓ o/s ✕</i>		\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 <i>n/s ✓ o/s ✕</i>		\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 <i>n/s ✓ o/s ✕</i>		\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 <i>n/s ✓ o/s ✕</i>		\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 <i>n/s ✓ o/s ✕</i>		\$	132.00
2 pcs	Front bumper o/s & n/s protector @ \$51.00 ✕		\$	102.00
1 pc	Air con condenser ✕		\$	805.00
1 pc	Radiator ✕		\$	669.00
1 pc	Air duct ✓		\$	210.00
1 pc	Front windscreen glass <i>YH ✓</i>		\$	801.00
1 pc	Front windscreen moulding <i>YH ✓</i>		\$	77.00
1 pc	Wiper top garnish ✕		\$	368.00
1 pc	Rear windscreen moulding ✕		\$	77.00
1 pc	Boot lid <i>X repair</i>		\$	1,119.00
1 pc	Boot lid lock ✕		\$	99.00
1 pc	Bootlid lock cable ✕		\$	35.00
1 pc	Bootlid striker ✕		\$	21.00
1 pc	Bootlid emblem ✓		\$	27.00
1 pc	Bootlid CRDi ✓		\$	29.00
1 pc	Boot lid rubber weatherstrip ✕		\$	96.00
1 pc	Boot lid lower garnish <i>X repair</i>		\$	290.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6015 H

2 pcs	Bootlid hinges @ \$66.00	X	14/1	\$	132.00
2 pcs	Bootlid hinge torsion bar @ \$33.00	X		\$	66.00
1 pc	Bootlid inner trim	X		\$	190.00
1 pc	End panel			\$	250.00
1 pc	End panel garnish	?		\$	74.00
1 pc	Towing hook bracket	X		\$	68.00
1 pc	Spare tyre clamp	X		\$	6.00
1 pc	Rear muffler assy	X		\$	1,009.00
1 pc	Rear exhaust pipe hanger	X		\$	49.00
1 pc	Exhaust pipe heat protector	X		\$	71.00
2 pcs	Rear o/s & n/s tail lamp @ \$421.00	X		\$	842.00
2 pcs	Bootlid n/s & o/s reflector @ \$350.00	X		\$	700.00
1 pc	Rear bumper			\$	696.00
1 pc	Rear bumper lower cover			\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00			\$	58.00
1 pc	Rear bumper inner sponge			\$	114.00
1 pc	Rear bumper reinforcement			\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	?		\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	?		\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	?		\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	nb ✓ o/s X		\$	92.00
				\$	16,452.00
				Less 10%	\$ 1,645.20
				\$	14,806.80

S/NETT

1 set	Rear bumper clips			\$	48.00
1 set	End panel inner garnish clips	X		\$	30.00
1 set	Bootlid inner trim clips	X		\$	52.00
1 set	Bootlid lower garnish clips	✓		\$	60.00
1 set	Bootlid stickers			\$	100.00
1 set	Reverse sensor			\$	280.00 200
2 pcs	Rear n/s & o/s fender stickers	X		\$	120.00
1 set	Floorboard compartment insulating paddings	X		\$	120.00
2 set	Front & rear windscreen sealant	X		\$	100.00
1 set	Wiper garnish clips	X		\$	48.00
1 pc	Front no. plate with casing			\$	50.00 30
1 pc	Front bumper clips			\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00	nb ✓ o/s X		\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00	nb ✓ o/s X		\$	6.00
1 set	Bonnet insulator clips	X		\$	52.00
1 pc	Front n/s fender sticker @ \$30.00	X		\$	30.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6015 H

Sundry	\$	50.00 20
Towing Fee	\$	50.00
To check for wiring and to focus head lamps	\$	80.00 20
To dismantle / refit new front windscreen glass onto new moulding	\$	150.00 100
To dismantle / refit rear windscreen glass onto new moulding	\$	150.00 X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, rear o/s fender, etc.	\$	2,200.00 1000
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s fender, rear o/s fender, front bumper, bonnet, front n/s fender	\$	2,000.00 1440
To apply rustproofing on the repaired and replaced panels.	\$	250.00 50
	\$	<u>21,192.80</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahir LKK

2/8/8

6 Rep.

4/5

After Repair p/b

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged panel(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: