

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 24 August 2018

To : LKK

By Fax: 6256-4315

Attn: Bryan Ang

Tel : 97237799

VEHICLE NO : FBF 8577U

Honda CBR 150R

ACCIDENT DATE: 17 August 2018

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>	
1 Handle Bar <i>bst</i>	1	125.00	✓
2 Front Mudguard <i>HN</i>	1	190.00	×
3 Front Brake Lever <i>bst</i>	1	75.00	✓
4 Visor <i>HN</i>	1	125.00	×
5 Mirror <i>cut</i>	1 set	125.00	✓
6 Throttle Grip <i>svl</i>	1 set	175.00	×
7 Head Lamp Assy <i>HN</i>	1	250.00	×
8 Fork Tube <i>distand</i>	1 set	480.00	✓
9 Fork Under Bracket <i>distand</i>	1	135.00	✓
10 Head Cowling <i>broken</i>	1	255.00	✓
11 Side Fairing L/RH <i>cut</i>	2	336.00	✓
12 Front Side Fairing Guard Top <i>broken</i>	2	350.00	✓
13 Bar End - Balancer <i>cut</i>	1 set	120.00	✓
14 Radiator Assy <i>Rental</i>	1	350.00	✓
15 Head Lamp Stay <i>HN</i>	1	120.00	×
16 Front RH Footrest Bracket <i>bst</i>	1	95.00	✓
17 Brake Pedal <i>bst</i>	1	68.00	✓
18 Footrest Rubber <i>bst</i>	1	65.00	✓
19 RH Front Signal <i>crack</i>	1	75.00	✓
20 Radiator Top Hose <i>cut</i>	1	195.00	✓ 80/-
21 Clutch Cover <i>cut</i>	1	65.00	✓
22 Steering Cone Bearing <i>Hel</i>	1	125.00	✓
23 Exhaust Guard <i>cut</i>	1	135.00	✓
24 Front Rim <i>distand</i>	1	280.00	✓
25 Front Brake Disc <i>HN</i>	1	230.00	×
26 RH Fairing Inner Guard (Garnish) <i>cut</i>	1	195.00	✓
27 Fuel Tank Top <i>HN</i>	1	250.00	×
		3534.00	
		3180.60	
	Sub-Total	4,989.00	
	Less 10%	498.90	
	Sub-Total	4,490.10	

VEHICLE NO : FBF 8577U

Honda CBR 150R

Nett items

1	Rear box cut		280.00	180/-
2	Towing fee		40.00	30/-
3	Remove & replace necessary parts, align & etc		350.00	200/-
4	Remove & replace fork assy, top up fork oil		180.00	80/-
5	Remove & replace front rim & disc		120.00	50/-
6	Supply body decal sticker - 1 set		280.00	120/-
7	Reconnect electrical harness wiring	860/-	80.00	NH
8	Putty & respray touch up paint to affected areas		350.00	200/-

Sub-Total 1,680.00

Nett Total 6,170.10

4040.60

1/3 3000/-

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

:LG

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

21/08/2018 @ 1500ms

klr Antwal

4/5mm

Signature with "5 days" written next to it

2 klc Auto

51249529

(2)