



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLG5194EMake & Model : TOTOTA PRIUS HYBRID 1.8 CVTYear of Manufacture : 2016Chassis No. : JTDKB3FU503535449Ins Company : AIG VS EQEngine No. : 2ZRR952349Excess : -Policy No. : -Date of Accident : 19.08.2018Time of Accident : 19:30

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ -

Plus/Less 20% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ -

Labour (Appendix B) \$ 2,760.00

Total Repair Cost \$ 2,760.00

Contact No

Frt Counter Operation

63837103 - Patrick Tia

63837730 - Brenda Ng

63837466 - Rohani

braddell_cr@sparkcarcare.com

Workshop Operation

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell_operation@sparkcarcare.com

*Not Authorized
Resurvey Required*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : KennethCompany : CLCSurvey conducted on : 21/8/18 at _____Remarks By Surveyor(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 04-5 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 21/8/18

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLG5194E Case Owner : 0

Make & Model : TOTOTA PRIUS HYBRID 1 Year Manufacture : 2016

Chassis No : JTDKB3FU503535449 Engine No : 2ZRR952349

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

| S/No | Part Description | QTY | Cost Price | List Price | Nett Price | S/N | Disposition By Surveyor |
|------|--|-----|------------|------------|------------|-----|-------------------------|
| 1 | Front bumper <i>CM</i> | 1 | | | | | ✓ |
| 2 | Front bumper badge logo <i>RM</i> | 1 | | | | | ✓ |
| 3 | Front bumper hole cover LH <i>SM</i> | 1 | | | | | ✓ |
| 4 | Front bumper retainer LH <i>CM</i> | 1 | | | | | ✓ |
| 5 | Front bumper retainer RH <i>SM</i> | 1 | | | | | X |
| 6 | Front bumper top seal <i>RM</i> | 1 | | | | | ✓ |
| 7 | Front bumper clips <i>RM</i> | 1 | | | | | ✓ |
| 8 | Front bumper lower grille | 1 | | | | | ? |
| 9 | Front bumper under cover <i>SM</i> | 1 | | | | | X |
| 10 | Front bumper fog lamp LH <i>CM</i> | 1 | | | | | ✓ |
| 11 | Front bumper sponge | 1 | | | | | ? |
| 12 | Front bumper sponge clips | 1 | | | | | ? |
| 13 | Front bumper reinforcement no. 2 <i>R</i> | 1 | | | | | X |
| 14 | Front bumper reinforcement no. 2 bracket LH | 1 | | | | | ? |
| 15 | Front bumper reinforcement no. 2 bracket RH <i>R</i> | 1 | | | | | X |
| 16 | Front bumper reinforcement <i>R</i> | 1 | | | | | X |
| 17 | Headlamp LH <i>CM</i> | 1 | | | | | ✓ |
| 18 | LH front fender <i>R</i> | 1 | | | | | ✓ |
| 19 | LH front fender emblem - HYBRID <i>RM</i> | 1 | | | | | ✓ |
| 20 | LH front fender inner shield <i>CM</i> | 1 | | | | | ✓ |
| 21 | LH front fender inner shield clips <i>RM</i> | 9 | | | | | ✓ |
| 22 | LH front fender protector <i>SM</i> | 1 | | | | | X |
| 23 | LH front fender top seal <i>SM</i> | 1 | | | | | X |
| 24 | LH front wheel rim (original) <i>Red</i> | 1 | | | | | ✓ |
| 25 | LH front tyre (DAVANTI DX390) | 1 | | | | | ? |
| 26 | LH front wheel hub sub-assy | 1 | | | | | ? |
| 27 | Steering knuckle arm LH | 1 | | | | | ? |
| 28 | LH front lower arm | 1 | | | | | ? |
| 29 | LH front lower arm ball joint | 1 | | | | | ? |
| 30 | LH front shock absorber set | 1 | | | | | ? |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLG5194E Case Owner : 0

Make & Model : TOTOTA PRIUS HYBRID 1 Year Manufacture : 2016

Chassis No : JTDKB3FU503535449 Engine No : 2ZRR952349

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

| S/No | Part Description | QTY | Cost Price | List Price | Nett Price | S/N | Disposition By Surveyor |
|------|------------------------------|-----|------------|------------|------------|-----|-------------------------|
| 31 | Front stabilizer bar link LH | 1 | | | | | 7 |
| 32 | Steering tie rod end LH | 1 | | | | | 7 |
| 33 | 0 | 0 | | | | | |
| 34 | 0 | 0 | | | | | |
| 35 | 0 | 0 | | | | | |
| 36 | 0 | 0 | | | | | |
| 37 | 0 | 0 | | | | | |
| 38 | 0 | 0 | | | | | |
| 39 | 0 | 0 | | | | | |
| 40 | 0 | 0 | | | | | |
| 41 | 0 | 0 | | | | | |
| 42 | 0 | 0 | | | | | |
| 43 | 0 | 0 | | | | | |
| 44 | 0 | 0 | | | | | |
| 45 | 0 | 0 | | | | | |
| 46 | 0 | 0 | | | | | |
| 47 | 0 | 0 | | | | | |
| 48 | 0 | 0 | | | | | |
| 49 | 0 | 0 | | | | | |
| 50 | 0 | 0 | | | | | |
| 51 | 0 | 0 | | | | | |
| 52 | 0 | 0 | | | | | |
| 53 | 0 | 0 | | | | | |
| 54 | 0 | 0 | | | | | |
| 55 | 0 | 0 | | | | | |
| 56 | 0 | 0 | | | | | |
| 57 | 0 | 0 | | | | | |
| 58 | 0 | 0 | | | | | |
| 59 | 0 | 0 | | | | | |
| 60 | 0 | 0 | | | | | |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.