

Guo Qiang
Joel Nahn

CS3/III 18012721/Bsb-1⁰²

II

21082018

OD(11) WS/1P R/S OD R/S 1P V/1N V/1M Y/1C

SLH 34555

LSM Lysion Motor

25 kaki Bukit Road 4 # 05-66/68

SHD3621Y
9438 9828

MCT18070295

State of Vehicle	Driver's Record
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

CA / REV / REF / REV 24 HRS (up)
Date/Time: 5:17pm @ 12/17/18

11/07/2018
13/07/2018

Notes and References

Vehicle IN/OUT

Day/Time	Simulation (x) Estimate
-	511.355

5211 64553 - X

HS \$ 7,150 / 8 days - checked By Simon.

(. \$ 4,350.00 Red - 38%)

RECEIVED 20 AUG 2010

L/S

Repair days

[Handwritten signature]

28/8/2018.

TGum

Dear

$$350 - 80 = 270$$

27/8/18

(08/11/13) wef

ASS. REC. BY:

REF:

ASSIGNMENT

From:

Date: 13/07/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLH 34555

at Workshop m/s

Lynston Motor (LSM)

of

25 kaki Sukit Rd 4 #05-66/68

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Daphne @ 94389828

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS lwp

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLH34555

Yr Regn:

APB, 2009

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Vios

c.c

1598

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

179693

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR0538EE 106/42192

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size:

F:

195/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIG / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

13-07-18

Survey held at

W/S

10:30 AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/7/18

Submit PRS Report

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

80

Transportation:

S - RS - SI

Photos

Others

10

TOTAL

90

Report Format :

Lump Sum / I.B.I. (\$

Catherine Chong (LKK Auto)

From: Joel Nah Shern Ern <JoelNah@iii.com.sg>
Sent: Tuesday, 21 August, 2018 9:12 AM
To: Catherine Chong (LKK Auto)
Cc: Olivia Lau (olivialau@lkkauto.com); Zuhaidah Samsuri
Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 11 JULY 2018 AT ABOUT 05:30HRS INVOLVING MOTOR VEHICLES NO(S). SLH3455S AND SHD3621Y ALONG BUKIT BATOK WEST AVE 5 [our ref: AP/2018/000080] [your ref: MCT18070295]

Dear all,

Rights have been granted for all the necessary documents in Merimen.

Joel Nah
Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #04-02 IOB Building
Singapore 049711
Tel: 6347 6100 Ext 206 Fax: 6224 4174

From: Zuhaidah Samsuri
Sent: Tuesday, 21 August, 2018 8:53 AM
To: Joel Nah Shern Ern <JoelNah@iii.com.sg>; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Cc: Olivia Lau (olivialau@lkkauto.com) <olivialau@lkkauto.com>
Subject: FW: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 11 JULY 2018 AT ABOUT 05:30HRS INVOLVING MOTOR VEHICLES NO(S). SLH3455S AND SHD3621Y ALONG BUKIT BATOK WEST AVE 5 [our ref: AP/2018/000080] [your ref: MCT18070295]

Hi Joel,

Please upload the attached docs in Merimen and share with LKK to conduct paper survey.

Thanks.

Best Regards
Aida Samsuri
Motor Claims Dept
India International Insurance Pte Ltd
64 Cecil Street #04/#05 IOB Building
Singapore 049711
Tel: 6347 6100 Ext 257 Fax: 6224 4174
Email: aida@iii.com.sg
Co. Reg Number: 198703792K

From: Mekavathanan Sarangapani
Sent: Monday, 20 August, 2018 5:42 PM
To: Olivia Lau (olivialau@lkkauto.com) <olivialau@lkkauto.com>
Cc: Zuhaidah Samsuri <aida@iii.com.sg>; Joel Nah Shern Ern <JoelNah@iii.com.sg>; Pooi Chin Han Daniel

<danielpooi@iii.com.sg>

Subject: FW: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 11 JULY 2018 AT ABOUT 05:30HRS INVOLVING MOTOR VEHICLES NO(S). SLH3455S AND SHD3621Y ALONG BUKIT BATOK WEST AVE 5 [our ref: AP/2018/000080] [your ref: MCT18070295]

CLAIM SUBFOLDER (1) Pending for Pay
PRI

Claim Audit	History Checking	Activity Log	Documents
Duplicate New Case	Assign Solicitor	File Review	Adj Market Value
Cancel Acceptance	Send Back Invoice/DV	Edit Claim Details	Revert to Pending Payment Requisition

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Submitted	Ins Auth'd
Main	19 Jul 2018		12 Jul 2018 00:00	23 Jul 2018 11:30 S\$0.00 (S\$96.30)	23 Jul 2018 11 S\$0.00

Main	Offer Processing	Claim Details	Adjuster's Details
CLAIM SUBFOLDER DETAILS [Created by ad]			
Insured:	-, Co. Reg. No.: -		
Main Claimant:	EC AUTO LEASING PTE LTD, Co. Reg. No.: 201815817W		
Vehicle Reg. No.:	SLH3455S	Date of Loss:	11/07/2018 05:00 [110 Months and]
Claim Type:	TP / MCT18070295	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHD3621Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Lynston Motorworks (HQ) PROFILE 25 Kaki Bukit Road 4, #08-43, 417800 Kaki Bukit - Tel: 9637725		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri -		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final R		
CLAIM REGISTERED			
Clim. No (Clim Reg Date)	MCT18070295 (23/07/2018)		Intimation (Notify Date)
Registration Type	[Manually registered]		Claim Status
Incurred TP			
S\$	0.00		
Subfolder	SubCode	Reg. No / Claimant	Person-in-Charge
TP		SLH3455S / EC AUTO LEASING PTE LTD	Zuhaidah Bte Samsuri

Trust PRI done . Please do up paper survey please

Best Regards,

Mekavathanan
HOD

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

DID: 6347 6105 Fax: 6224 4174



INDIA
INTERNATIONAL
INSURANCE
SINGAPORE
Serving the region since 1907



**SINGAPORE
POLICE FORCE**



T/20180711/2130

Police Station Of Origin:
Choa Chu Kang NPP
116 Teck Whye Lane #01-740 SINGAPORE
680116
Tel No: 1800-7629999

Report No. T/20


CONTINUATION OF REPORT

Brief Details.

On the 11/07/2018 at about 0530hrs I was traveling in my vehicle bearing registration number : towards Bukit Batok West Avenue 5 on the right lane, suddenly this vehicle bearing registration SHD3621Y make and illegal U-turn which cause me to collide on the driver right door. We both and exchange particular, traffic police and ambulance was at scene. No one was injured. After home I felt a pain on my neck, right shoulder and left knee cap, I then went to the family clinic : given 3 days medical leave.







DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON. 11 July 2018 @ 05:30 hr. I

VEH A was driving along the above

I VEH A was on lane 2 before making

a right turn I VEH A CHG. NO VEH

on my Right the moment I just in

Suddenly VEH. B came very fast and

VEHICLE DAMAGE INSPECTION REPORT

Our File No:
Date:

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0
Insured Vehicle No :	SLH3455S	Insured Vehicle No :	SHD362
Date of Loss:	11/07/2018	Nature of Claim:	TP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Registration No:	SLH3455S	
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Eng
Reg. Date:	22/04/2009 (Man. Year: 2009)	Cha
Colour:	Silver	Odo
Engine Capacity:	1598 cc	
Market Value/New Car Price:	N/A	
Amount Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:
Front Left Side:	Michelin 6 mm	Rear Left Side:
Front Right Side:	Michelin 6 mm	Rear Right Side:

above values represent the remaining tyre treads depth

LIST OF CLAIMS	Repairer's	Adjuster's
Parts	0.00	0.00
Accessories Items	0.00	0.00
Labor	0.00	0.00
Paintwork Labour	0.00	0.00
Other	0.00	0.00
Nett Amount (S\$)	0.00	0.00

INSPECTION

Date of Assignment: 12/07/2018

Date: 20 August 2018

Dear Sirs,

PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 11 JULY 2018 ABOUT 05:30HRS INVOLVING MOTOR VEHICLES NO(S). SLH3455S AND SHD3621Y A BUKIT BATOK WEST AVE 5

We refer to the above matter.

We act for EC Auto Leasing Pte Ltd, the owner of SLH3455S.

We are instructed by our clients to notify you of a road traffic accident on 11 July 2018 at about 05 along Bukit Batok West Ave 5 involving our clients' vehicle and your taxi bearing registration n SHD3621Y, driven by you. A copy of our client's Singapore accident statement filed on 12 July 2018 is enclosed.

We are instructed that the above-mentioned road traffic accident was caused by your negligence driving, management and/or control of your taxi.

As a result of the abovementioned road traffic accident, our clients' vehicle was damaged and our has been put to loss and expense, particular of which are as follows:

Costs of repair	\$ 11,500.00
------------------------	---------------------

Loss of use	\$ 3,000.00
--------------------	--------------------

-	Pre-repair	\$ 300.00
	(2 days including intervening weekend x \$150 per day)	
-	During repair works	\$2,700.00
	(18 days including intervening weekend x \$150 per day)	

Grand Total	\$ 14,500.00
--------------------	---------------------

Progress

CLQ00109 SST V1.0 INDIA INTERNATIONAL INSURANCE LIVE DB 20

Claim No..... MCT18070295 Claim Item

Claimant..... SLH3455S-TPD Claim Item No. 1.01

Descr. of loss.... DAMAGE TO TPV SLH3455S

print 1 Cause

Claim Reserves

Payment category	Reserve/Cur:SGD	Planned
SURVEY FEE	0.00	0.00
POLICY EXCESS	0.00	0.00
LOSS	3,000.00	0.00
MEDICAL EXPENSES	0.00	0.00
LEGAL FEE (S & C)	0.00	0.00
GST INPUT TAX	0.00	0.00
PARTY & PARTY COSTS	0.00	0.00
RECOVERY FROM T P	0.00	0.00

Top of File ...

Top of File ...

PgUp F4 F7 F8 5cash call 9List 15N.Itm 19N.Clm 17Reserve 18Pay

Best Regards,

Mekavathanan

HOD

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

DID: 6347 6105 Fax: 6224 4174



From: Charles Hoon [mailto:charles@aplp.com.sg]

Sent: Monday, August 20, 2018 5:16 PM

To: Motor Claim - III <motorclaim@iii.com.sg>; Zuhaidah Samsuri <aida@iii.com.sg>

Cc: 'Miss Daphne' <isafegarage@gmail.com>

Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 11 JULY 2018 AT ABOUT 05:30HRS INVOLVING MOTOR VEHICLES NO(S). SLH3455S AND SHD3621Y ALONG BUKIT BATOK WEST AVE 5 [our ref: AP/2018/000080] [your ref: MCT18070295]

Dear Andrew / Aida,

Please find attached, our letter of even date.

Regards,

Charles Hoon

AP Law Practice

9 Temasek Boulevard #09-01 Suntec Tower 2 Singapore 038989

T: 64071429 F: 64071427 E: charles@aplp.com.sg

Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

From: Motor Claim - III <motorclaim@iii.com.sg>

Sent: Thursday, 12 July 2018 5:03 PM

To: Charles Hoon <charles@aplp.com.sg>

Cc: Zuhaidah Samsuri <aida@iii.com.sg>; 'sur@lkkauto.com' <sur@lkkauto.com>

Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 11 JULY 2018 AT ABOUT 05:30HRS INVOLVING MOTOR VEHICLES NO(S). SLH3455S AND SHD3621Y ALONG BUKIT BATOK WEST AVE 5 [our ref: AP/2018/000080] [your ref: to be advised]

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SLH3455S

III INSURED VEHICLE NO. : SHD3621Y

DATE OF LOSS : 11/07/2018

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor **LKK AUTO CONSULTANTS** to conduct the pre-repair survey.

This claim is handled by **Aida**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,

ANDREW LIM

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 227

S&P 'A-' (stable) rated Company

From: Charles Hoon [<mailto:charles@aplp.com.sg>]

Sent: Thursday, 12 July, 2018 4:49 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: Zuhaidah Samsuri <aida@iii.com.sg>

Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 11 JULY 2018 AT ABOUT

05:30HRS INVOLVING MOTOR VEHICLES NO(S). SLH3455S AND SHD3621Y ALONG BUKIT BATOK WEST AVE 5 [our ref: AP/2018/000080] [your ref: to be advised]

Dear Andrew,

We refer to your email below.

Our clients do not agree to your list of surveyors.

We are instructed to propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a) Alan Cheong
- b) TT Rajan
- c) Oh Han Cheong
- d) Andrew How
- e) Dave Ho Joo Koong
- f) Lee Kok Weng
- g) Seah Kwang Boon
- h) Lee K.W.
- i) Mr Willy Goh
- j) Mr Zali Saidi

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

Regards,

Charles Hoon

AP Law Practice

9 Temasek Boulevard #09-01 Suntec Tower 2 Singapore 038989

T: 64071429 F: 64071427 E: charles@aplp.com.sg

Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

From: Motor Claim - III <motorclaim@iii.com.sg>

Sent: Thursday, 12 July 2018 4:44 PM

To: Charles Hoon <charles@aplp.com.sg>

Cc: Zuhaidah Samuri <zaida@iii.com.sg>

Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 11 JULY 2018 AT ABOUT 05:30HRS INVOLVING MOTOR VEHICLES NO(S). SLH3455S AND SHD3621Y ALONG BUKIT BATOK WEST AVE 5 [our ref: AP/2018/000080] [your ref: to be advised]

Dear Sir / Madam,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

ANDREW LIM

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 10B Building | Singapore 049711

Tel: 6347 6100, Ext - 227

S&P 'A-' (stable) rated Company

From: Charles Hoon [mailto:charles@apl.com.sg]

Sent: Thursday, July 12, 2018 4:27 PM

To: Sherini Pillay [mailto:s@iii.com.sg]

Subject: PROPOSED DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 11 JULY 2018 AT ABOUT 05:30HRS INVOLVING MOTOR VEHICLES NO(S). SLH3455S AND SHD3621Y ALONG BUKIT BATOK WEST AVE 5 [our ref: AP/2018/0000] [your ref: to be advised]

Dear Sherini,

Please find enclosed your letter of even date.

Regards,

Charles Hoon

AP Law Practice

9 Temasek Boulevard | #09-01 | Suntec Tower 2 Singapore 038989

T: 64071429 F: 64071430 | charles@apl.com.sg

Singapore UEN: 190000000

This email transmission is confidential and intended only for the address(es). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, including sharing your personal data with our service providers (located both inside and outside Singapore) and with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER

This email is confidential and intended for the person to whom it has been addressed.

It may contain confidential, legal and/or legally privileged information.

If you are not the intended recipient, you should delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet e-mail transmission may not be entirely secure or accurate as information could be intercepted, delayed or contain viruses.

Therefore, we accept no liability for any errors or omissions in the content of this message or for any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registered Office: 64 Cecil Street

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, including sharing your personal data with our service providers (located both inside and outside Singapore) and with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim,

which includes the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the intended recipient, please do not print, copy, retransmit, or otherwise use this e-mail. If you have received this e-mail in error, please notify us immediately and inform us of the error and also be hereby notified that a report of this error will be made to the appropriate authorities. Any use, transmission, printing, copying or dissemination of this information in any manner is strictly prohibited and may be unlawful.
Internet e-mail transmission is not entirely secure or accurate as information could be intercepted, altered, or contain viruses.
There may be errors or omissions in the content of this message due to technical issues which may arise as a result of Internet transmission.
Please print this message only when absolutely necessary and help in preservation of environment.
Registered in Singapore.

Kindly inform us of any change in your contact details. If you have made a claim to us, you are deemed to have agreed to us collecting, using, disclosing, and sharing your personal data, sharing your personal data with our service providers (located both inside and outside of Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Corporation of Singapore. This enables us to ensure proper processing, handling and use of your personal data, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the intended recipient, please do not print, copy, retransmit, or otherwise use this e-mail. If you have received this e-mail in error, please notify us immediately and inform us of the error and also be hereby notified that a report of this error will be made to the appropriate authorities. Any use, transmission, printing, copying or dissemination of this information in any manner is strictly prohibited and may be unlawful.
Internet e-mail transmission is not entirely secure or accurate as information could be intercepted, altered, or contain viruses.
There may be errors or omissions in the content of this message due to technical issues which may arise as a result of Internet transmission.
Please print this message only when absolutely necessary and help in preservation of environment.
Registered in Singapore.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address : 1 Simei St 3 #02-24 S(529890)

Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 2014044340

INVOICE

M/s. EC Auto Leasing Pte Ltd
C/o. 50 Playfair Road
Noel Building #05-04
Singapore 367995

Invoice No. : HA/1808-18

Date : 14/08/2018


Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 714.00
SGD Dollar : Seven Hundred Fourteen Dollars Only.	
Our Reference : PAS/TP/PAS/TP/0290718	
Vehicle No. : SLH3455S	
Make & Model : Toyota Corolla Altis	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/PAS/TP-0290

Date of Report : 14/08/2018

To : M/s. EC Auto Leasing Pte Ltd

C/o. 50 Playfair Road

Noel Building #05-04

Singapore 367995

Date of Assignment : 13/07/2018

Report requested by : M/s. EC Auto Leasing Pte Ltd

Date of Accident : 11/07/2018

Date of Inspection : 13/07/2018

Claim No. : Third Party Claim

Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SLH3455S

Make & Model : Toyota Corolla Altis

Date of Registration : 22/04/2009

Colour : Met. Silver

Engine Capacity (cc) : 1598cc

Mileage (km) : 179693km

Chassis / Frame No. : MR053ZEE106142192

Engine No. : 3ZZ4871773

TYRE CONDITION

Front LH : 5 mm

Make : Michelin

Front RH : 5 mm

Make : Michelin

Rear LH : 5 mm

Make : Michelin

Rear RH : 5 mm

Make : Michelin

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good

Paintwork : Good

Handbrake : Serviceable

Footbrake : Serviceable

Steering : Serviceable

Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Isafe Garage

50, Playfair Road, Noel Building, #05-04, Singapore 367995

ASSESSMENT

Repairer's Estimate : \$ 17,982.33

Revised Amount : \$ 14,380.58

Less Excess : \$ -

Recommended Reserve : \$ 11,500.00 (Lump Sum)

Estimated Normal Period of Repairs : 12 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simel St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 2014044340

Vehicle No : SLH3455S

Report No. : PAS/TP/PAS/TP/0290718

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Isafe Garage, 25, Kaki Bukit Road 4, Synergy@KB, #05-66/67/68, Singapore 417800.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the LHF portion. (The LHF roadwheel was also affected)

DAMAGES

The bonnet, front support panel, front chassis members, front bumper, front fenders, front wheel housings, LHF alloy rim, LHF knuckle arm, LHF lower arm, LHF suspension, LHF driveshaft, front crossmember, LHF doors, LH headlamp, LHF fog lamp, front grille, LH side skirts, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$14,380.58.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$11,500.00.


This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No.: SLH3455S

Report No.: PAS/TP/PAS/TP/0290718

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	1 pc	Bonnet	Dented		\$ 906.60	\$ 906.60 DT ✓
2	1 pc	Bonnet seal	Necessary		\$ 60.30	\$ 60.30 NN ✓
3	2 pcs	Bonnet insulator clip	Necessary	\$ 2.30	\$ 4.60	\$ 4.60 NEC ✓
4	2 pcs	Bonnet hinge R/L	Bent	\$ 56.60	\$ 113.20	\$ 113.20 NN ✓
5	1 pc	Bonnet insulator	Refit		\$ 268.90	\$ -
6	7 pcs	Bonnet insulator clip	Necessary	\$ 2.50	\$ 17.50	\$ 17.50 NEC ✓
7	1 pc	Bonnet lock	Bent		\$ 90.70	\$ 90.70 NN ✓
8	2 pcs	Headlamp R/L	LH Broken	\$ 713.80	\$ 1,427.60	\$ 713.80 BR ✓
9	1 pc	Frt grille	Cracked		\$ 314.90	\$ 314.90 CR ✓
10	1 pc	Frt grille emblem (Logo)	Necessary		\$ 71.60	\$ 71.60 NEC ✓
11	1 pc	Frt bumper	Dented/Broken		\$ 463.60	\$ 463.60 BR ✓
12	1 pc	Frt bumper seal	Necessary		\$ 52.50	\$ 52.50 NEC ✓
13	1 pc	Frt bumper grille	Broken/Dislodged/Mission		\$ 102.80	\$ 102.80 MIS ✓
14	1 pc	Frt bumper fog lamp LH	Broken/Dislodged/Mission		\$ 298.10	\$ 298.10 MIS ✓
15	1 pc	Frt bumper fog lamp garnish LH	Broken/Dislodged/Mission		\$ 62.00	\$ 62.00 MIS ✓
16	6 pcs	Frt bumper clip	Necessary	\$ 3.80	\$ 22.80	\$ 22.80 NEC ✓
17	2 pcs	Frt bumper retainer R/L	Cracked/Necessary	\$ 55.20	\$ 110.40	\$ 110.40 BR ✓
18	1 pc	Frt bumper reinforcement	Dented		\$ 293.90	\$ 293.90 BT ✓
19	1 pc	Frt bumper lower cover	Broken/Dislodged/Mission		\$ 149.70	\$ 149.70 MIS ✓
20	8 pcs	Frt bumper lower cover clip	Necessary	\$ 3.30	\$ 26.40	\$ 26.40 NEC ✓
21	2 pcs	Frt fender R/L	LH Dented	\$ 622.10	\$ 1,244.20	\$ 622.10 DD ✓
22	2 pcs	Frt fender emblem (VVT-i) R/L	Necessary	\$ 42.10	\$ 84.20	\$ 84.20 NEC ✓
23	1 pc	Frt fender cowl LH	Broken/Dislodged/Mission		\$ 171.20	\$ 171.20 TN ✓
24	6 pcs	Frt fender cowl clip LH	Necessary	\$ 3.20	\$ 19.20	\$ 19.20 NEC ✓
25	1 pc	Frt fender enclosure LH	Torn		\$ 77.60	\$ 77.60 TN ✓
26	1 pc	Frt support panel assy	Dented		\$ 721.30	\$ 721.30 DD ✓
27	1 pc	Frt apron panel assy LH	Dented/Distorted		\$ 496.00	\$ 496.00 DD ✓
28	1 pc	A/c condenser	Dented		\$ 1,490.40	\$ 1,490.40 NN ✓
29	1 pc	Frt shock absorber LH	Bent/Jammed		\$ 393.70	\$ 393.70 NN ✓
30	1 pc	Frt wheel hub LH	Warped/Distorted		\$ 214.00	\$ 214.00 ✓
31	1 pc	Frt wheel bearing LH	Damaged/Necessary		\$ 101.70	\$ 101.70 WT ✓
32	1 pc	Frt knuckle arm LH	Bent/Distorted		\$ 478.10	\$ 478.10 ✓
33	1 pc	Frt lower ball joint LH	Bent		\$ 215.80	\$ 215.80 NN ✓
34	1 pc	Frt lower arm LH	Bent		\$ 602.10	\$ 602.10 ✓
35	1 pc	Frt drive shaft LH	Bent		\$ 1,466.30	\$ 1,466.30 ✓
36	1 pc	Frt stabilizer bar	Refit		\$ 398.90	\$ -
37	1 pc	Frt stabilizer link LH	Bent		\$ 195.00	\$ 195.00 NN ✓
38	1 pc	Frt crossmember	Realign		\$ 1,925.30	\$ -
39	1 pc	LH side mirror outer cover	Cracked		\$ 59.70	\$ 59.70 BR ✓
40	1 pc	LH side mirror signal lamp	Cracked		\$ 47.70	\$ 47.70 CR ✓
41	1 pc	LH side mirror housing	Broken		\$ 1,142.80	\$ 1,142.80 BR ✓
42	1 pc	Frt door glass moulding LH	Dented/Defaced		\$ 126.50	\$ 126.50 NN ✓
43	1 pc	Frt door protector LH	Grazed/Necessary		\$ 112.70	\$ 112.70 NEC ✓
					\$ 16,642.50	\$ 12,713.50



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 201404434D

Vehicle No.: SLH3455S

Report No.: PAS/TP/PAS/TP/0290718

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$S)	Our Assessment (\$S)
				\$ 16,642.50	\$ 12,713.50
44	1 pc	Frt door protector insert LH	Necessary	\$ 12.40	\$ 12.40 <i>NECV</i>
45	1 pc	Airbag sensor LH	Dented/Cracked	\$ 308.20	\$ 308.20 <i>X</i>
46	1 pc	Frt door LH	Dented/Repair		(Refer labour no. 8 & 10)
47	1 pc	LH side skirt	Dented/Repair		(Refer labour no. 8 & 10)
48	1 pc	Frt fender RH	Dented/Repair		(Refer labour no. 8 & 10)
49	1 pc	Frt apron panel assy RH	Dented/Repair		(Refer labour no. 8, 9 & 10)
50	2 pcs	Frt chassis member R/L	Dented/Repair <i>NN X</i>		(Refer labour no. 8, 9 & 10)
				\$ 16,963.10	\$ 13,034.10
			Less Discount : 25%	\$ 4,240.78	25% \$ 3,258.53
			List Parts Sub-Total :	\$ 12,722.33	\$ 9,775.58
1	1 pc	Frt alloy rim LH	Dented/Defaced	S/N \$ 300.00	\$ 300.00 <i>CutV</i>
2	1 pc	Frt tyre LH (Depreciate 30%)	Cut/Bulged	S/N \$ 250.00	\$ 175.00 <i>NN X</i>
3	1 pc	Brake fluid	Necessary	S/N \$ 20.00	\$ 20.00 <i>NN X</i>
4	1 bot	Radiator coolant	Necessary	S/N \$ 60.00	\$ 60.00 <i>NN X</i>
5	1 pc	Battery (Depreciate 50%)	Dented	S/N \$ 150.00	\$ 75.00 <i>DDV</i>
			Special Nett Sub-Total :	\$ 780.00	\$ 630.00
			Parts Total :	\$ 13,502.33	\$ 10,405.58



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529690)

Mobile: 9295 2204 Fax: 6722 8608 Email: pasvcs@hotmail.com

Business Reg: 201404434D

Vehicle No.: SLH3455S

Report No.: PAS/TP/PAS/TP/0290718

S/No. Labour Descriptions

Repairer's Estimate (S\$)	Our Assessment (S\$)
---------------------------	----------------------

1	Towing.	\$ 120.00	\$ 85.00 ⁶⁰
2	To check electrical system, repair wire harness and focus headlamp.	\$ 80.00	\$ 60.00 ³⁰
3	To remove and reinstall a/c condenser, a/c pipings for necessary repairs. (Include vacuum & recharge a/c gas)	\$ 120.00	\$ 120.00
4	To remove and reinstall radiator & cooling system for necessary repairs. (Include pressure test cooling system)	\$ 100.00	\$ 80.00 ¹⁰⁰
5	To remove and reinstall engine electrical connectors & components, wire harness, etc. for necessary repairs. To lift up/support engine for replace/repair both wheelhousing and front chassis members.	\$ 200.00	\$ 150.00 ^X
6	To remove, check, replace LHF undercarriage parts and realign front crossmember (Include flush and bleed brakes system)	\$ 300.00	\$ 250.00 ^{100.00 + 50}
7	To conduct wheel alignment.	\$ 120.00	\$ 120.00 ²⁰
8	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,500.00	\$ 1,320.00 ⁷⁰⁰
9	To conduct chassis alignments.	\$ 320.00	\$ 300.00 ^{NN X}
10	To spray painting, blending on affected and adjacent area.	\$ 1,500.00	\$ 1,400.00 ^{1,000.00}
11	To spray anti-rust coating on new and affected panels.	\$ 120.00	\$ 90.00 ^{60.00}
Labour Total :		\$ 4,480.00	\$ 3,975.00 ^{2385.00}
Total (Parts & Labour) :		\$ 17,982.33	\$ 14,380.58 ^{9625.12}

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 11,500.00

Under normal circumstances, the repairs should be completed within a reasonable period

of **12 Working Days.** (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

124 Photographs were taken at the time of inspection.

Repair days

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III18012721/Bsbe2-1		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 28-08-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3621Y	Veh. Inspected	SLH 3455S	
Policy No.		Coverage (\$)	0.00	
Claim No.	MCT18070295	Excess (\$)	0.00	
Assign From	JOEL NAH	Assign Date	21/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053ZEE106142192	Colour	SILVER	
Odometer	179693	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	6 mm	
L/H Front Tyre	195/65 R15	MICHELIN	6 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/07/2018	Inspection Date	13/07/2018	
Survey held at	LSM LYNSTON MOTOR - 25 KAKI BUKIT RD 4 #05-66			
Repairer	-			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 3455S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	DENTED	906.60	906.60
1	BONNET SEAL	NOT NECESSARY	60.30	-
2	BONNET INSULATOR CLIP @\$2.30	NECESSARY	4.60	4.60
2	BONNET HINGE R/L @\$56.60	NOT NECESSARY	113.20	-
1	BONNET INSULATOR	REFIT	268.90	-
7	BONNET INSULATOR CLIP @\$2.50	NECESSARY	17.50	17.50
1	BONNET LOCK	NOT NECESSARY	90.70	-
2	HEADLAMP R/L @\$713.80	N/S BROKEN	1,427.60	713.80
1	FRT GRILLE	CRACKED	314.90	314.90
1	FRT GRILLE EMBLEM (LOGO)	NECESSARY	71.60	71.60
1	FRT BUMPER	BROKEN	463.60	463.60
1	FRT BUMPER SEAL	NECESSARY	52.50	52.50
1	FRT BUMPER GRILLE	MISSING	102.80	102.80
1	FRT BUMPER FOG LAMP LH	MISSING	298.10	298.10
1	FRT BUMPER FOG LAMP GARNISH LH	MISSING	62.00	62.00
6	FRT BUMPER CLIP @\$3.80	NECESSARY	22.80	22.80
2	FRT BUMPER RETAINER R/L @\$55.20	BROKEN	110.40	110.40
1	FRT BUMPER REINFORCEMENT	BENT	293.90	293.90
1	FRT BUMPER LOWER COVER	MISSING	149.70	149.70
8	FRT BUMPER LOWER COVER CLIP @\$3.30	NECESSARY	26.40	26.40
2	FRT FENDER R/L @\$622.10	N/S DENTED	1,244.20	622.10
2	FRT FENDER EMBLEM (VVT-I) R/L @\$42.10	N/S NECESSARY	84.20	42.10
1	FRT FENDER COWLING LH	TORN	171.20	171.20
6	FRT FENDER COWLING CLIP LH @\$3.20	NECESSARY	19.20	19.20
1	FRT FENDER ENCLOSER LH	TORN	77.60	77.60
1	FRT SUPPORT PANEL ASSY	DENTED	721.30	721.30
1	FRT APRON PANEL ASSY LH	DENTED	496.00	496.00
1	A/C CONDENSER	NOT NECESSARY	1,490.40	-
1	FRT SHOCK ABSORBER LH	NOT NECESSARY	393.70	-
1	FRT WHEEL HUB LH	WARPED / DISTORTED	214.00	214.00
1	FRT WHEEL BEARING LH	CUT	101.70	101.70
1	FRT KNUCKLE ARM LH	DISTORTED	478.10	478.10
1	FRT LOWER BALL JOINT LH	NOT NECESSARY	215.80	-

Report Ref No. CS3/III18012721/Bsbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT LOWER ARM LH	BENT	602.10	602.10
1	FRT DRIVE SHAFT LH	NOT NECESSARY	1,466.30	-
1	FRT STABILIZER BAR	REFIT	398.90	-
1	FRT STABILIZER LINK LH	NOT NECESSARY	195.00	-
1	FRT CROSSMEMBER	REALIGN	1,925.30	-
1	LH SIDE MIRROR OUTER COVER	BROKEN	59.70	59.70
1	LH SIDE MIRROR SIGNAL LAMP	CRACKED	47.70	47.70
1	LH SIDE MIRROR HOUSING	BROKEN	1,142.80	1,142.80
1	FRT DOOR GLASS MOULDING LH	NOT NECESSARY	126.50	-
1	FRT DOOR PROTECTOR LH	NECESSARY	112.70	112.70
1	FRT DOOR PROTECTOR INSERT LH	NECESSARY	12.40	12.40
1	AIRBAG SENSOR LH	NOT NECESSARY	308.20	-
1	FRT DOOR LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	LH SIDE SKIRT (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRT APRON PANEL ASSY RH (NPA)	TO REPAIR SEE LABOUR	-	-
2	FRT CHASSIS MEMBER R/L LESS 25% DISCOUNT	NOT NECESSARY	-4,240.78	-2,132.98
SPECIAL NETT ITEMS			12,722.32	6,398.92
1	FRT ALLOY RIM LH (SN)	CUT	300.00	300.00
1	FRT TYRE LH (SN)	NOT NECESSARY	250.00	-
1	BRAKE FLUID (SN)	NOT NECESSARY	20.00	-
1	BOT RADIATOR COOLANT (SN)	NOT NECESSARY	60.00	-
1	BATTERY (SN) (DEPRECIATE 50%)	DENTED	150.00	75.00
LABOUR			780.00	375.00
TOWING.			120.00	60.00
TO CHECK ELECTRICAL SYSTEM, REPAIR WIRE HARNESS AND FOCUS HEADLAMP.			80.00	30.00
TO REMOVE AND REINSTALL A/C CONDENSER, A/C PIPINGS FOR NECESSARY REPAIRS. (INCLUDE VACUUM & RECHARGE A/C GAS) }			120.00	100.00

Report Ref No. CS3/III18012721/Bsbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REINSTALL RADIATOR & COOLING SYSTEM FOR NECESSARY REPAIRS. (INCLUDE PRESSURE TEST COOLING SYSTEM) }		100.00	-
	TO REMOVE AND REINSTALL ENGINE ELECTRICAL CONNECTORS & COMPONENTS, WIRE HARNESS, ETC. FOR NECESSARY REPAIRS. TO LIFT UP / SUPPORT ENGINE FOR REPLACE / REPAIR BOTH WHEELHOUSING AND FRONT CHASSIS MEMBERS.	NOT NECESSARY	200.00	-
	TO REMOVE, CHECK, REPLACE LHF UNDERCARRIAGE PARTS AND REALIGN FRONT CROSSMEMBER (INCLUDE FLUSH AND BLEED BRAKES SYSTEM)		300.00	150.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRT DOOR LH, LH SIDE SKIRT, FRT FENDER RH AND FRT APRON PANEL ASSY RH.		1,500.00	700.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	320.00	-
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		1,500.00	1,000.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		120.00	60.00
			4,480.00	2,160.00
GRAND TOTAL			17,982.32	8,933.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,150.00

Report Ref No. CS3/III18012721/Bsbe2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.