

VO

CC 3, Asm 180

15192,

Cwa 3

64593

Kenneth

ASSIGNMENT

DOI:

20/8/18

Date / Time:

20/8/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

Dng pang chye

3844133 (V/L: YES / NO)

SHP 3844B



INSRS:

WSP:

Tel:

Liability:

RMKS:

pang-co



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

20/8

SHP 3844B - 07/08/18 13:00 P.O. / Kebab 2: 11/18/18

GBF 8125R - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

20/8

Sent By:

hm

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

21/7/19.

Confirm with

Wai Kin

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27.

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 5182.28

Loss of Rental (LOR):

S\$ 310.80

(

3

days) x

103.60

Loss of Use (LOU):

S\$ 150.00

(\$

50

x

3

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 7.49

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$ 5650.57

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 5650.57

Name 1:

Trans Cab Auto Services Pte Ltd

Payee 2 (if any):

S\$

Name 2:

Payee 3 (if any):

S\$

Name 3:

ASS. REC. BY:

REF:

AXA/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S110 384B

Yr Regn:

10, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c

1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

352196

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 282677

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NTP / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

Rear

R/Bal.

6

mm

R/Bal.

9

mm

L/Bal.

6

mm

L/Bal.

9

mm

D.O.A.

12/8/18

D.O.I.

20/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/8

File pass to Catherine

84843.25



Jasmine

(26 days + 1/2 x 103.60 + 150)

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 384B**AAD1808-075***Not Authorised**Resurvey B4 paint @ 4843.25*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 384B

VF1ABL15AUC282677

RENAULT

LATITUDE

12.8.2018

AXA**PART****LIST**

1	1 BUMPER COVER REAR	\$	Bh 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	Ncl 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	Sn 113.47	X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	Sn 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	Sn 44.99	X
6	1 BUMPER REFLECTOR RH	\$	Bv 43.61	✓
7	1 BUMEP R BRACKET SIDE LH REAR	\$	R 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	Sn 44.99	X
9	1 BUMPER REFLECTOR LH	\$	Sn 43.61	X
10	1 BUMPER BEAM REAR	\$	Bh 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	R 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	R 225.95	X
13	1 OUTER PANEL REAR (End Panel)	\$	R 1,471.77	X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn 404.56	X
15	1 TAILLAMP RH	\$	Sn 552.55	X
16	1 TAILLAMP PANEL RH	\$	R 986.70	X
17	1 BOOT REAR	\$	R 2,872.68	X
18	1 BOOT FINISHER	\$	Sn 470.06	X
19	1 BOOT WHEATERSTRIP	\$	Sn 323.05	X
20	1 BOOT REFLECTOR LAMP LH	\$	Sn 493.35	X
21	1 BOOT REFLECTOR LAMP RH	\$	cm 493.35	✓
22	1 BOOT BADGE 'RENAULT'	\$	Nr 225.36	—
23	1 BOOT BADGE	\$	Nr 225.36	—
24	1 BOOT STRUT LH	\$	Bh 276.08	} X
25	1 BOOT STRUT RH	\$	Sn 276.08	
26	1 BOOT HINGE LH	\$	R 367.84	
27	1 BOOT HINGE RH	\$	R 367.84	
28	1 BOOT INNER TRIM	\$	Sn 586.45	
29	1 BOOT SWITCH	\$	Sn 168.13	

Trans-cab Auto Services Pte Ltd

AAD1808-075

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 384B

30	1 BOOT LOCK	\$	<i>na</i> 202.67 <i>X</i>
31	1 BOOT LOCK CATCH	\$	<i>na</i> 74.40 <i>X</i>
		\$	14,507.62
10%		\$	7.44
		\$	14,500.18

Specical Nett

1	1SET PARKING AID	\$	<i>shay</i> 700.00 <i>600.00</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 <i>—</i>
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 <i>—</i>
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 <i>X</i>
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00 <i>X</i>
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 <i>X</i>
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00 <i>X</i>
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 <i>X</i>
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 <i>—</i>
10	1 EXHAUST MOUNTING REAR	\$	<i>na</i> 17.82 <i>X</i>
11	2 REAR WINDSCREEN SELANT	\$	<i>na</i> 80.00 <i>X</i>
12	1 WINDSCREEN MOULDING	\$	<i>na</i> 100.00 <i>X</i>
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00 <i>X</i>
	TOTAL	\$	1,244.82

TOTAL PARTS \$ 15,745.00**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>4400</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00 <i>3000</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>

Trans-cab Auto Services Pte Ltd

AAD1808-075

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 384B

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00 X
To repair and realign rear exhaust pipe.	\$	~ 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X

TOTAL \$ 6,780.00**Over All Total \$ 22,525.00**

21081.67

(PART-BY-PART)**Repair Days**~~10 DAYS~~

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD384B

Vehicle to be Exported: Yes

Intended De-registration Date: 13 Aug 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C002993

Chassis No.: VF1ABL15AUC282677

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 10 Jun 2016

First Registration Date: 10 Jun 2016

Transfer Count: 0

Actual ARF Paid: \$19,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 09 Jun 2024

PARF Rebate Amount: \$14,998.00

Intended COE Rebate Details

COE Expiry Date: 09 Jun 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$37,164.00

COE Rebate Amount: \$27,052.00

Total Rebate Amount: \$42,050.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Aug 2018

OK



Service Request Details

Claim

S8M00S0E

Reference

None 

Loss Date

August 12, 2018

Request Date

August 21, 2018

Due Date

August 29, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHD384B

Make

TPVD RENAULT

Model

LATITUDE-2.0 L (A)

Service Address

Primary Contact/Insured

ONG PLUMBING AND ELECTRICAL PTE LTD

BLK 114 PASIR RIS STREET 11, #13-575, 510114, Singapore

96259968

Claim Handler

OH Vale

6568804897

vale.oh@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

LETTER OF UNDERTAKING

I/We, ONG PLUMBING AND ELECTRICAL PTE LTD, the owner of vehicle no. BAF 8125R

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, _____

Signed and Acknowledge by:

* 51254404I
Nric no. and signature of policyholder

* 
Company Stamp

13/08/2018
Date

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1808-075

Your Ref : GBF8125R

Date : 16.July 2019

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SHD0384B AND GBF8125R ON 12/08/18 03:10 PM ALONG PIE SLIP ROAD TOWARD TOA PAYOH

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	5,182.28
2.	Loss of Rental for <u>3</u> days @ \$ <u>103.60</u> per day	\$	310.80
3.	Loss of Income for <u>3</u> days @ \$ <u>50</u> per day	\$	150.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	5,650.57

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)



Re:RE: TP MANDATE IA -S8M00S0E

Type

 Question

Message

Hi Pls proceed, tks-VO

Reply



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/ASM18015192/Kwa3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 05-08-2019



ATTN: VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 8125R	Veh. Inspected	SHD 384B
Policy No.	P1915797	Coverage (\$)	0.00
Claim No.	S8M00S0E	Excess (\$)	0.00
Assign From		Assign Date	20/08/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF1ABL15AUC282677	Colour	METALLIC WHITE / RED
Odometer	352196	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	6 mm
L/H Front Tyre	215/60 R16	GITI	6 mm
R/H Rear Tyre	215/60 R16	GITI	9 mm
L/H Rear Tyre	215/60 R16	GITI	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/08/2018	Inspection Date	20/08/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2.500 Working Days
-------------------------------------	--------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 384B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR (CONSISTENT)	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	DENTED	768.84	768.84
1	BUMPER BRACKET CTR REAR (CONSISTENT)	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH (CONSISTENT)	BROKEN	43.61	43.61
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	135.97	-
1	BUMPER RETAINER LH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR (CONSISTENT)	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	225.95	-
1	OUTER PANEL REAR (END PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	SERVICEABLE	404.56	-
1	TAILLAMP RH (CONSISTENT)	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	BOOT REAR (CONSISTENT)	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER (CONSISTENT)	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP (CONSISTENT)	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH (CONSISTENT)	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH (CONSISTENT)	CRACKED	493.35	493.35
1	BOOT BADGE 'RENAULT' (CONSISTENT)	NECESSARY	225.36	225.36
1	BOOT BADGE (CONSISTENT)	NECESSARY	225.36	225.36
1	BOOT STRUT LH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT STRUT RH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-

Report Ref No. CC3/ASM18015192/Kwa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM (CONSISTENT)	SERVICEABLE	586.45	-
1	BOOT SWITCH (CONSISTENT)	SERVICEABLE	168.13	-
1	BOOT LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH (CONSISTENT)	TO REPAIR SEE LABOUR	74.40	-
	LESS 10% DISCOUNT		-1,450.76	-364.25
			13,056.85	3,278.25
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN) (CONSISTENT)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN) (CONSISTENT)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN) (CONSISTENT)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN) (CONSISTENT)	SERVICEABLE	17.82	-
2	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
			1,244.82	765.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00

Report Ref No. CC3/ASM18015192/Kwa3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BRACKET SIDE LH REAR, BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, OUTER PANEL REAR (END PANEL), TAILLAMP PANEL RH, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK AND BOOT LOCK CATCH. TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	2,200.00	300.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	-
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			6,780.00	800.00
GRAND TOTAL			21,081.67	4,843.25
RECOMMENDED COST OF REPAIRS				4,843.25

Report Ref No. CC3/ASM18015192/Kwa3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.