

Trans-cab Auto Services Pte Ltd

AAD1808-075

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 384B

Not Authorised
Recovery B4 paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 384B

VF1ABL15AUC282677

RENAULT

LATITUDE

12.8.2018

AXA**PART****LIST**

1	1 BUMPER COVER REAR	\$	B 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	Net 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	Sn 113.47	X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	Sn 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	Sn 44.99	X
6	1 BUMPER REFLECTOR RH	\$	Bu 43.61	✓
7	1 BUMEP R BRACKET SIDE LH REAR	\$	R 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	Sn 44.99	X
9	1 BUMPER REFLECTOR LH	\$	Sn 43.61	X
10	1 BUMPER BEAM REAR	\$	777.52	?
11	1 BUMPER BEAM BRACKET LH REAR	\$	R 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	225.95	?
13	1 OUTER PANEL REAR (End Panel)	\$	R 1,471.77	X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn 404.56	X
15	1 TAILLAMP RH	\$	Sn 552.55	X
16	1 TAILLAMP PANEL RH	\$	R 986.70	X
17	1 BOOT REAR	\$	R 2,872.68	X
18	1 BOOT FINISHER	\$	Sn 470.06	X
19	1 BOOT WHEATERSTRIP	\$	Sn 323.05	X
20	1 BOOT REFLECTOR LAMP LH	\$	Sn 493.35	X
21	1 BOOT REFLECTOR LAMP RH	\$	CM 493.35	✓
22	1 BOOT BADGE 'RENAULT'	\$	Net 225.36	—
23	1 BOOT BADGE	\$	Net 225.36	—
24	1 BOOT STRUT LH	\$	Sn 276.08	} X
25	1 BOOT STRUT RH	\$	Sn 276.08	
26	1 BOOT HINGE LH	\$	R 367.84	
27	1 BOOT HINGE RH	\$	R 367.84	
28	1 BOOT INNER TRIM	\$	Sn 586.45	
29	1 BOOT SWITCH	\$	Sn 168.13	

Trans-cab Auto Services Pte Ltd

AAD1808-075

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 384B

30	1 BOOT LOCK	\$	<i>n</i> 202.67 <i>X</i>
31	1 BOOT LOCK CATCH	\$	<i>n</i> 74.40 <i>X</i>
		\$	14,507.62
		10% \$	7.44
		\$	14,500.18

Special Nett

1	1SET PARKING AID	\$	<i>Shay</i> 700.00 <i>600.00</i>
2	1SET REAR BUMPER CLIP	\$	<i>n</i> 66.00 <i>—</i>
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>n</i> 33.00 <i>—</i>
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>n</i> 10.00 <i>X</i>
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>n</i> 20.00 <i>X</i>
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>n</i> 10.00 <i>X</i>
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>n</i> 20.00 <i>X</i>
8	1SET BUMPER LOWER REAR RIVET	\$	<i>n</i> 22.00 <i>X</i>
9	1SET BUMPER LOWER REAR CLIP	\$	<i>n</i> 66.00 <i>—</i>
10	1 EXHAUST MOUNTING REAR	\$	<i>Sh</i> 17.82 <i>X</i>
11	2 REAR WINDSCREEN SELANT	\$	<i>n</i> 80.00 <i>X</i>
12	1 WINDSCREEN MOULDING	\$	<i>n</i> 100.00 <i>X</i>
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>n</i> 100.00 <i>X</i>
	TOTAL	\$	1,244.82

TOTAL PARTS \$ 15,745.00**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>4401</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00 <i>3001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>n</i> 170.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>

Trans-cab Auto Services Pte Ltd

AAD1808-075

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 384B

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i>	170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	<i>X</i>
TOTAL	\$		6,780.00	

Over All Total	\$	22,525.00
-----------------------	-----------	------------------

(PART-BY-PART)

Repair Days

~~10 DAYS~~*2 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: