

22/8/2002

ASS. REC. BY:

REF:

CS/CTI18015193/71908157

Special Instruction:

Surveyor
Munir

Taufik

ASSIGNMENT (Office)

From (Person):

ehong Boon Sen

of

CTI

Date/Time: 20/8/18 @ 4:54pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S/L 42824

Insured:

SKU 5604J

at Workshop m/s

Platinum Perkz

Tel:

6741 0610

of

53 Ubi Ave 1 # 01-25

Policy No:

DMPCS N3074221802

Claim No:

8NM18D04007C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time:

10:10am 20/8/18

Person Contacted:

Dora

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	S/L 42824 - NA / FWD 18015036/24	DOA: 16/8/2018
	SKU 5604J - NA / FWD 18015036/24	DOA: 16/8/2018

(08/11/13) wof

ASS. REC. BY:

REF: CTF

ASSIGNMENT

CoE 2018 Nov.

From:

Date: 21/08/2018

Estimated Cost:

ON ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No:

S/L 42024

at Workshop m/s

platinum werkz

of

53 Ubi Ave 1 #01-25

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

\$11K.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

S/L 42824

Yr Regn: 2008 Nov

Type: ☒ M.Car ☐ M.Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

Make:

Suzuki S/L 4

c.c. 1586

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

174818

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JSA GY A21500202933

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orModi: Nil ☒ S/Rim ☐ STD A/Rim or

Tyre Size:

F:

R:

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

21/08/18 @ 1220

Survey held at

Platinum werkz

Des. of Damages: Frt / ☒ Rear ☐ O/S ☐ N/S ☐ UIC ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rebate \$ 8720

24/12/18

Inform w/s repair limit \$2000.

Taufik,

Confirm with w/s the phase 4/5/2000, 6 days

P/s check parts prices.
(Red to \$976.62, 75%)

RECEIVED 02 JAN 2019

Date/Time, File Pass to?

1) 01/1/2019

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

220

Transportation:

Photos

Others

TOTAL

Report Format:

net TP

Lump Sum / I.B.I. (\$

2000)

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18015193/T1qd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 21-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKU 5604J	Veh. Inspected	SJL 4282U
Policy No.	DMPCSN3074221802	Coverage (\$)	0.00
Claim No.	SNM18D04007C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	21/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/08/2018	Inspection Date	21/08/2018
Survey held at	PLATINUM WERKZ PTE. LTD. 53 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2018		20 Aug 2018 16:54 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:	GOH AH ENG, ID: S7204395B		
Main Claimant:	KWA KAM MOK, ID: S1318322H		
Vehicle Reg. No.:	SJL4282U	Date of Loss:	16/08/2018 17:00 - :59
Claim Type:	TP / SNM18D04007C02	Policy/Cover Note No.:	DMPCSN3074221802 (Comprehensive)
Vehicle Reg. No. (Insured):	SKU5604J	Policy No. (Claimant):	PNPV2018-00007844
		Excess:	S\$0.00
Repairer:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/08/2018]		
Driver/Custodian (Insured):	CHEE CHEN YEW (53 / Male), NRIC: S1694461J, Tel: +6591124887		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/08/2018 18:28
Date Of Accident	16/08/2018 17:50
Exact Location Of Accident	SLE (TPE) BEFORE EXIT 9
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL4282U
Insured/Policyholder	
Name Of Registered Owner	KWA KAM MOK
NRIC No	S1318322H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97549130
Alternative Phone No	OFFICE-97549130

Vehicle Particulars

Manufacturer	SUZUKI
Model	SX4 1.6HB AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00007844
Cover Note Number	

Driver

Name of Driver	EDWARD KWA PENG RONG (KE PINRONG)
NRIC No	S9423494H
Date Of Birth	27/06/1994
Occupation	INDOOR
Date Of Driving Pass	03/08/2017
Driving Experience	1 YEAR AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97549130
Fax Number	
Contact Number	OFFICE-97549130
Email Address	NOEMAIL

Address	BLK 746 WOODLANDS CIRCLE #05-732
Postcode	730746
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180816/2153.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU5604J
Vehicle Make/Model/Colour	HONDA VEZEL
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLF2087M
Vehicle Make/Model/Colour HONDA ELANTRA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name EDWARD KWA PENG RONG (KE PINRONG)
Approximate Age
Injuries Sustain NECK & BACK
Injured person in which vehicle? SJL4282U
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN ALONG SLE TOWARDS TPE BEFORE EXIT 9.

VEHICLE A:
SJL4282U

VEHICLE B:
SKL5604J

VEHICLE C:
SLF2087M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

FOLLOW POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(if driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/Pass No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20180816/2153

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

1 of 4

Report No: T/20180816/2153

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/08/2018 20:45		Vide Report No.:		Station Diary No.: 93	
Informant's Particulars					
Name of Informant: EDWARD KWA PENG RONG			Address: APT BLK 746 WOODLANDS CIRCLE #05-732 SINGAPORE 730746		
ID Type / ID No.: NRIC NO / S9423494H			Contact No.: Home/Office: Mobile: 97549130		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 24	Date of Birth: 27/06/1994	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Student			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 16/08/2018 18:00	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 SELETAR EXPRESSWAY TAMPINES EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Chain				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJL4282U	Car	SUZUKI	SX4 1.6HB AT		Slightly Damaged	2
SKU5604J	Car	HONDA	VEZEL 1.5X CVT			1
SLF2087M	Car	HYUNDAI	ELANTRA AD 1.6 GLS AT			0

Police Report



**SINGAPORE
POLICE FORCE**



T/20180816/2153

2 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20180816/2153

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	EDWARD KWA PENG RONG	ID No.	S9423494H
Related Vehicle	SJL4282U (Car)	Contact No.	97549130
Hospital/Clinic	PROHEALTH MEDICAL GROUP @ PUNGGOL DAMAI PTE LTD	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	16/08/2018	Date Discharge	16/08/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	Unknown Driver	ID No.	NIL
Related Vehicle	SKU5604J (Car)	Contact No.	91124887
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ROY	ID No.	NIL
Related Vehicle	SLF2087M (Car)	Contact No.	98436533
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 16/08/2018 at about 1800hrs, I was driving my car, white color Suzuki SX4, bearing registration plate no. SJL4282U, along SLE travelling towards TPE. The traffic volume was quite heavy at that time. Somewhere just before Exit 9, the car driving in front of me suddenly came to a stop. Therefore, I had to do an emergency brake and my car came to a stop. Few seconds later, I felt hard bump for twice. I came out of my car and discovered that it was a 3-car chain collision. The car which collided onto the rear of my car was a white color Honda Vezel, bearing registration plate no. SKU5604J, and the last car was a red color Hyundai Elantra, bearing registration plate no. SLF2087M.

Police Report



SINGAPORE
POLICE FORCE



T/20180816/2153

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

4 of 4

Report No. T/20180816/2153

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 MUHAMMAD HANAFI BIN ROSLI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

16/08/2018 20:45

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt MOHAMAD ZULFAZDLI BIN
ABDULLAH

Contact No.: 65476367

Classification Of Case:

Authentication Stamp

NP158

PLATINUM WERKZ PTE LTD

53, UBI AVENUE 1, #01-25, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408934
Contact: +65 6741 0610 Email: platinumwerkz@gmail.com FAX: 67410892

Estimate

Vehicle: SJL 4282U

Model: SUZUKI SX4

No	Particular	Qty	Amount (\$)
	<u>List Price</u>		
1	REAR TAILGATE	1PC	bt 834.86
2	REAR TAILGATE LOGO	1PC	nr 48.05
3	REAR TAILGATE EMBLEM "SUZUKI"	1PC	nr 36.65
4	REAR TAILGATE EMBLEM "SX4"	1PC	nr 35.60
5	REAR TAILGATE WEATHERSTRIP	1PC	ant 129.20
6	REAR TAILGATE LOCK SENSOR	1PC	bt 165.20
7	REAR TAILLAMP @ \$257.50	2PCS	Xm 515.00
8	REAR BUMPER REFLECTOR LH/RH @ \$68.00	2PCS	Xm 136.00
9	REAR BUMPER	1PC	de 518.75
10	REAR REFORCEMENT @ \$422.65	2PCS	bt 845.30
11	REAR BUMPER BRACKET @ \$91.50	2PCS	nr 183.00
12	REAR BUMPER SIDE RETAINER @ \$42.20	2PCS	nr 84.40
13	REAR BUMPER GARNISH (CENTRE) @ \$310.90	1 2PCS	de 621.80
14	REAR BUMPER GARNISH LH/RH @ \$98.00	2PCS	Xm 196.00
15	REAR END PANEL	1PC	bt 343.50
16	REAR TAILLAMP PANEL LH @ \$245.60	2PCS	Rp 491.20
17	REAR END PANEL INNER GARNISH	1PC	de 112.60
18	REAR FENDER GARNISH LH @ \$130.50	2PCS	Xm 261.00
19	REAR SPARE TYRES TANK	1PC	Rp 398.50
20	REAR TAILGATE INNER GARNISH	1PC	nr 258.60
21	REAR EXHAUST SILENCER	1PC	nr 326.55
22	REAR END PANEL INNER MEMBER	1PC	Rp 242.50
	Total		6,784.26
	Less 15%		(1,017.64)
	Sub-Total cost for parts		5,766.62

<u>Part Replacement - Special</u>			
	<u>Nett Item</u>		
1	REAR WINDSCREEN SEALANT SET	1SET	nr 80.00
2	REAR WINDSCREEN INNER FOAM TAPE	1SET	nr 65.00
3	REVERSE SENSOR	1SET	200 280.00 nr
4	REAR BUMPER CLIP	1SET	30 45.00 nr
5	REAR NUMBER PLATE C/W CASING	1SET	45 60.00 bt
	Sub-Total cost for parts		530.00

Labour & MISC Charges		
1	TO REMOVE , REFIX REAR WINDSCREEN	120 150.00
2	TO CHECK UP REAR ELECTRICAL WIRING	30 40.00
3	TO REMOVE AND REFIX REVERSE SENSOR	30 60.00
4	TO REMOVE , REFIX REAR INTERIOR UPHOLSTERY TO ASSIT REPAIR	60 120.00
5	TO RESPRAY UNDERCOATING	40 110.00
6	TO RESPRAY PAINTING & etc	800 1,200.00
7	PANEL BEATING , REMOVE & REPLACING	700 1,200.00
Sub-Total Labour		1,680.00
Grand Total		7,976.62

4126.62

62563561

Tanjiluh 97495749

WP

21/8/18 @ 1220

6days

sure lkk auto. com

Resurvey after repair

lumpsum.

[Signature]

23/8/18

Repair limit \$2000

w/s agree to repair

4/5 \$ 2000, 6days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	20 Aug 2018		20 Aug 2018 16:54 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GOH AH ENG, ID: S7204395B		
Main Claimant:	KWA KAM MOK, ID: S1318322H		
Vehicle Reg. No.:	SJL4282U	Date of Loss:	16/08/2018 17:00 - :59 [117 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04007C02	Policy/Cover Note No.:	DMPCSN3074221802 (Comprehensive)
Vehicle Reg. No. (Insured):	SKU5604J	Policy No. (Claimant):	PNPV2018-00007844
		Excess:	S\$0.00
Repairer:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/08/2018]		
Driver/Custodian (Insured):	CHEE CHEN YEW (53 / Male), NRIC: S1694461J, Tel: +6591124887		
Adj. Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SJL4282U (SNM18D04007C02)**
[SKU5604J]
TP
KWA KAM MOK
Aug 16 2018 5:00PM
[GOH AH ENG]
Platinum Werkz Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View In Browser ▼

Assessment Reports

No	Finalized On	National Assessment Centre Services (Ubi)	1 per page ▼	Thumbnail	Print
1	17/08/18 18:40	Accident Statement		Load HTM	

Photos/Images

No	Finalized On	National Assessment Centre Services (Ubi)	3 per page ▼	Thumbnail	Print
1	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
10	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
11	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
12	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
13	17/08/18 18:36	Accident Photo [Linked Accident Report Documents]		Load JPG	☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/12/18 12:55	General View		Load JPG ☒
2	31/12/18 12:55	General View		Load JPG ☒
3	31/12/18 12:55	General View		Load JPG ☒
4	31/12/18 12:55	General View		Load JPG ☒
5	31/12/18 12:55	General View		Load JPG ☒
6	31/12/18 12:55	General View		Load JPG ☒
7	31/12/18 12:55	General View		Load JPG ☒
8	31/12/18 12:55	General View		Load JPG ☒
9	31/12/18 12:55	General View		Load JPG ☒
10	31/12/18 12:55	General View		Load JPG ☒
11	31/12/18 12:55	General View		Load JPG ☒
12	31/12/18 12:55	General View		Load JPG ☒
13	31/12/18 12:55	General View		Load JPG ☒
14	31/12/18 12:55	General View		Load JPG ☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
15	31/12/18 12:55	General View	 Load JPG	☒
16	31/12/18 12:55	General View	 Load JPG	☒
17	31/12/18 12:55	General View	 Load JPG	☒
18	31/12/18 12:55	Odometer Reading	 Load JPG	☒
19	31/12/18 12:55	General View	 Load JPG	☒
20	31/12/18 12:55	General View	 Load JPG	☒
21	31/12/18 12:55	General View	 Load JPG	☒
22	31/12/18 12:55	General View	 Load JPG	☒
23	31/12/18 12:55	General View	 Load JPG	☒
24	31/12/18 12:55	General View	 Load JPG	☒
25	31/12/18 12:55	General View	 Load JPG	☒
26	31/12/18 12:55	General View	 Load JPG	☒
27	31/12/18 12:55	General View	 Load JPG	☒
28	31/12/18 12:55	General View	 Load JPG	☒
29	31/12/18 12:55	General View	 Load JPG	☒
30	31/12/18 12:55	General View	 Load JPG	☒
31	31/12/18 12:55	General View	 Load JPG	☒
32	31/12/18 12:55	General View	 Load JPG	☒
33	31/12/18 12:55	General View	 Load JPG	☒
34	31/12/18 12:55	General View	 Load JPG	☒
35	31/12/18 12:55	General View	 Load JPG	☒
36	31/12/18 12:55	General View	 Load JPG	☒
37	31/12/18 12:55	General View	 Load JPG	☒
38	31/12/18 12:55	General View	 Load JPG	☒
39	31/12/18 12:55	General View	 Load JPG	☒
40	31/12/18 12:55	General View	 Load JPG	☒
41	31/12/18 12:55	General View	 Load JPG	☒
42	31/12/18 12:55	General View	 Load JPG	☒
43	31/12/18 12:55	General View	 Load JPG	☒
44	31/12/18 12:55	General View	 Load JPG	☒
45	31/12/18 12:55	General View	 Load JPG	☒
46	31/12/18 12:55	General View	 Load JPG	☒
47	31/12/18 12:55	General View	 Load JPG	☒
48	31/12/18 12:55	General View	 Load JPG	☒
49	31/12/18 12:55	General View	 Load JPG	☒
50	31/12/18 12:55	General View	 Load JPG	☒
51	31/12/18 12:55	General View	 Load JPG	☒
52	31/12/18 12:55	General View	 Load JPG	☒
53	31/12/18 12:55	General View	 Load JPG	☒
54	31/12/18 12:55	General View	 Load JPG	☒
55	31/12/18 12:55	General View	 Load JPG	☒
56	31/12/18 12:55	General View	 Load JPG	☒
57	31/12/18 12:55	General View	 Load JPG	☒
58	31/12/18 12:55	General View	 Load JPG	☒
59	31/12/18 12:55	General View	 Load JPG	☒
60	31/12/18 12:55	General View	 Load JPG	☒
61	31/12/18 12:55	General View	 Load JPG	☒
62	31/12/18 12:55	General View	Load JPG	☒

Assessment Reports			1 per page ▾	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
63	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
64	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
65	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
66	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
67	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
68	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
69	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
70	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
71	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
72	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
73	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
74	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
75	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
76	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
77	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
78	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
79	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
80	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
81	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
82	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
83	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
84	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
85	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
86	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
87	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
88	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
89	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
90	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
91	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
92	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
93	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
94	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
95	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
96	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
97	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
98	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
99	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
100	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
101	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
102	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
103	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
104	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
105	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
106	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
107	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
108	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
109	31/12/18 12:59	Reinspection Photo	 Load JPG	☒
110	31/12/18 12:59	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
111	31/12/18 12:59	Reinspection Photo	 Load JPG	✓
112	31/12/18 12:59	Reinspection Photo	 Load JPG	✓
113	31/12/18 12:59	Reinspection Photo	 Load JPG	✓
114	31/12/18 12:59	Reinspection Photo	 Load JPG	✓
115	31/12/18 12:59	Reinspection Photo	 Load JPG	✓
116	31/12/18 12:59	Reinspection Photo	 Load JPG	✓
117	31/12/18 12:59	Reinspection Photo	 Load JPG	✓
118	31/12/18 12:59	Reinspection Photo	 Load JPG	✓
119	31/12/18 12:59	Reinspection Photo	 Load JPG	✓
120	31/12/18 12:59	Reinspection Photo	 Load JPG	✓
121	31/12/18 12:59	Reinspection Photo	 Load JPG	✓
122	31/12/18 12:59	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/08/18 16:53	PRS	 Load PDF	
2	20/08/18 16:54	OI GIA	 Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/08/18 18:36	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	✓
2	17/08/18 18:36	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	✓
3	17/08/18 18:36	Police Report [Linked Accident Report Documents]	 Load JPG	✓
4	17/08/18 18:36	Police Report [Linked Accident Report Documents]	 Load JPG	✓
5	17/08/18 18:36	Police Report [Linked Accident Report Documents]	 Load JPG	✓
6	17/08/18 18:36	Police Report [Linked Accident Report Documents]	 Load JPG	✓

Linked Accident Report Documents

Assessment Reports			View	View in Browser ▼
No	Finalized On	National Assessment Centre Services (Ubi)	1 per page ▼	✓
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/08/18 18:40	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/08/18 18:36	Accident Photo	 Load JPG	✓
2	17/08/18 18:36	Accident Photo	 Load JPG	✓
3	17/08/18 18:36	Accident Photo	 Load JPG	✓
4	17/08/18 18:36	Accident Photo	 Load JPG	✓
5	17/08/18 18:36	Accident Photo	 Load JPG	✓
6	17/08/18 18:36	Accident Photo	 Load JPG	✓
7	17/08/18 18:36	Accident Photo	 Load JPG	✓
8	17/08/18 18:36	Accident Photo	 Load JPG	✓
9	17/08/18 18:36	Accident Photo	 Load JPG	✓
10	17/08/18 18:36	Accident Photo	 Load JPG	✓
11	17/08/18 18:36	Accident Photo	 Load JPG	✓
12	17/08/18 18:36	Accident Photo	 Load JPG	✓
13	17/08/18 18:36	Accident Photo	 Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
Documentation			1 per page ▼	✓
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/08/18 18:36	Accident Sketch Plan	 Load JPG	✓
2	17/08/18 18:36	Accident Sketch Plan	 Load JPG	✓
3	17/08/18 18:36	Police Report	 Load JPG	✓
4	17/08/18 18:36	Police Report	 Load JPG	✓
5	17/08/18 18:36	Police Report	 Load JPG	✓
6	17/08/18 18:36	Police Report	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118015193/T1QD3S2
Date: 04/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3074221802
Claimant Vehicle No: SJL4282U Insured Vehicle No: SKU5604J
Date of Loss: 16/08/2018 Nature of Claim: TP Claim No: SNM18D04007C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJL4282U
Make & Model: SUZUKI SX4, 1.6 HB (A) Engine No: HIDDEN
Reg. Date: 01/11/2008 (Man. Year: 2008) Chassis No: JSAGYA21500202933
Colour: White Odometer: 174818 km
Engine Capacity: 1586 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,296.62	3,520.81	2,775.81	44.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,780.00	1,100.00	38.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,176.62	5,300.81	3,875.81	42.24
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	9,176.62	2,000.00	7,176.62	78.21

INSPECTION

Date of Assignment: 20/08/2018
Date Inspected: 21/08/2018 Inspected At: Platinum Werkz Pte Ltd (HQ)
53 Ubi Ave 1 01-25 Paya Ubi Industrial Park
Singapore 408934
Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2019)
Parts:	144	SUZUKI SX4 1.6 HB (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL4282U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	834.86 FL	*834.86 FL
2	1		*REAR TAILGATE LOGO	Necessary	48.05 FL	*48.05 FL
3	1		*REAR TAILGATE EMBLEM SUZUKI	Necessary	36.65 FL	*36.65 FL
4	1		*REAR TAILGATE EMBLEM SX4	Necessary	35.60 FL	*35.60 FL
5	1		*REAR TAILGATE WEATHERSTRIP	Cut	129.20 FL	*129.20 FL
6	1		*REAR TAILGATE LOCK SENSOR	Bent	165.20 FL	*165.20 FL
7	2		*REAR TAILLAMP	Not Necessary	515.00 FL	*- FL
8	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	136.00 FL	*- FL
9	1		*REAR BUMPER	Deformed	518.75 FL	*518.75 FL
10	2		*REAR REINFORCEMENT	Bent	845.30 FL	*845.30 FL
11	2		*REAR BUMPER BRACKET	Necessary	183.00 FL	*183.00 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	84.40 FL	*84.40 FL
13	2		*REAR BUMPER GARNISH (CENTRE)	Deformed 1pc Only	621.80 FL	*310.90 FL
14	2		*REAR BUMPER GARNISH LH/RH	Not Necessary	196.00 FL	*- FL
15	1		*REAR END PANEL	Bent	343.50 FL	*343.50 FL
16	2		*REAR TAILLAMP PANEL LH	Repair	491.20 FL	*- FL
17	1		*REAR END PANEL INNER GARNISH	Deformed	112.60 FL	*112.60 FL
18	2		*REAR FENDER GARNISH LH	Not Necessary	261.00 FL	*- FL
19	1		*REAR SPARE TYRE TANK	Repair	398.50 FL	*- FL
20	1		*REAR TAILGATE INNER GARNISH	Not Necessary	258.60 FL	*- FL
21	1		*REAR EXHAUST SILENCER	Not Necessary	326.55 FL	*- FL
22	1		*REAR END PANEL INNER MEMBER	Repair	242.50 FL	*- FL
23	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
24	1		*SET REAR WINDSCREEN INNER FOAM TAPE	Necessary	65.00 FS	*65.00 FS
25	1		*SET REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
26	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
27	1		*SET REAR NUMBER PLATE C/W CASING	Bent	60.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,314.26	4,068.01
- List Item Discount on L Items 15.00/15.00% (\$\$)	1,017.64	547.20
Total Parts (\$\$)	6,296.62	3,520.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIX REAR WINDSCREEN.	New	150.00	120.00
2	TO CHECK UP REAR ELECTRICAL WIRING.	New	40.00	30.00
3	TO REMOVE AND REFIX REVERSE SENSOR.	New	60.00	30.00
4	TO REMOVE, REFIX REAR INTERIOR UPHOLSTERY TO ASSIST REPAIR.	New	120.00	60.00
5	TO RESPRAY UNDERCOATING.	New	110.00	40.00
6	TO RESPRAY PAINTING & ETC.	New	1,200.00	800.00
7	PANEL BEATING, REMOVE & REPLACING.	New	1,200.00	700.00
Gross Labour Cost (S\$)			2,880.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >