

ASS. REC. BY:

REP:

CS/CTI18015195/ Nsd3

Special Instruction:

SURVEYOR
merimen

From (Person):

Naz
Gleane Cheong

ASSIGNMENT (Office)

of CTI

Date/Time: 20/8/18 @ 4:09pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 505R

Insured:

SBW 68K

at Workshop in/s

Stuttgart Auto

Tel:

63602845

of

12 Singul Karut Ave

Policy No:

DMPCSN/20416/806

Claim No:

8NM18D03990C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/08/2018

CA / REV / REP. / REV 24 HRS (up)

23/08/2018 @ 2pm OW

Date/Time:

10:26am @ 21/8/18

Person Contacted:

Eva

H.O.D. Endorsement:

Vehicle IN ☒ OUT

Date/Time

Action/Instruction

(✓) Estimate

SKQ 505R - NBA/CTI18014911/Y

D.O.A. 15/8/18

SBW 68K - NBA/CTI18014911/Y

D.O.A. 15/8/18

22/10/18

Confirmed PIR \$ 6,002.46 @ 3 days with Naz
(\$ 6,180.00 Red - 16%)

ISS. REC. BY: wlf

REF: CTI

NAZ

ASSIGNMENT

From: Date: 23/8/18

Estimated Cost

Of: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKQ 505R

at Workshop m/s

Stuttgart Auto

of

12 Singel Kadut Ave

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

pmo owner waiting

Make of Veh:

Eva

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

1 up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

3KQ 505R

Yr Regn: 25 NOV 2014

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make

PORSCHE BOXSTER

cc 2,706

Colour

RED

A/C ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading

41,008

T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No:

C/No:

WPOZ 22982 FK 110174

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size:

F:

165 / 35 R20

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

5

mm

R/Bal

5

mm

L/Bal

5

mm

L/Bal

5

mm

D.O.A

15/08/18

D.O.I

23/8/18

Survey held at

STUTTGART AUTO

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 1 OCT 2018

CTI P/P

[Signature]

23/10/2018

Date/Time, File Pass to?

23/10/18

1)

typ. 4

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 6,002.46 r/p)



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS



China Taiping Insurance (S) Pte Ltd		NAME : Mr Ong Boon Tiong	WIP : 36704
3 Anson Rd, #16-00		ADDRESS : 65C Lorong M Telok Kurau	EXCESS :
Springleaf Tower		Singapore 423391	DATE: 17.08.2018
Singapore, 079909		TEL :	
ATTN. : MOTOR CLAIMS			
FAX :			
VEH NO :	SKQ505R	DATE IN :	CONTACT PERSON : EVA 63602846
CHASSIS NO :	WP0ZZZ98ZFK110174	MILEAGE :	TYPE OF CLAIM : TP AGAINST 5BW68K
MODEL :	BOXSTER	DATE REG.: 25.11.2014	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
1	FRONT BUMPER	1		\$ 1,730.90
2	NUMBER PLATE HOLDER	1		\$ 38.50
	TOTAL PARTS			\$ 1,769.40
	LESS 10%			\$ 176.94
	TOTAL PARTS COST			\$ 1,592.46
	Labour Description			
1	TO REMOVE / REPLACE FRONT BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 3,120.00
2	TO RESPRAY FRONT BUMPER.			\$ 1,500.00
3	TO SUPPLY 1 PC NUMBER PLATE WITH CASING. (NO CASING)		NETT	\$ 70.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 250.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		NETT	\$ 600.00
6	SUNDRIES.		NETT	\$ 50.00
	TOTAL LABOUR		\$ -	\$ 5,590.00
	TOTAL PARTS		\$ -	\$ 1,592.46
	TOTAL		\$ -	\$ 7,182.46
	LESS EXCESS		\$ -	\$ -
	TOTAL AFTER EXCESS		\$ -	\$ -
	GST 7%		\$ -	\$ -
	GRAND TOTAL		\$ -	\$ -

REMARKS

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A

QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED
IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

NAZ LKK

23/8/18 1415

PIP

3 DAYS

BEFORE PAINT PHOTO

67415434

Naz@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


29/8/18



EUROKARS GROUP

China Taiping Insurance (S) Pte Ltd		NAME : Mr Ong Boon Tiong		WIP : 36704	
3 Anson Rd, #16-00		ADDRESS : 65C Lorong M Telok Kurau		EXCESS :	
Springleaf Tower		Singapore 423391		DATE: 17.08.2018	
ATTN. : MOTOR CLAIMS		TEL :			
FAX :					
VEH NO :	SKQ505R	DATE IN :		CONTACT PERSON :	EVA 63602846
CHASSIS NO :	WP0ZZZ98ZFK110174	MILEAGE :		TYPE OF CLAIM :	TP AGAINST SBW68K
MODEL :	BOXSTER	DATE REG.:	25.11.2014	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description				
	QTY			REVISED	PRICES
1	FRONT BUMPER	1	P981-505-010-53-	\$ 1,730.90	\$ 1,730.90
2	NUMBER PLATE HOLDER	1	P981-701-051-00-1E0	\$ 38.50	\$ 38.50
	TOTAL PARTS			\$ 1,769.40	\$ 1,769.40
	LESS 10%			\$ 176.94	\$ 176.94
	TOTAL PARTS COST			\$ 1,592.46	\$ 1,592.46
	Labour Description				
1	TO REMOVE / REPLACE FRONT BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT			\$ 2,340.00	\$ 3,120.00
2	TO RESPRAY FRONT BUMPER			\$ 1,200.00	\$ 1,500.00
3	TO SUPPLY 1 PC NUMBER PLATE WITHOUT CASING			\$ 70.00	\$ 70.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 200.00	\$ 250.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 600.00	\$ 600.00
6	SUNDRIES.			NETT	\$ 50.00
	TOTAL LABOUR			\$ 4,410.00	\$ 5,590.00
	TOTAL PARTS			\$ 1,592.46	\$ 1,592.46
	TOTAL			\$ 6,002.46	\$ 7,182.46
	LESS EXCESS			\$ -	\$ -
	TOTAL AFTER EXCESS			\$ 6,002.46	
	GST 7%			\$ 420.17	\$ -
	GRAND TOTAL			\$ 6,422.63	\$ -

NUMBER OF DAYS:3 WORKING DAYS(EXCLUDE WAITING FOR SURVEY.AUTHORIZATION.PARTS.SATURDAY.SUNDAY AND PUBLIC HOLIDAY)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2018		20 Aug 2018 16:09 Edit Adj Rpt	\$46,002.46 Edit Estimates	\$46,002.46 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHEW CHIN YAM LAWRENCE , ID: S1471311E								
Main Claimant:	GEOFFREY ONG BOON TIONG , ID: S7216218H								
Vehicle Reg. No.:	SKQ505R	Date of Loss:	15/08/2018 11:00 - :59 [44 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03990C02	Policy/Cover Note No.:	DMPCSN1204161806 (Comprehensive)						
Vehicle Reg. No. (Insured):	SBW68K	Policy No. (Claimant):	S117V16127/VPS/R02						
		Excess:	\$0.00						
Repairer:	Stuttgart Auto Pte Ltd (HQ) 27A Tanjong Penjuru, 609042 Sungei Kadut - Tel: 6331 0680 / 6331 0686 (DID)								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 30/08/2018]								
Driver/Custodian (Insured):	CHEW CHIN YAM LAWRENCE (56 / Female), NRIC: S1471311E								
Adj Asg. Remarks:	EST \$7182.46, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKQ505R (SNM18D03990C02)
[SBW68K]

TP

GEOFFREY ONG BOON TIONG

Aug 15 2018 11:00AM

[CHEW CHIN YAM LAWRENCE]

Stuttgart Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Video									1 per page		☒
No	Finalized On	Stuttgart Auto Pte Ltd (HQ)							Thumbnail	Print	
1	16/08/18 09:33	Video - Accident [Linked Accident Report Documents]							Load MP4		
Assessment Reports									1 per page		☒
No	Finalized On	Stuttgart Auto Pte Ltd (HQ)							Thumbnail	Print	
1	16/08/18 09:36	Accident Statement							Load HTM		
Photos/Images									3 per page		☒
No	Finalized On	Stuttgart Auto Pte Ltd (HQ)							Thumbnail	Print	
1	16/08/18 09:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
2	16/08/18 09:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
3	16/08/18 09:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
4	16/08/18 09:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
5	16/08/18 09:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
6	16/08/18 09:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
7	16/08/18 09:31	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	28/08/18 17:09	General View							Load JPG	☒	
2	28/08/18 17:09	General View							Load JPG	☒	
3	28/08/18 17:09	General View							Load JPG	☒	
4	28/08/18 17:09	General View							Load JPG	☒	
5	28/08/18 17:09	General View							Load JPG	☒	
6	28/08/18 17:09	General View							Load JPG	☒	
7	28/08/18 17:09	General View							Load JPG	☒	
8	28/08/18 17:09	General View							Load JPG	☒	
9	28/08/18 17:09	General View							Load JPG	☒	
10	28/08/18 17:09	General View							Load JPG	☒	
11	28/08/18 17:09	General View							Load JPG	☒	
12	28/08/18 17:09	General View							Load JPG	☒	
13	28/08/18 17:09	General View							Load JPG	☒	
14	28/08/18 17:09	General View							Load JPG	☒	
15	28/08/18 17:09	General View							Load JPG	☒	
Documentation									1 per page		☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	20/08/18 16:07	EMAIL FM TRANS							Load PDF		
2	20/08/18 16:07	REPAIR EST WITH TP GIA							Load PDF		
3	20/08/18 16:07	OI GIA							Load PDF		

Video			1 per page	☒
No	Finalized On	Stuttgart Auto Pte Ltd (HQ)	Thumbnail	Print
			1	
No	Finalized On	Stuttgart Auto Pte Ltd (HQ)	Thumbnail	Print
1	16/08/18 09:27	Sketch Plan [Linked Accident Report Documents]	1	Load TIF

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Stuttgart Auto Pte Ltd (HQ)	Thumbnail	Print
1	16/08/18 09:33	Video - Accident	1	Load MP4
Assessment Reports			1 per page	☒
No	Finalized On	Stuttgart Auto Pte Ltd (HQ)	Thumbnail	Print
1	16/08/18 09:36	Accident Statement	1	Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Stuttgart Auto Pte Ltd (HQ)	Thumbnail	Print
1	16/08/18 09:31	Accident Photo	1	Load JPG
2	16/08/18 09:31	Accident Photo	1	Load JPG
3	16/08/18 09:31	Accident Photo	1	Load JPG
4	16/08/18 09:31	Accident Photo	1	Load JPG
5	16/08/18 09:31	Accident Photo	1	Load JPG
6	16/08/18 09:31	Accident Photo	1	Load JPG
7	16/08/18 09:31	Accident Photo	1	Load JPG
Documentation			1 per page	☒
No	Finalized On	Stuttgart Auto Pte Ltd (HQ)	Thumbnail	Print
1	16/08/18 09:27	Sketch Plan	1	Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118015195/NSD3Q2

Date: 26/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1204161806
Claimant Vehicle No:	SKQ505R	Insured Vehicle No:	SBW68K
Date of Loss:	15/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D03990C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ505R	Engine No:	F03209
Make & Model:	PORSCHE BOXSTER, 2.7 (A)	Chassis No:	WP0ZZZ98ZFK110174
Reg. Date:	25/11/2014 (Man. Year: 2014)	Odometer:	41008 km
Colour:	Red		
Engine Capacity:	2706 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/35 R20	Rear Tyre Size:	265/35 R20
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,712.46	1,662.46	50.00	2.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,470.00	4,340.00	1,130.00	20.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,182.46	6,002.46	1,180.00	16.43
+ GST 7.00/7.00% (S\$)	502.77	420.17	82.60	16.43
Nett Amount (S\$)	7,685.23	6,422.63	1,262.60	16.43

INSPECTION

Date of Assignment:	20/08/2018	
Date Inspected:	23/08/2018	Inspected At: 12 SUNGEI KADUT AVE. SINGAPORE 729648 Repairer: Stuttgart Auto Pte Ltd (HQ)
Estimated Period of Repair:	3.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Oct 2018)	
Parts:	N/A	PORSCHE BOXSTER 2.7 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ505R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,730.90 FL	*1,730.90 FL
2	1		*NUMBER PLATE HOLDER	Cracked	38.50 FL	*38.50 FL
3	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
4	1		*NUMBER PLATE (NO CASING)	Cracked	70.00 FS	*70.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,889.40	1,839.40
- List Item Discount on L Items 10.00/10.00% (S\$)	176.94	176.94
Total Parts (S\$)	1,712.46	1,662.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE /REPLACE FRONT BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	3,120.00	2,340.00
2	TO RESPRAY FRONT BUMPER	New	1,500.00	1,200.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	200.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
Gross Labour Cost (S\$)			5,470.00	4,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >