

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKU2547K/18008122

20th August 2018

The Manager
Motor Claim Department
AXA Insurance Pte Ltd
8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

not allowed
take photo before party.
24/8/18
4 days.
9/12/18

Date of Accident : 18th August 2018
Location : Junction of Rivervale Drive & Punggol Road
Third Party Claim Vehicle No : SJK 8916 D
Repair Cost For Vehicle No : SKU 2547 K Mercedes C180

Estimate Supply of Parts & Labours *net item*

No.	Particulars	Qty	Price	Amounts
1	Rear bumper fascia <i>D.S</i>	1	1,687.00	\$ 1,687.00 —
2	Rear bumper clips <i>nu</i>	1 set	12.00	\$ 12.00 ✓
3	Rear bumper side retainer L&RH <i>nu</i>	2	52.00	\$ 104.00 —
4	Rear bumper lower lip <i>D.S</i>	1	215.00	\$ 215.00 ✓
5	Rear bumper towing cover <i>nu</i>	1	64.00	\$ 64.00 —
6	Rear bumper reinforcement beam	1	632.00	\$ 632.00 ?
7	Rear bumper parking sensor	4	282.00	\$ 1,128.00 ?
8	Rear bumper chrome L&RH <i>nu</i>	2	92.00	\$ 184.00 ?
9	Rear bumper chrome centre <i>nu</i>	1	247.00	\$ 247.00 —
10	Rear bumper dust cover RH & centre	2	87.00	\$ 174.00 ?
11	Rear bumper inner bracket L&RH	2	34.00	\$ 68.00 ?
12	Rear bumper lower bracket	1	35.00	\$ 35.00 ?
13	Rear bumper bracket L&RH	2	58.00	\$ 116.00 ?
14	Tail lamp L&RH	2	732.00	\$ 1,464.00 ?
15	Rear end panel <i>nu</i>	1	1,372.00	\$ 1,372.00 ✓
16	Rear boot w/strip <i>11</i>	1	178.00	\$ 178.00 ✓
17	Rear bumper lower flash guard	1	108.00	\$ 108.00 ?
18	Rear end panel sealer (s/net) <i>11</i>	1	180.00	\$ 180.00 x
				\$ 7,968.00

50%?

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKU2547K/18008122

20th August 2018

Balance b/f

\$ 7,968.00

Labour Charges :-

Cut out, renew, knocking & welding rear end panel, rear bumper reinforcement beam, rear bumper fascia, remove & install all damage parts, straighten & re-align body

Amounts

\$ 1,800.00

Spray painting on damage parts

\$ 1,400.00

Tuff-kote on damage parts

\$ 40.00

Remove & refix, diagnostic & reset rear bumper sensor

\$ 280.00

Check all lighting after repairs

\$ 65.00

Labour Charge

\$ 3,585.00

Total Amount

\$11,553.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: