

ASS. REC. BY:

REF:

CS/SFF18015199/Tigber

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Lim Wei Yea

of

SFF

Date/Time: 20081218 446pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

QX 226M

Insured:

at Workshop m/s

SMRT

Tel:

of

60 Woodlands Ind Park E4

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

0409 2018

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

QX 226M - CS/SFF18013862/Nsb

DIA: 25/9/2018

05/1/18 @ 4:40pm revert to Wei Yea by email.

Material = \$4098; Man hrs = 57 hrs.

Tanfer

REF:

SPF

ADDITIONAL

From: _____ Date: _____
 Estimated Cost: _____
 (OD) TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m's _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

(Policy Condition)


Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Veh No: QX226M Yr Regd: _____
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota ALTIS C.C. 1598
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 255835 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/65R15
 R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken

Front _____ Rear 6
 R/Bal. 6 mm R/Bal. _____ mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 4/9/18
 Survey held at 2B sq Unit Dr
 Des. of Damages Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

704 - 185/65R15 .Falken.
185/65R15 ~

RECEIVED 05 OCT 2018

Date/Time: File Pass to?

to 04/10/18 Tanfer

Date/Time: File Return to?

21

Report Format :

Lump Sum / LB t: \$

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp \$
☐ : Interview \$
☐ : Tech Insp \$
☐ : Appraisal \$

Survey Fee

Transportation

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

11. 12. 13. 14. 15. 16. 17. 18. 19. 20.

21. 22. 23. 24. 25. 26. 27. 28. 29. 30.

31. 32. 33. 34. 35. 36. 37. 38. 39. 40.

41. 42. 43. 44. 45. 46. 47. 48. 49. 50.

51. 52. 53. 54. 55. 56. 57. 58. 59. 60.

61. 62. 63. 64. 65. 66. 67. 68. 69. 70.

71. 72. 73. 74. 75. 76. 77. 78. 79. 80.

200

200

Catherine Chong (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Monday, 20 August, 2018 4:46 PM
To: assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); 'Ai Phing (LKKAuto'; 'Shiau Chan (LKKAuto'
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX226M)
Attachments: QX226M.XLSX

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX 226M

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Shiau Chan (LKKAuto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Thursday, 4 October 2018 11:34 AM
To: Shiau Chan (LKKAuto); assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF)
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX226M)

Hi Shiau Chan,

Please proceed to close this.

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Thursday, 4 October 2018 11:21
To: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX226M)

Dear Sir/Madam,

Kindly advise whether we can submit our report accordingly to your good office.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Wednesday, 5 September 2018 6:31 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX226M)

Hi Shiau Chan,

Received with thanks.
Will review and let you know if any queries.

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Wednesday, 5 September 2018 16:40
To: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX226M)

Dear Wei Yea,

Please find the attachment of QX 226M.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 27 August 2018 6:13 PM
To: 'Wei Yea LIM (SPF)' <LIM_Wei_Yea@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: 'Kim Pang CHAY (SPF)' <CHAY_Kim_Pang@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN_Kwee_Huat@spf.gov.sg>; 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>; 'Bernard SEAH (SPF)' <Bernard_SEAH@spf.gov.sg>; 'Peng Seng NG (SPF)' <NG_Peng_Seng@spf.gov.sg>; 'Rashid ABU HASAN (SPF)' <Rashid_Abu_Hasan@spf.gov.sg>; Ai Phing (LKKAUTO)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 5 September 2018 4:40 PM
To: 'Wei Yea LIM (SPF)'; assignments
Cc: 'Kim Pang CHAY (SPF)'; 'Kwee Huat TAN (SPF)'; 'Perry HE (SPF)'; 'Bernard SEAH (SPF)'; 'Peng Seng NG (SPF)'; 'Rashid ABU HASAN (SPF)'
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX226M)
Attachments: QX226 Photo.pdf; QX 226M.xls

Dear Wei Yea,

Please find the attachment of QX 226M.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 27 August 2018 6:13 PM
To: 'Wei Yea LIM (SPF)' <LIM_Wei_Yea@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: 'Kim Pang CHAY (SPF)' <CHAY_Kim_Pang@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN_Kwee_Huat@spf.gov.sg>; 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>; 'Bernard SEAH (SPF)' <Bernard_SEAH@spf.gov.sg>; 'Peng Seng NG (SPF)' <NG_Peng_Seng@spf.gov.sg>; 'Rashid ABU HASAN (SPF)' <Rashid_Abu_Hasan@spf.gov.sg>; Ai Phing (LKKAUTO) <aiphing@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX226M)

Dear Wei Yea,

Please be informed that our surveyor still pending appointment for survey from Mr Kong.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]
Sent: Monday, 27 August, 2018 5:40 PM
To: assignments <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; 'Ai Phing (LKKAUTO)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAUTO)' <siewsc@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX226M)

Hi Catherine,

May I check if there is an update on this appraisal?

Date:	02.08.2018	Date:		Date:	
Sign:		Sign:		Sign:	
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	
All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made					



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR:	SMRT	VEH TYPE:	FRC	UNIT:	SERANGOON NPC
VEH NO:	QX226M	REPAIR TYPE:	ACCIDENT		
VEH MAKE/MODEL:	TOYOTA ALTIS	ODOMETER:	255835		

Reference No. 0226/SPF/4W/18/07/38

iLMS No. 1100008872

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Rear Bumper <i>de ✓</i>	\$234.00	1		234.00	234.00
1.2	Both Side Rear Bumper Retainers (Left & Right) <i>nw ✓</i>	\$34.00	2		34.00	68.00
1.3	Reverse Sensor <i>bt ✓</i>	\$200.00	1		200.00	200.00
1.4	Rear End Panel <i>bt ✓</i>	\$264.00	1		264.00	264.00
1.5	Rear End Panel Garnish <i>cu ✓</i>	\$90.00	1		90.00	90.00
1.6	Rear Bumper Reinforcement <i>bt ✓</i>	\$66.00	1		66.00	66.00
1.7	LH Outer Tail Lamp <i>cu ✓</i>	\$162.00	1		162.00	162.00
1.8	RH Outer Tail Lamp <i>cu ✓</i>	\$162.00	1		162.00	162.00
1.9	Boot Lid Cover <i>bt ✓</i>	\$324.00	1		324.00	324.00
1.10	Boot Lid Cover Trim <i>X</i>	\$96.00	1		96.00	96.00
1.11	Car Boot Inner Lock <i>bt ✓</i>	\$60.00	1		60.00	60.00
1.12	LH Boot Lamp <i>cu ✓</i>	\$72.00	1		72.00	72.00
1.13	Car Boot Rubber Seal <i>fu ✓</i>	\$72.00	1		72.00	72.00
1.14	Car Boot Insulator <i>cu ✓</i>	\$240.00	1		240.00	240.00
1.15	Front Bumper <i>de ✓</i>	\$234.00	1		234.00	234.00
1.16	Both Side Front Bumper Retainers (Left & Right) <i>de ✓</i>	\$30.00	2		30.00	60.00
1.17	Front Bumper Lower Grille <i>bt mis ✓</i>	\$48.00	1		48.00	48.00
1.18	Front Number Plate <i>mis ✓</i>	\$50.00	1		50.00	50.00
1.19	Center Engine Under Cover <i>mis ✓</i>	\$72.00	1		72.00	72.00
1.20	Bonnet Stand <i>mis ✓</i>	\$30.00	1		30.00	30.00
1.21	Bonnet Stand Stopper <i>de ✓</i>	\$5.00	1		5.00	5.00
1.22	Bonnet Stand Holder <i>mis ✓</i>	\$15.00	1		15.00	15.00
1.23	Front Support Panel <i>bt ✓</i>	\$264.00	1		264.00	264.00
1.24	Front Bumper Reinforcement <i>bt ✓</i>	\$138.00	1		138.00	138.00
1.25	Front RH Door Frame Rubber Seal <i>X</i>	\$84.00	1		84.00	84.00
1.26	Front RH Door Scuff <i>X</i>	\$84.00	1		84.00	84.00
1.27	Front RH Door Step Cover <i>X</i>	\$84.00	1		84.00	84.00
1.28	Rear RH Door Step Cover <i>X</i>	\$84.00	1		84.00	84.00
1.29	Front LH Door Frame Rubber Seal <i>X</i>	\$84.00	1		84.00	84.00
1.30	Front LH Door Scuff <i>X</i>	\$84.00	1		84.00	84.00
1.31	Rear LH Door Step Cover <i>X</i>	\$84.00	1		84.00	84.00
1.32	RHS Safety Belt Cover <i>X</i>	\$180.00	1		180.00	180.00
1.33	LHS Safety Belt Cover <i>X</i>	\$180.00	1		180.00	180.00
1.34	Radiator <i>bt ✓</i>	\$456.00	1		456.00	456.00
1.35	Radiator Upper Hose <i>fw ✓</i>	\$24.00	1		24.00	24.00
1.36	Radiator Lower Hose <i>fw ✓</i>	\$26.00	1		26.00	26.00
1.37	Radiator Overflow Hose <i>de ✓</i>	\$26.00	1		26.00	26.00
1.38	Air-Con Condenser <i>bt ✓</i>	\$360.00	1		360.00	360.00
1.39	Air-Con Condenser Piping <i>bt ✓</i>	\$192.00	1		192.00	192.00
1.40	Air-Con Discharge Hose <i>bt ✓</i>	\$84.00	1		84.00	84.00
1.41	To Replace & Supply New Cushion Covers (Driver/Front Passenger/Rear Passenger) SOR 3, Item no. 9	\$1,134.00	1	0%	1134.00	1134.00 <i>5142</i>
2	Additional Services					
2.1	NA	\$0.00	0	0%	0.00	0.00
Remarks:					Parts Total:	\$ 6,276.00

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Rear Bumper:		5	0.00
	Remove & Replace Rear Bumper			
	Remove & Replace Both Side Rear Bumper Retainers (Left & Right)			
	Remove & Replace Reverse Sensor			
	Wiring for Reverse Sensor			
	Putty & Spray Paint for Rear Complete Bumper (2 colours)			
1.2	Rear End Panel & Rear Bumper Reinforcement:		8	0.00
	Remove & Replace Rear End Panel			
	Remove & Replace Rear End Panel Garnish			
	Remove & Replace Rear Bumper Reinforcement			
1.3	Outer Tail Lamps:		1.5	0.00
	Remove & Replace LH Outer Tail Lamp			

	Remove & Replace RH Outer Tail Lamp			
	Wiring for Both LH & RH Outer Tail Lamp			
1.4	Boot Lid Cover & LH Boot Lamp:		10	0.00
	Remove & Replace Boot Lid Cover			
	Remove & Replace Boot Lid Cover Trim			
	Remove & Replace Car Boot Inner Lock			
	Remove & Replace LH Boot Lamp			
	Remove & Replace Car Boot Rubber Seal			
	Replace Boot Lid Insulator			
	Wiring for LH Boot Lamp			
	Putty & Spray Paint for Boot Lid Cover (3 colours)			
1.5	Front Bumper:		5	0.00
	Remove & Replace Front Bumper			
	Remove & Replace Both Side Front Bumper Retainers (Left & Right)			
	Putty & Spray Paint for Front Complete Bumper (2 colours)			
1.6	Lower Grill, Front Number Plate & Engine Under Cover:		1	0.00
	Remove & Replace Front Number Plate			
	Replace Front Bumper Lower Grill			
	Replace Center Engine Under Cover			
1.7	Bonnet Stand:		0.5	0.00
	Replace Bonnet Stand			
	Replace Bonnet Stand Holder			
	Replace Bonnet Stand Stopper			
1.8	Front Support Panel & Front Bumper Reinforcement:	6	7	0.00
	Remove & Replace Front Support Panel			
	Remove & Replace front Bumper Reinforcement			
1.9	RHS Door Covers & Rubber Seal: ✕		2	0.00
	Remove & Replace Front RH Door Frame Rubber Seal ✕			
	Replace Front RH Door Scuff ✕			
	Replace Front RH Door Step Cover ✕			
	Replace Rear RH Door Step Cover ✕			
	Replace RHS Safety Belt Cover ✕			
1.10	LHS Door Covers & Rubber Seal: ✕		2	0.00
	Remove & Replace Front LH Door Frame Rubber Seal ✕			
	Replace Front LH Door Scuff ✕			
	Replace Rear LH Door Step Cover ✕			
	Replace LHS Safety Belt Cover ✕			
1.11	Radiator:	6	8	0.00
	Remove & Replace Radiator			
	Remove & Replace Radiator Upper Hose			
	Remove & Replace Radiator Lower Hose			
	Top Up Coolant for Radiator			
1.12	Air-Con Condenser:	8	12	0.00
	Remove & Replace Air-Con Condenser			
	Remove & Replace Air-Con Condenser Piping			
	Top Up Air-Con Gas			
1.13	Bonnet Cover:		2	0.00
	Remove & Replace "POLICE" Wordings Stickers (To be provided by AEMD)			
	Putty & Spray Paint for Bonnet Cover			
1.14	Rear LH Panel:		4	0.00
	Panel beating for Rear LH Panel:			
	Putty & Spray Paint for Rear LH Panel (3 colours)			
SUB-TOTAL			68	0.00
2	Additional Services			
2.1	Towing Service From Station to Workshop (SOR 8)	138.60	1	138.60
2.2	Return Service From Workshop to Station (SOR 7)	44.10	1	44.10
SUB-TOTAL			2	182.70
Labour Total:			S	182.70
GRAND TOTAL :			S	6,458.70
Total sum billed under SOR only :			S	182.70
Total sum billed under CVR only :			S	6,276.00
Contractor shall complete the entire repair within 40 working days upon vehicle collection date . (Include parts awaiting time)				

Verification of Scope of Work				
Contractor QC		Vetted By:		Approved By:
Name:	KONG SEW KUI	Name:		Name:

Registration No. QX 226M

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	REAR BUMPER	1	DEFORMED	\$234.00	\$234.00	
1.2	BOTH SIDE REAR BUMPER RETAINERS (LEFT & RIGHT)	2	NECESSARY	\$34.00	\$68.00	
1.3	REVERSE SENSOR	1	NOT WORKING	\$200.00	\$200.00	
1.4	REAR END PANEL	1	BENT	\$264.00	\$264.00	
1.5	REAR END PANEL GARNISH	1	CRACKED	\$90.00	\$90.00	
1.6	REAR BUMPER REINFORCEMENT	1	BENT	\$66.00	\$66.00	
1.7	LH OUTER TAIL LAMP	1	CRACKED	\$162.00	\$162.00	
1.8	RH OUTER TAIL LAMP	1	CRACKED	\$162.00	\$162.00	
1.9	BOOT LID COVER	1	BENT	\$324.00	\$324.00	
1.10	BOOT LID COVER TRIM	1	NOT NECESSARY	\$96.00	\$0.00	
1.11	CAR BOOT INNER LOCK	1	BENT	\$60.00	\$60.00	
1.12	LH BOOT LAMP	1	CUT	\$72.00	\$72.00	
1.13	CAR BOOT RUBBER SEAL	1	TORN	\$72.00	\$72.00	
1.14	CAR BOOT INSULATOR	1	CRACKED	\$240.00	\$240.00	
1.15	FRONT BUMPER	1	DEFORMED	\$234.00	\$234.00	
1.16	BOTH SIDE FRONT BUMPER RETAINERS (LEFT & RIGHT)	2	NECESSARY	\$30.00	\$60.00	
1.17	FRONT BUMPER LOWER GRILLE	1	MISSING	\$48.00	\$48.00	
1.18	FRONT NUMBER PLATE	1	MISSING	\$50.00	\$50.00	
1.19	CENTER ENGINE UNDER COVER	1	MISSING	\$72.00	\$72.00	
1.20	BONNET STAND	1	MISSING	\$30.00	\$30.00	

1.21	BONNET STAND STOPPER	1		DEFORMED	\$5.00	\$5.00	
1.22	BONNET STAND HOLDER	1		MISSING	\$15.00	\$15.00	
1.23	FRONT SUPPORT PANEL	1		BENT	\$264.00	\$264.00	
1.24	FRONT BUMPER REINFORCEMENT	1		BENT	\$138.00	\$138.00	
1.25	FRONT RH DOOR FRAME RUBBER SEAL	1		NOT NECESSARY	\$84.00	\$0.00	
1.26	FRONT RH DOOR SCUFF	1		NOT NECESSARY	\$84.00	\$0.00	
1.27	FRONT RH DOOR STEP COVER	1		NOT NECESSARY	\$84.00	\$0.00	
1.28	REAR RH DOOR STEP COVER	1		NOT NECESSARY	\$84.00	\$0.00	
1.29	FRONT LH DOOR FRAME RUBBER SEAL	1		NOT NECESSARY	\$84.00	\$0.00	
1.30	FRONT LH DOOR SCUFF	1		NOT NECESSARY	\$84.00	\$0.00	
1.31	REAR LH DOOR STEP COVER	1		NOT NECESSARY	\$84.00	\$0.00	
1.32	RHS SAFETY BELT COVER	1		NOT NECESSARY	\$180.00	\$0.00	
1.33	LHS SAFETY BELT COVER	1		NOT NECESSARY	\$180.00	\$0.00	
1.34	RADIATOR	1		BENT	\$456.00	\$456.00	
1.35	RADIATOR UPPER HOSE	1		TWISTED	\$24.00	\$24.00	
1.36	RADIATOR LOWER HOSE	1		TWISTED	\$26.00	\$26.00	
1.37	RADIATOR OVERFLOW HOSE	1		DEFORMED	\$26.00	\$26.00	
1.38	AIR-CON CONDENSER	1		BENT	\$360.00	\$360.00	
1.39	AIR-CON CONDENSER PIPING	1		BENT	\$192.00	\$192.00	
1.40	AIR-CON DISCHARGE HOSE	1		BENT	\$84.00	\$84.00	
2	SCOPE OF REPAIRS						
1.1	REAR BUMPER:						5
	Remove & replace rear bumper						
	Remove & replace both side rear bumper retainers (left & right)						
	Remove & replace reverse sensor						
	Wiring for reverse sensor						

[illegible]

[illegible]

[illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18015199/T1qbe2		
CONTRACT MANAGEMENT SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 01-11-2018		
ATTN : LIM WEI YEA		Code : SPF3		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		QX 226M	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	LIM WEI YEA	Assign Date	20/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053ZEE106101968	Colour	WHITE	
Odometer	255835	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	FALKEN	6 mm	
L/H Front Tyre	185/65 R15	FALKEN	6 mm	
R/H Rear Tyre	185/65 R15	FALKEN	6 mm	
L/H Rear Tyre	185/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	Inspection Date		04/09/2018	
Survey held at	2B SUNGEI KADUT DR			
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD			
5a. Remarks				



Registration No. QX 226M

S/N	ITEM DESCRIPTION	PARTS				MAN- HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	REAR BUMPER	1	DEFORMED	\$234.00	\$234.00	
1.2	BOTH SIDE REAR BUMPER RETAINERS (LEFT & RIGHT)	2	NECESSARY	\$34.00	\$68.00	
1.3	REVERSE SENSOR	1	NOT WORKING	\$200.00	\$200.00	
1.4	REAR END PANEL	1	BENT	\$264.00	\$264.00	
1.5	REAR END PANEL GARNISH	1	CRACKED	\$90.00	\$90.00	
1.6	REAR BUMPER REINFORCEMENT	1	BENT	\$66.00	\$66.00	
1.7	LH OUTER TAIL LAMP	1	CRACKED	\$162.00	\$162.00	
1.8	RH OUTER TAIL LAMP	1	CRACKED	\$162.00	\$162.00	
1.9	BOOT LID COVER	1	BENT	\$324.00	\$324.00	
1.10	BOOT LID COVER TRIM	1	NOT NECESSARY	\$96.00	\$0.00	
1.11	CAR BOOT INNER LOCK	1	BENT	\$60.00	\$60.00	
1.12	LH BOOT LAMP	1	CUT	\$72.00	\$72.00	
1.13	CAR BOOT RUBBER SEAL	1	TORN	\$72.00	\$72.00	
1.14	CAR BOOT INSULATOR	1	CRACKED	\$240.00	\$240.00	
1.15	FRONT BUMPER	1	DEFORMED	\$234.00	\$234.00	
1.16	BOTH SIDE FRONT BUMPER RETAINERS (LEFT & RIGHT)	2	NECESSARY	\$30.00	\$60.00	
1.17	FRONT BUMPER LOWER GRILLE	1	MISSING	\$48.00	\$48.00	
1.18	FRONT NUMBER PLATE	1	MISSING	\$50.00	\$50.00	
1.19	CENTER ENGINE UNDER COVER	1	MISSING	\$72.00	\$72.00	
1.20	BONNET STAND	1	MISSING	\$30.00	\$30.00	
1.21	BONNET STAND STOPPER	1	DEFORMED	\$5.00	\$5.00	
1.22	BONNET STAND HOLDER	1	MISSING	\$15.00	\$15.00	
1.23	FRONT SUPPORT PANEL	1	BENT	\$264.00	\$264.00	
1.24	FRONT BUMPER REINFORCEMENT	1	BENT	\$138.00	\$138.00	
1.25	FRONT RH DOOR FRAME RUBBER SEAL	1	NOT NECESSARY	\$84.00	\$0.00	
1.26	FRONT RH DOOR SCUFF	1	NOT NECESSARY	\$84.00	\$0.00	

1.27	FRONT RH DOOR STEP COVER	1	NOT NECESSARY	\$84.00	\$0.00	
1.28	REAR RH DOOR STEP COVER	1	NOT NECESSARY	\$84.00	\$0.00	
1.29	FRONT LH DOOR FRAME RUBBER SEAL	1	NOT NECESSARY	\$84.00	\$0.00	
1.30	FRONT LH DOOR SCUFF	1	NOT NECESSARY	\$84.00	\$0.00	
1.31	REAR LH DOOR STEP COVER	1	NOT NECESSARY	\$84.00	\$0.00	
1.32	RHS SAFETY BELT COVER	1	NOT NECESSARY	\$180.00	\$0.00	
1.33	LHS SAFETY BELT COVER	1	NOT NECESSARY	\$180.00	\$0.00	
1.34	RADIATOR	1	BENT	\$456.00	\$456.00	
1.35	RADIATOR UPPER HOSE	1	TWISTED	\$24.00	\$24.00	
1.36	RADIATOR LOWER HOSE	1	TWISTED	\$26.00	\$26.00	
1.37	RADIATOR OVERFLOW HOSE	1	DEFORMED	\$26.00	\$26.00	
1.38	AIR-CON CONDENSER	1	BENT	\$360.00	\$360.00	
1.39	AIR-CON CONDENSER PIPING	1	BENT	\$192.00	\$192.00	
1.40	AIR-CON DISCHARGE HOSE	1	BENT	\$84.00	\$84.00	
2	SCOPE OF REPAIRS					
1.1	REAR BUMPER:					5
	Remove & replace rear bumper					
	Remove & replace both side rear bumper retainers (left & right)					
	Remove & replace reverse sensor					
	Wiring for reverse sensor					
	Putty & spray paint for rear complete bumper (2 colour)					
1.2	REAR END PANEL & REAR BUMPER REINFORCEMENT:					8
	Remove & replace rear end panel					
	Remove & replace rear end panel garnish					
	Remove & replace rear bumper reinforcement					
1.3	OUTER TAIL LAMPS:					1.5
	Remove & replace LH outer tail lamp					
	Remove & replace RH outer tail lamp					
	Wiring for both LH & RH outer tail lamp					
1.4	BOOT LID COVER & LH BOOT LAMP:					10
	Remove & replace boot lid cover					
	Remove & replace boot lid cover trim					
	Remove & replace car boot inner lock					

	Remove & replace LH boot lamp					
	Remove & replace car boot rubber seal					
	Replace boot lid insulator					
	Wiring for LH boot lamp					
	Putty & spray paint for boot lid cover (3 colour)					
1.5	FRONT BUMPER:					5
	Remove & replace front bumper					
	Remove & replace both side front bumper retainers (left & right)					
	Putty & spray paint for front complete bumper (2 colour)					
1.6	LOWER GRILLE, FRONT NUMBER PLATE & ENGINE UNDER COVER:					1
	Remove & replace front number plate					
	Replace front bumper lower grill					
	Replace center engine under cover					
1.7	BOONET STAND:					0.5
	Replace bonnet stand					
	Replace bonnet stand holder					
	Replace bonnet stand stopper					
1.8	FRONT SUPPORT PANEL & FRONT BUMPER REINFORCEMENT:					6
	Remove & replace front support panel					
	Remove & replace front bumper reinforcement					
1.9	RHS DOOR COVERS & RUBBER SEAL:					0
	Remove & replace front RH door frame rubber seal					
	Replace front RH door scuff					
	Replace front RH door step cover					
	Replace rear RH door step cover					
	Replace RHS safety belt cover					
1.10	LHS DOOR COVERS & RUBBER SEAL:					0
	Remove & replace front LH door frame rubber seal					
	Replace front LH door scuff					
	Replace rear RH door step cover					
	Replace RHS safety belt cover					
1.11	RADIATOR:					6
	Remove & replace radiator					

	Remove & replace radiator upper hose					
	Remove & replace radiator lower hose					
	Top up coolant for radiator					
1.12	AIR-CON CONDENSER:					8
	Remove & replace air-con condenser					
	Remove & replace air-con condenser piping					
	Top up air-cond gas					
1.13	BONNET COVER:					2
	Remove & replace "POLICE" wordings stickers (to be provided by AEMD)					
	Putty & spray paint for bonnet cover					
1.14	REAR LH PANEL:					4
	Panel beating for rear LH panel:					
	Putty & spray paint on rear LH panel (3 colours)					
COSTING		TOTAL PARTS COST			\$4,098.00	
		TOTAL MAN-HOUR				57

Registration No. QX 226M

Vehicle Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.