



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2004307
INV Date 04/06/2020
Reference CC4/LPC18015208/Gea3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SGK 5064S
Insured Veh. SJP 9576T
Claim No. 18/18/18/VP05/020840
Policy No. Z18VP05017783
Accident Date 15/08/2018
Inspection Date 23/08/2018

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18015208/Gea3q2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 04-06-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 9576T	Veh. Inspected	SGK 5064S
Policy No.	Z18VP05017783	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020840	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	21/08/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PICNIC	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JTEGH23B500022247	Colour	SILVER
Odometer	300347	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/08/2018	Inspection Date	23/08/2018
Survey held at	ALLSWELL MOTOR TRADERS 100 JALAN SULTAN #02-41 SULTAN PLAZA SINGAPORE 199001		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 5064S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LH REAR FENDER (SN)	TO REPAIR SEE LABOUR	591.00	-
1	REAR BUMPER (SN)	TO REPAIR SEE LABOUR	980.00	-
2	CLIPS FOR BUMPER @\$11.00 (SN)	NOT NECESSARY	22.00	-
			1,593.00	-
LABOUR				
	PANEL KNOCKING ON LH REAR FENDER.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		260.00	200.00
	REPAIR LH REAR BUMPER.		160.00	100.00
	SPRAY PAINTING ON AFFECTED AREA.		460.00	200.00
			880.00	500.00
GRAND TOTAL			2,473.00	500.00
RECOMMENDED COST OF REPAIRS				500.00

Report Ref No. CC4/LPC18015208/Gea3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGK 5064S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

