

# Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com

(3rd party claim against *Lampac*)

## Estimate repair

Vehicle No. : SGK5064S  
 Make & Model : Toyota Picnic  
 Chassis No. : \_\_\_\_\_  
 Date of survey : \_\_\_\_\_

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Submitted by Repairer: *SM*  
 Signature: \_\_\_\_\_  
 COE expiry: 31-05-2026  
 Date: \_\_\_\_\_  
 Engine No.: \_\_\_\_\_

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01.	LH Rear fender	01	\$591.00		to repair
02	Rear bumper	01	\$980.00		to repair
	<i>Special note.</i>				
01	Clips for bumper @ \$11.00 x 2	01	\$22.00		
	<u>Labour description</u>				
01	Panel knocking on LH rear fender	01	\$260.00	200	
02	Putty / grind / LH rear bumper	01	\$160.00	100	
03.	Spray painting on affected area	01	\$460.00	200	
				<del>400</del>	
				Total	\$1400
					See
	3 Days .				
	Part by part				
	After repair photos .				
	Gene Ong .				
	23/8/18 .				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.