

DING AUTOMOTIVE PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C

#01-20
Singapore 575645
Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

17/08/2018 10:52

JOB-NO: 50110872

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHB2102X
MAKE / MODEL: HYUNDAI / i40
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP

TRANS: AUTO
SA: Ding Auto User 1

CHASSIS: KMHLB41UMGU074907
ENGINE: D4FDEU441005

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	300
2 RUST PROOFING	1.00	80.00	0.00	80.00		Y	20
3 SUNDRIES	1.00	50.00	0.00	50.00		Y	30
4 R&R SPARE TYRE BOARD/ CARPET/ TRIM	1.00	120.00	0.00	120.00		Y	50
5 R&R REAR EXHAUST PIPE & MUFFLER	1.00	100.00	0.00	100.00		Y	X
6 R&R REVERSE SENSOR	1.00	60.00	0.00	60.00		Y	30
7 RESPRAY REVERSE SENSOR	1.00	60.00	0.00	60.00		Y	20
8 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
9 RESPRAY REAR BUMPER DIFFUSER	1.00	180.00	0.00	180.00		Y	100
10 RESPRAY SPARE TYRE PANEL	1.00	250.00	0.00	250.00		Y	X
11 RESPRAY REAR FENDER LH	1.00	250.00	0.00	250.00		Y	X
12 TO RESETTING AND RECODING TAIL LAMP (LED) & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	150.00	0.00	150.00		Y	80
13 RESPRAY REAR END PANEL INNER & OUTER	1.00	350.00	0.00	350.00		Y	
TOTAL:		2,900.00	0.00	2,900.00			
<u>MATERIALS</u>							
1 REAR BUMPER	1.00	599.68	0.00	599.68	L	Y	de ✓
2 REAR BUMPER DIFFUSER	1.00	228.40	0.00	228.40	L	Y	de ✓
3 REAR BUMPER RETAINER LH	1.00	42.63	0.00	42.63	L	Y	re ✓
4 REAR BUMPER RETAINER RH	1.00	42.63	0.00	42.63	L	Y	re ✓
5 REAR BUMPER REFLECTOR RH	1.00	43.85	0.00	43.85	L	Y	X
6 TAIL LAMP LH	1.00	697.80	0.00	697.80	L	Y	X
7 TAIL LAMP RH <i>Not consistent</i>	1.00	697.80	0.00	697.80	L	Y	X
8 REAR END PANEL TOP GANISH	1.00	215.45	0.00	215.45	L	Y	X
9 BOOTLID RUBBER BEADING	1.00	89.56	0.00	89.56	L	Y	cut ✓
10 BOOTLID LOCK CATCH	1.00	38.46	0.00	38.46	L	Y	X
11 BOOTLID LOCK	1.00	228.80	0.00	228.80	L	Y	X
12 REAR BUMPER REINFORCEMENT	1.00	484.40	0.00	484.40	L	Y	7 de ✓
13 REAR BUMPER REINFORCEMENT SPONGE	1.00	89.62	0.00	89.62	L	Y	7
14 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	98.63	0.00	98.63	L	Y	7
15 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	98.63	0.00	98.63	L	Y	bt ✓
16 REAR EXHAUST PIPE & MUFFLER RH	1.00	967.22	0.00	967.22	L	Y	X

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
17 REAR EXHAUST PIPE & MUFFLER GASKET RH	1.00	42.88	0.00	42.88	L	Y	X
18 REAR END PANEL OUTER	1.00	629.95	0.00	629.95	L	Y	Ry
19 REAR END PANEL INNER	1.00	456.22	0.00	456.22	L	Y	X
20 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	al
21 REAR BUMPER RUBBER PROTECTOR PAD	1.00	150.00	0.00	150.00	S	Y	al
22 REAR BUMPER REVERSE SENSOR SET	1.00	230.00	0.00	230.00	S	Y	200 ✓ one
23 REAR END PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	X
24 REPAIR REAR FENDER LH	1.00	0.00	0.00	0.00	S	Y	X
25 REPAIR SPARE TYRE PANEL	1.00	0.00	0.00	0.00	S	Y	X
TOTAL:		6,257.61	0.00	6,257.61			

TOTAL PARTS & LABOUR :

9,157.61 0.00 9,157.61

EXCESS/LOADING:S\$ 0.00

No. Of Day: 3

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: 17 / 8 / 15

SURVEYED BY: Tanpin

CONTACT NO: 97445244

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: