

22/03/2002

ASS. REC. BY:

REF:

CS3/LCR18015220/N24d302

Official Instruction:

Survivor:
member

Naz

ASSIGNMENT (Office)

From (Person): chin lee ying

of

LCR

Date/Time:

21/8/18 @ 11:37am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY1914G

Insured:

SLL 353B

at Workshop m/s

Lian Hong Painter

Tel:

6453 5779

of

160 Sin Ming Drive #06-10

Policy No:

0999994805

Claim No:

163617549386

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/08/2018

CA / REV / REP. / REV 24 HRS Cup?

H.O.D. Endorsement:

Date/Time:

12:10pm @ 21/8/18

Person Contacted:

Ms. Nomy

Vehicle

IN OUT

Date/Time	Action/Instruction (X) Estimate
	SJY1914G-X
	SLL 353B
	Dismantle: 23/8/2018
	After repair: 29/8/2018

REF:

Surveyor: NAL

REF:

ALG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJY 19146

Yr Regn: 10 AY 4 201

Type M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: AUDI A4 1.8 TFSI MU C.C 1.7 98

Colour BLACK

A/C: Insured / Std / NI / NA

Sp. Reading 167, 414

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAHZZZ8K1AA080943

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

mm

R/Bal. 5 mm

mm

L/Bal. 5 mm

mm

L/Bal. 5 mm

mm

D.O.A. 18/8/18

D.O.I. 21/8/18

Survey held at LIAN HENG

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/10/18

Submit DAR report

Repair days 4/5

RECEIVED 6 OCT 2018

TCU

4/10/18

Date/Time, File Pass to?



: Preli. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: 2

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)



: Others (\$ _____)

Report Format : DAR

Lump Sum / I.B.I: (\$ _____)

TOTAL

200

180

20

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 21/8/2018 11:37:54 AM
Attachments:  tmp63F3.tif

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

Nedumaran Muthukrishnan
LL.B (Hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

Please reply to our Branch Office for this matter

Branch Office: 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneducoco.com.sg
scence.lan@mneducoco.com.sg

Our Reference : MN/IG/L1/1812596/st
Your Reference : SLL 353B

20 August 2018

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way, #07-16
Singapore 079120

BY FAX 6835-7416 ONLY


Dear Sirs,

1. NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)
2. ACCIDENT ON 18/08/2018 INVOLVING VEHICLE NOS. SJY 1914G AND SLL 353B ALONG HILLVIEW ROAD TOWARDS UPPER BUKIT TIMAH ROAD.

We are instructed by ANTONIO FRANCBSCO MANETTO (owner of motor vehicle no. SJT 1914G) and/or LIAN HENG PAINTER COMPANY (the motor workshop for SJT 1914G) to notify you of a road traffic accident on 18/8/2018 at about 1130 hours along HILLVIEW ROAD TOWARDS UPPER BUKIT TIMAH ROAD involving our client's vehicle registration number [SJY 1914G] and [SLL 353B] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know **within 2 working days** of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


NEDUMARAN MUTHUKRISHNAN
(Branch Office)
c.c. 1) LCRF PTE LTD

2) Lian Heng Painter Company
160 Sin Ming Drive
#06-10 Sin Ming AutoCity
Singapore 575722
Tel : 6453-5779 / 9863-2371 (Ms Nomy / Mr Henry)

(Vehicle : SLL 353B)

(Vehicle : SJY 1914G)

Fax : 6453-3173



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/LCR18015220/Nz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 21-08-2018



Code : LCR

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLL 353B	Veh. Inspected	SJY 1914G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	21/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/08/2018	Inspection Date	21/08/2018
Survey held at	160 SIN MING DRIVE # 06-10		
Repairer	LIAN HENG PAINTER CO.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 12:03
Date Of Accident	18/08/2018 11:30
Exact Location Of Accident	HILLVIEW ROAD TOWARDS UPPER BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY1914G
Insured/Policyholder	
Name Of Registered Owner	ANTONIO FRANCESCO MANETTO
NRIC No	S7464836C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91262411
Alternative Phone No	OTHERS-91262411

Vehicle Particulars

Manufacturer	AUDI
Model	A4
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100376347-04
Cover Note Number	

Driver

Name of Driver	ANTONIO FRANCESCO MANETTO
NRIC No	S7464836C
Date Of Birth	04/10/1974
Occupation	INDOOR
Date Of Driving Pass	31/05/2010
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91262411
Fax Number	
Contact Number	OTHERS-91262411
EMail Address	NOEMAIL

167 414
Michelle

225/50 R17

5mm

WAUZZZ8K1A10
80943

Address	8 RIDGEWOOD CLOSE #18-09
Postcode	276698
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL353B
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANTHONY
NRIC/Passport Number	S1164309D
Contact Number	9098990
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 20 AUG 2018

12:03hrs

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: Poh Kwee Choo
S6840583A

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date : 18/08/18.

Time : ~~11:30am~~ 11:30am

I stopped my car before turning from Hillview Rd into Bukit Timah Rd and was hit by vehicle SLL 3533 B from the rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 20 AUG 2018

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: Poh Kwee Choo
 NRIC/FIN No.: S6840583A

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket	RA	BR	✓ 1
1148	993068	Rear Bumper Side Retainer	RH	DL	✓ 1
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam	RH	BT	✓ 1
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	OUT	✓	2
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish	BT	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	BR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding / Trim	TN	✓	
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH	BR	✓	
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SJY 1914 G

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		RH Rear fender Ventilation	BR	✓	

No of Items: 12

Assessor: _____

TGim Jim

4/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Aug 2018 Edit Reg		21 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	-								
Vehicle Reg. No.:	SJY1914G	Date of Loss:	18/08/2018 00:00 - :59 [96 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1636175493SG	Policy/Cover Note No.:	0999994805 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLL353B	Policy No. (Claimant):							
		Excess:							
Repairer:	Lian Heng Painter Company () 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY, 575722 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 31/08/2018]								
Claimant's Solicitor:	M NEDUMARAN & CO - Tel: 65098480								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> AIG_SG (23/08/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




































Claim Documents











***SJY1914G (1636175493SG)**
[SLL353B]

TP

-

Aug 18 2018 12:00AM
[LCRF PTE LTD]
Lian Heng Painter Company

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
2	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
3	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
4	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
5	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
6	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
7	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
8	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
9	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
10	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
11	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
12	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
13	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
14	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
15	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
16	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
17	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
18	23/08/18 11:54	General View														Load JPG	<input checked="" type="checkbox"/>	
19	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
20	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
21	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
22	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
23	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
24	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
25	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
26	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
27	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
28	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
29	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
30	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
31	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
32	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
33	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
34	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
35	28/08/18 17:50	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
36	03/10/18 15:48	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>	
37	03/10/18 15:48	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/10/18 15:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	03/10/18 15:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	03/10/18 15:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	03/10/18 15:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	03/10/18 15:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	03/10/18 15:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	03/10/18 15:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	03/10/18 15:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	03/10/18 15:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	23/08/18 14:20	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/LCR18015220/NZ4D3E2

Date: 05/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994805

Claimant Vehicle No : SJY1914G

Insured Vehicle No : SLL353B

Date of Loss: 18/08/2018

Nature of Claim:

TP

Claim No: 1636175493SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY1914G**

Make & Model: AUDI A4, 1.8 TFSI MU CVT (A)

Engine No: CDH075301

Reg. Date: 10/08/2010 (Man. Year: 2009)

Chassis No: WAUZZZ8K1AA080943

Colour: Black

Odometer: 167414 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size:

225/50 R17

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/08/2018

Date Inspected: 21/08/2018 Inspected At:

Lian Heng Painter Company
160 SIN MING DRIVE, #06-10 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER BRACKET RH	Broken	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER RH	Dislodged	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*REAR BUMPER BEAM RH	Bent	0.00 F	*- F
7	2		*REVERSE SENSOR	Cut	0.00 F	*- F
8	1		*REAR END PANEL	Repair	0.00 F	*- F
9	1		*REAR END PANEL TOP GARNISH	Bent	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Broken	0.00 F	*- F
11	1		*BOOTLID MOULDING / TRIM	Torn	0.00 F	*- F
12	1		*BOOTLID LAMP RH	Broken	0.00 F	*- F
13	1		*RH REAR FENDER VENTILATION	Broken	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >