

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Aug-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6770 K

1 pc	n/s head lamp @ \$1028.00	X	\$	1,028.00
	<i>Front bumper repair</i>		\$	1,028.00
		Less 10%	\$	102.80
			\$	925.20
	To adjust and focus front n/s head lamp		\$	40.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, etc.		\$	450.00 X
	To putty and spray painting on front bumper		\$	200.00 180
			\$	1,615.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*Kalvi (1014)
21/8/18 1030h.
2 Pgs
4s
After Repair Ltd*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: