

(08/11/13) wef
ASS. REC. BY: *P. J. M.*

REF: *HPC*

58523

ASSIGNMENT

From: _____ Date: *21/08/2018*

Estimated Cost: _____

ON / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *8JV 8548A*
at Workshop m/s *Goldbell Pandan*
of *Blk K Pandan Loop, Ind. Est #01-12*

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____


(Client's Record)

Make of Veh: _____

Morning
Andy @ 8816 2798

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: *22K*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *12* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *(wp)*

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *STV 8548A* Yr Regn: *2010 / FEB*

Type: *M. Car* / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *MAZDA 3 1-6A* C.C. *1598*

Colour: *RED* A/C: Insured / Std / NI / NA

Sp. Reading: *145411* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JM 6BL 102140128 269*

Gen. Cond: Good / *Fair* / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *205/60R16*
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / *YOKO* or

Front

Rear

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. *17/08/18* D.O.I. *21/08/18*

Survey held at *Green Hill*

Des. of Damages: *FR / Rear* / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/08/18 Email to Andy inform the repair (not is 7k. He agreed and confirm)

1/5: +7,000 (RED: +10,093.60 59%)

IN V: +22,000

LTP: +14,248

Net: +7,752

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 636894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 1 / 4

ESTIMATE

Date	: 20/08/2018	Reg No	: SJV8548A
To	: LONPAC INSURANCE BHD.	Model	: 3 1.6L SDN
Attn.	:	Chassis No	: JM6BL10Z1A0128269
Office / Mobile	:	Engine No	: Z6831645
Email Address	:	Quotation No.	: 69008
		Ref. No.	: GBE/SVC/SALES
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 17/08/2018
Attn.	: ANDYOOILK	Policy No.	: 5098052393
Office / Mobile	: +65 67730073	Claim Type	: THIRD PARTY CLAIM
Email / Fax No.	: AndyOoiLK@goldbell.com.sg	Workshop	: PANDAN

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		BOOT LID	1	1,162.00	-20	929.60	929.60
2		BOOT LID LOGO	1	71.00	-20	56.80	56.80
3		BOOT LID DAMPER LH	1	78.00	-20	62.40	62.40
4		BOOT LID DAMPER RH	1	78.00	-20	62.40	62.40
5		BOOT LID INNER LOCK	1	178.00	-20	142.40	142.40
6		BOOT LID INNER LOCK CABLE	1	30.00	-20	24.00	24.00
7		BOOT LID INNER TRIM COVER	1	152.00	-20	121.60	121.60
8		BOOT LID REFLECTOR LH	1	321.00	-20	256.80	256.80
9		BOOT LID REFLECTOR RH	1	321.00	-20	256.80	256.80
10		BOOT LID MAZDA 3 EMBLEM	1	63.00	-20	50.40	50.40
11		BOOT LID THIRD BRAKE LIGHT	1	490.00	-20	392.00	392.00
12		BOOT LID RUBBER BEADING	1	141.00	-20	112.80	112.80
13		REAR BUMPER	1	1,050.00	-20	840.00	840.00
14		REAR BUMPER SIDE REFLECTOR LH	1	60.00	-20	48.00	48.00
15		REAR BUMPER SIDE REFLECTOR RH	1	60.00	-20	48.00	48.00
16		REAR BUMPER REINFORCEMENT	1	530.00	-20	424.00	424.00
17		REAR BUMPER BRACKET LH	1	14.00	-20	11.20	11.20
18		REAR BUMPER BRACKET RH	1	14.00	-20	11.20	11.20
19		REAR NUMBER PLATE LAMP LH & RH	1	156.00	-20	124.80	124.80
20		REAR BUMPER SIDE RETAINER LH	1	37.00	-20	29.60	29.60
21		TAILLAMP LH	1	1,119.00	-20	895.20	895.20
22		TAILLAMP RH	1	1,119.00	-20	895.20	895.20
23		TAILLAMP INNER PANEL LH	1	76.00	-20	60.80	60.80
24		REAR END PANEL	1	410.00	-20	328.00	328.00
25		REAR END PANEL TOP GARNISH	1	194.00	-20	155.20	155.20
26		SPARE TYRE PANEL	1	1,019.00	-20	815.20	815.20
27		SPARE TYRE BOARD	1	489.00	-20	391.20	391.20
28		REAR FENDER LH	1	1,075.00	-20	860.00	860.00
29		REAR FENDER INNER TRIM COVER LH	1	194.00	-20	155.20	155.20
30		REAR FENDER INNER SHIELD LH	1	47.00	-20	37.60	37.60
31		REAR FENDER LOWER AIR VENT LH	1	72.00	-20	57.60	57.60
32		REAR WHEELHOUSE PANEL LH	1	893.00	-20	714.40	714.40
33		REAR WINDSCREEN GLASS MOULDING	1	108.00	-20	86.40	86.40
34		REAR EXHAUST BOX	1	1,026.00	-20	820.80	820.80



ST R

Certificate No: AJA/591/21/243

Certificate No: AJA/21/243



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 2 / 4

ESTIMATE

Date	: 20/08/2018	Reg No	: SJV8548A
To	: LONPAC INSURANCE BHD.	Model	: 3 1.6L SDN
Attn.	:	Chassis No	: JM6BL10Z1A0128269
Office / Mobile	:	Engine No	: Z6831645
Email Address	:	Quotation No.	: 69008
		Ref. No.	: GBE/SVC/SALES
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 17/08/2018
Attn.	: ANDYOOILK	Policy No.	: 5098052393
Office / Mobile	: +65 67730073	Claim Type	: THIRD PARTY CLAIM
Email / Fax No.	: AndyOoiLK@goldbell.com.sg	Workshop	: PANDAN

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
35		REAR EXHAUST BOX RUBBER MOUNTING	2	17.00	-20	13.60	27.20 <i>XNN</i>
36		BOOT LID HINGE LH	1	123.00	-20	98.40	98.40 <i>3NN</i>
37		BOOT LID HINGE RH	1	123.00	-20	98.40	98.40 <i>8NN</i>
38		FRONT BUMPER	1	1,027.00	-20	821.60	821.60 <i>DE</i>
39		FRONT BUMPER REINFORCEMENT	1	442.00	-20	353.60	353.60 <i>3NN</i>
40		FRONT BUMPER LOGO	1	45.00	-20	36.00	36.00 <i>NA</i>
41		FRONT BUMPER TOWING COVER LH	1	28.00	-20	22.40	22.40 <i>MS</i>
42		FRONT BUMPER CENTRE GRILLE	1	228.00	-20	182.40	182.40 <i>DE</i>
43		FRONT BUMPER SIDE GRILLE LH	1	45.00	-20	36.00	36.00 <i>SC</i>

PARTS TOTAL : 11,953.60

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE WITH GARNISH	1	35	60.00 <i>CR</i>
2	REAR NUMBER PLATE WITH GARNISH	1	35	60.00 <i>MS</i>
3	REAR BUMPER REVERSE SENSOR	1	220	280.00 <i>MS</i>
4	REAR WINDSCREEN GLASS SEALANT	1		50.00 <i>MS</i>
5	REAR SPARE TYRE	1		280.00 <i>XNN</i>

PARTS TOTAL: 730.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during repair
- Parts prices are subject to confirm
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



STAR

Certificate No. AIA/2010/1243

Certificate No. AIA/2010/1243



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co Reg No. 108003963G

Page 3 / 4

ESTIMATE

Date :	20/08/2018	Reg No :	SJV8548A
To :	LONPAC INSURANCE BHD.	Model :	3 1.6L SDN
Attn. :		Chassis No :	JM6BL10Z1A0128269
Office / Mobile :		Engine No :	Z6831645
Email Address :		Quotation No. :	69008
		Ref. No. :	GBE/SVC/SALES
From :	GOLDBELL ENGINEERING PTE LTD	D.O.A. :	17/08/2018
Attn. :	ANDYOOILK	Policy No. :	5098052393
Office / Mobile :	+65 67730073	Claim Type :	THIRD PARTY CLAIM
Email / Fax No. :	AndyOoiLK@goldbell.com.sg	Workshop :	PANDAN

LABOUR CHARGES

1	TO REMOVE AND REPLACE DAMAGED PARTS ,CUT ,WELD , PANEL BEAT AND STRAIGHTEN AND REALIGH , ETC	2000.00 1500
2	TO PUTTY ,CLEANE ,SPRAY PAINT AND POLISH , ETC , TO RESPRAY REAR BUMPER , REAR END PANEL , SPARE TYRE PANEL , REAR FENDER LH , REAR FENDER RH , BOOT LID , FRONT BUMER ,BONNET	1600.00 1300
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS TO ASSIST REPAIR	120.00
4	TOWING CHARGES	180.00 70
5	RUST PROOFING	100.00 80
6	TO REMOVE AND REPLACE REAR EXHAUST BOX AND PIPE	180.00 80
7	TO REMOVE AND REFIT REAR SPARE TYRE BOARD AND SPARE TYRE	150.00 80
8	TO CHECK AND REPAIR WIRING SYSTEM	80.00 30

LABOUR TOTAL :	4,410.00
SUB-TOTAL :	17,093.60
GST @ 7% for \$ 17,093.60	1,196.55
GRAND TOTAL (\$\$) :	18,290.15



Certificate No. AIA/EB/101243

Certificate No. AIA/EB/101243



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 4 / 4

ESTIMATE

Date	: 20/08/2018	Reg No	: SJV8548A
To	: LONPAC INSURANCE BHD.	Model	: 3 1.6L SDN
Attn.	:	Chassis No	: JM6BL10Z1A0128269
Office / Mobile	:	Engine No	: Z6831645
Email Address	:	Quotation No.	: 69008
		Ref. No.	: GBE/SVC/SALES
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 17/08/2018
Attn.	: ANDYOOILK	Policy No.	: 5098052393
Office / Mobile	: +65 67730073	Claim Type	: THIRD PARTY CLAIM
Email / Fax No.	: AndyOoiLK@goldbell.com.sg	Workshop	: PANDAN

PREPARED BY : ANDYOOILK

DATE / TIME : 21/08/18 @ 1145

SURVEYOR : PASUL

MOBILE NO : 90010066

OFFICE FAX NO : _____

EMAIL ADDRESS : _____

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 12 days

REMARKS : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/18/18/VP05/020843
Our ref: CC4/LPC18015228/R1ea3

Date: 24.08.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJV 8548A


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.08.2018 at the premises of M/s Goldbell Engineering Pte Ltd have the following to report:-

Workshop Estimate Amount	: S\$	17,093.60	
Revised Estimate Amount	: S\$	11,301.60	
"Check" Items Amount	: S\$	1,755.20	
Total (Including Check Items)	: S\$	13,056.80	
Market Value	: S\$	22,000.00	(est.)
LTA Reimbursement Value	: S\$	14,248.00	(est.)
Nett Value	: S\$	7,752.00	(est.)

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 12.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 20 August, 2018 3:25 PM
To: admin-d@lkkauto.com
Cc: MT_Claim_SG; andyooilk@goldbell.com.sg
Subject: FW: PLEASE ARRANGE FOR SURVEY - ACCIDENT DATE 18/07/2018 - SJV8548A (NTUC INCOME INSURANCE) TP CLAIM AGAINST SJJF5244E (LONPAC INSURANCE BHD)
Attachments: SJV8548A-ESTIMATE.pdf

Our Ref : 18/18/18/VP05/020843

Dear Nivitha,

Kindly proceed to conduct the survey as indicated below.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

20082018 @ 4:20pm
Andy veh in

21082018 @ morning

From: Andy Ooi Lee Keong [mailto:AndyOoiLK@goldbell.com.sg]
Sent: Monday, 20 August, 2018 2:45 PM
To: MT_Claim_SG
Cc: Ramesh; Derek Chow Zhi Da
Subject: PLEASE ARRANGE FOR SURVEY - ACCIDENT DATE 18/07/2018 - SJV8548A (NTUC INCOME INSURANCE) TP CLAIM AGAINST SJJF5244E (LONPAC INSURANCE BHD)

Hi Motor claims ,

Please help me to arrange survey , Third party claim against SJF5244E – LONPAC INSURANCE BHD

Attached above our GIA Report & Workshop Estimate .

Remark : Vehicle in , LOCATION ADDRESS AT GOLDBELL PANDAN BLOCK K PANDAN LOOP IND ESTATE #01-12

SINGAPORE 128230 , PLEASE CONTACT ANDY -97396452

Thank & regards

 Andy Ooi Lee Keong | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims
DID: +65 6458 9596 | Tel: +65 6773 0073 | Fax: +65 6458 7172 |
Mobile: +65 8816 2798 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Pandan)
Blk K, Pandan Loop Ind. Estate, #01-12 Singapore 128230



Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 29 August, 2018 12:05 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: PLEASE ARRANGE FOR SURVEY - ACCIDENT DATE 18/07/2018 - SJV8548A (NTUC INCOME INSURANCE) TP CLAIM AGAINST SJJF5244E (LONPAC INSURANCE BHD)
Attachments: 29082018120235.pdf
Categories: HMK

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 29 August, 2018 11:41 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAUTO); Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO)
Subject: RE: PLEASE ARRANGE FOR SURVEY - ACCIDENT DATE 18/07/2018 - SJV8548A (NTUC INCOME INSURANCE) TP CLAIM AGAINST SJJF5244E (LONPAC INSURANCE BHD)

WITHOUT PREJUDICE

LPC ref: 18/18/18/VP05/020843
LKK REF: CC4/LPC18015228/R1ea3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SJV 8548A

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Hi Motor claims ,

Please help me to arrange survey , Third party claim against SJF5244E – LONPAC INSURANCE BHD

Attached above our GIA Report & Workshop Estimate .

Remark : Vehicle in , LOCATION ADDRESS AT GOLDBELL PANDAN BLOCK K PANDAN LOOP IND ESTATE #01-12

SINGAPORE 128230 , PLEASE CONTACT ANDY -97396452

Thank & regards



Andy Ooi Lee Keong | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6458 9596 | Tel: +65 6773 0073 | Fax: +65 6458 7172 |
Mobile: +65 8816 2798 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Pandan)
Blk K, Pandan Loop Ind. Estate, #01-12 Singapore 128230



Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 7 September 2018 9:08 AM
To: Andy Ooi Lee Keong
Cc: Ramesh; Derek Chow Zhi Da
Subject: RE: PLEASE ARRANGE FOR SURVEY - ACCIDENT DATE 18/07/2018 - SJV8548A (NTUC INCOME INSURANCE) TP CLAIM AGAINST SJJF5244E (LONPAC INSURANCE BHD)

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]
Sent: Monday, 20 August, 2018 3:25 PM
To: admin-d@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>; andyooilk@goldbell.com.sg
Subject: FW: PLEASE ARRANGE FOR SURVEY - ACCIDENT DATE 18/07/2018 - SJV8548A (NTUC INCOME INSURANCE) TP CLAIM AGAINST SJJF5244E (LONPAC INSURANCE BHD)

Our Ref : 18/18/18/VP05/020843

Dear Nivitha,



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18015228/R1ea3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 28-01-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 5244E	Veh. Inspected	SJV 8548A
Policy No.	Z18VP05018705	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020843	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	20/08/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 1.6 (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JM6BL10Z1A0128269	Colour	RED
Odometer	145411	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/08/2018	Inspection Date	21/08/2018
Survey held at	BLOCK K PANDAN LOOP IND ESTATE #01-12		
Repairer	GOLDBELL ENGINEERING PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **12 Working Days**

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 8548A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	BUCKLED	1,162.00	1,162.00
1	BOOT LID LOGO	NECESSARY	71.00	71.00
1	BOOT LID DAMPER LH	NOT NECESSARY	78.00	-
1	BOOT LID DAMPER RH	NOT NECESSARY	78.00	-
1	BOOT LID INNER LOCK	BENT	178.00	178.00
1	BOOT LID INNER LOCK CABLE	NOT NECESSARY	30.00	-
1	BOOT LID INNER TRIM COVER	NOT NECESSARY	152.00	-
1	BOOT LID REFLECTOR LH	CRACKED	321.00	321.00
1	BOOT LID REFLECTOR RH	NOT NECESSARY	321.00	-
1	BOOT LID MAZDA 3 EMBLEM	NECESSARY	63.00	63.00
1	BOOT LID THIRD BRAKE LIGHT	CRACKED	490.00	490.00
1	BOOT LID RUBBER BEADING	NECESSARY	141.00	141.00
1	REAR BUMPER	TORN	1,050.00	1,050.00
1	REAR BUMPER SIDE REFLECTOR LH	CRACKED	60.00	60.00
1	REAR BUMPER SIDE REFLECTOR RH	CRACKED	60.00	60.00
1	REAR BUMPER REINFORCEMENT	BENT	530.00	530.00
1	REAR BUMPER BRACKET LH	NECESSARY	14.00	14.00
1	REAR BUMPER BRACKET RH	NECESSARY	14.00	14.00
1	REAR NUMBER PLATE LAMP LH & RH	MISSING	156.00	156.00
1	REAR BUMPER SIDE RETAINER LH	NECESSARY	37.00	37.00
1	TAILLAMP LH	CRACKED	1,119.00	1,119.00
1	TAILLAMP RH	CRACKED	1,119.00	1,119.00
1	TAILLAMP INNER PANEL LH	BENT	76.00	76.00
1	REAR END PANEL	BUCKLED	410.00	410.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	194.00	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,019.00	-
1	SPARE TYRE BOARD	NOT NECESSARY	489.00	-
1	REAR FENDER LH	BUCKLED	1,075.00	1,075.00
1	REAR FENDER INNER TRIM COVER LH	NOT NECESSARY	194.00	-
1	REAR FENDER INNER SHIELD LH	NOT NECESSARY	47.00	-

Report Ref No. CC4/LPC18015228/R1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER LOWER AIR VENT LH	NOT NECESSARY	72.00	-
1	REAR WHEELHOUSE PANEL LH	TO REPAIR SEE LABOUR	893.00	-
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	108.00	108.00
1	REAR EXHAUST BOX	TO REPAIR SEE LABOUR	1,026.00	-
2	REAR EXHAUST BOX RUBBER MOUNTING @ \$17.00	NOT NECESSARY	34.00	-
1	BOOT LID HINGE LH	NOT NECESSARY	123.00	-
1	BOOT LID HINGE RH	NOT NECESSARY	123.00	-
1	FRONT BUMPER	DEFORMED	1,027.00	1,027.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	442.00	-
1	FRONT BUMPER LOGO	NECESSARY	45.00	45.00
1	FRONT BUMPER TOWING COVER LH	MISSING	28.00	28.00
1	FRONT BUMPER CENTRE GRILLE	DEFORMED	228.00	228.00
1	FRONT BUMPER SIDE GRILLE LH	SCRATCHED	45.00	45.00
	LESS 20% DISCOUNT		-2,988.40	-1,925.40
			11,953.60	7,701.60
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE WITH GARNISH (SN)	CRACKED	60.00	35.00
1	REAR NUMBER PLATE WITH GARNISH (SN)	MISSING	60.00	35.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	280.00	220.00
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR SPARE TYRE (SN)	NOT NECESSARY	280.00	-
			730.00	340.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE DAMAGED PARTS, CUT, WELD, PANEL BEAT AND STRAIGHTEN AND REALIGN, ETC. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL, REAR WHEELHOUSE PANEL LH AND REAR EXHAUST BOX.		2,000.00	1,500.00
	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC. TO RESPRAY REAR BUMPER, REAR END PANEL, SPARE TYRE PANEL, REAR FENDER LH, REAR FENDER RH, BOOT LID, FRONT BUMPER, BONNET.		1,600.00	1,300.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS TO ASSIST REPAIR.		120.00	120.00

Report Ref No. CC4/LPC18015228/R1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING CHARGES.		180.00	70.00
	RUST PROOFING.		100.00	80.00
	TO REMOVE AND REPLACE REAR EXHAUST BOX AND PIPE.		180.00	80.00
	TO REMOVE AND REFIT REAR SPARE TYRE BOARD AND SPARE TYRE.		150.00	80.00
	TO CHECK AND REPAIR WIRING SYSTEM.		80.00	30.00
			4,410.00	3,260.00
GRAND TOTAL			17,093.60	11,301.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,000.00

Report Ref No. CC4/LPC18015228/R1ea3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.