

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9672K**AAD1808-109**

Not Withheld
21 Sep @ 3500

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9672K

CHEVROLET

EPICA 2.0

14.8.2018

AIG**PART****LIST**

1	1	Rear Bumper	\$	<i>Ry</i> 1,202.00	—
2	1	Rear Bumper Beam	\$	<i>Ry</i> 239.94	—
3	1	Rear Bumper Centre Absorber	\$	<i>C M</i> 260.00	—
4	1	Rear Bumper Side Retainer RH	\$	<i>C M</i> 68.76	✓
5	1	Rear Bumper Side Retainer LH	\$	<i>D 1</i> 68.76	✓
6	1	Rear Bumper Reflectors RH	\$	<i>Ru</i> 119.74	✓
7	1	Rear Bumper Reflectors LH	\$	<i>Ru</i> 119.74	✓
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i> 93.00	X
9	1	Rear End Panel Outer	\$	<i>Ry</i> 623.76	✓
10	1	Rear End Panel Inner Trim	\$	<i>Sn</i> 263.84	X
11	1	Rear Luggage Floor Panel	\$	<i>R</i> 973.00	X
12	1	Rear Luggage Floor Panel Insulator	\$	<i>Sn</i> 63.50	X
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sn</i> 378.00	X
14	1	Bootlid	\$	<i>Ry</i> 973.00	✓
15	1	Bootlid inner trim board	\$	<i>Sn</i> 400.00	X
16	1	Bootlid Weatherstrip	\$	<i>Sn</i> 344.28	X
17	1	Bootlid Lock - Top	\$	<i>D 1</i> 466.56	✓
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>Ru</i> 120.62	✓
19	1	Bootlid Logo	\$	<i>Ru</i> 138.84	✓
20	1	Bootlid 'EPICA LT' Badge	\$	<i>Ru</i> 119.84	✓
21	1	Bootlid Reflector Centre	\$	<i>Sn</i> 217.97	X
22	1	Bootlid Reflector RH	\$	<i>Sn</i> 128.40	X
23	1	Bootlid Reflector LH	\$	<i>Sn</i> 128.40	X
24	1	Rear Tail Lamp RH	\$	<i>C M</i> 479.30	✓
25	1	Rear Tail Lamp LH	\$	<i>Sn</i> 479.30	X
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00	X
27	1	Rear Fender RH	\$	<i>R</i> 1,145.00	X
28	1	Rear Fender Inner Trim RH	\$	<i>Sn</i> 418.44	X
29	1	Rear Fender LH	\$	<i>R</i> 1,145.00	X

Trans-cab Auto Services Pte Ltd**AAD1808-093**

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 9672K

30 1 Rear Fender Inner Trim LH \$ *Sn* 418.44 X

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i>	40.00	X
2	1Set	Rear Bumper Parking Sensor	\$	<i>shar</i>	300.00	✓
3	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i>	44.00	✓
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i>	30.00	} X
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i>	30.00	
6	1	Rear Exhaust Mounting	\$	<i>sn</i>	300.00	
7	2	Rear Windscreen Sealant	\$	<i>nn</i>	80.00	
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i>	100.00	
9	1	Spare Tyre	\$	<i>sn</i>	180.00	
10	1	Spare Wheel Rim	\$	<i>sn</i>	126.74	

TOTAL	\$	1,230.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,667.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
 Necessary Portion, Remove And Renewal Of
 Parts, Adjust And Realign The Same

\$ 3,500.00 *8001*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *601*

Putty And Spray Painting Of The Affected
 Portion.

\$ 3,200.00 *10001*

To reinstall rear bumper parking sensor.

\$ 170.00 *601*

To transfer of end panel fittings and conduct
 water seepage test.

\$ 170.00 *601*

Trans-cab Auto Services Pte Ltd

AAD1808-093

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9672K

To transfer of boot fittings and conduct water
seepage test. \$ 170.00 *601*

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair. \$ *na* 380.00 *X*

To check steering geometry and computer
wheel alignment \$ *na* 220.00 *X*

\$ 8,150.00

TOTAL \$ 20,817.43

Repair Days (LUMP SUM)

~~10 Days~~

5 days