

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **20.08.2018**

Accident Date : **14.08.2018**

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Hyundai Sonata" Reg. No. SJT2812L Claiming Against Your Insured Reg. No. SKT1272P		
1pc	Rear Bumper	3.00	616.00 ✓
12pcs	Rear Bumper Clips		36.00 ✓
1pc	Rear Bumper Reinforcement		475.00 X
5pcs	Rear Bumper Reinforcement Brackets (Plastic)	11.00	55.00 X
1pc	Rear Bumper Boot Auto Radar		245.00 X
1pc	Boot Emblem		30.00 —
1pc	Boot Badge "Sonata"		45.30 —
1pc	Boot Badge "V111"		44.90 —
			1,547.20
	Less 20%		309.44
			1,237.76
	To Rebore Rear Bumper Hole, Transfer Reverse Sensors, Wiring, Module Etc		120.00 501
	Labour Charge - Panel Beating, Repairing Of Boot, End Panel and Parts Replacement		480.00 250
	To Respray Affected Areas		600.00 400
	Total :		2,437.76

*Not Authorised  
Respray B&P  
3 days*

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: