

KIM KEAT MOTOR CO
Blk 10 Ang Mo Kio Industrial Park 2A
Avenue 5 #05-34 AMK Autopoint
Singapore 568047

Not with him
U1 Sup @?
Resurvey After Paint
4 days

20 Aug 2018

AXA Insurance Pte Ltd.
 Survey Dept.

Re: Quotation for damaged to FP8522C

Item	Description of Parts	Qty	Amount	
1.	Mirror RH	1pc	38.00	✓
2.	Brake Lever	1pc	15.00	✓
3.	Handle Bar RH	1pc	85.00	✓
4.	Weight RH	1pc	15.00	✓
5.	Meter Assy Comp.	1pc	680.00	x
6.	Stay	1pc	85.00	✓
7.	Top Cowl Assy	1pc	185.00	✓
9.	Front Signal Lamp RH	1pc	38.00	✓
10.	Fork Tube L&R	2pcs	280.00	✓
11.	Fork Seal Set L&R	2set	55.00	✓
12.	Steering Stem	1pc	185.00	✓
13.	Steering Cone Bearing Assy	1set	55.00	✓
14.	Brake Disc Front	1pc	280.00	✓
15.	Fuel Tank	1pc	580.00	✓
16.	Brake Pedal	1pc	55.00	✓
17.	Footrest Assy Front RH	1pc	38.00	✓
18.	Muffler	1pc	685.00	✓
19.	Tail Cowl	1pc	125.00	✓
20.	Tail Lamp Comp.	1Pc	98.00	✓
21.	Mudguard	1pc	135.00	✓
Total			\$ 3712.00	
Less 10%			- 371.20	
Sub-total			\$ 3340.80	

Nett Item				
22.	Number Plate Front	1pc	12.00	✓
23.	Number Platte Rear	1pc	15.00	✓
24.	Fork Oil	1bottle	10.00	✓
25.	To Repspray Top Cowl, Fuel Tank and Tail Cowl		280.00	2401
26.	Transport Fee		30.00	✓
27.	Labour		280.00	1801
Grand Total			\$ 3967.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: