

A&S REC. BY:

REF:

CS/CT18015247/Ggd3

Special Instruction:

Surveyor:

menmen

ASSIGNMENT (Office)

From (Person):

Chong Boun Sen

of

CPI

Date/Time:

21/8/18 @ 2.18pm

Estimated Cost:

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL 5512B

Insured:

GRD 5791X

at Workshop m/s

Abwin Service

Tel:

6713 9400

of

No-8 Kaki Bkt Ave 4# 07-48 premier

Policy No:

DMCVSN3091831702

Claim No:

SNM18D04048C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/08/2018

CA / REV / REP. / REV 24 HRS (up)

23/08/2018

H.O.D. Endorsement:

Date/Time:

1:33pm @ 21/8/18

Person Contacted:

Ivan

Vehicle

☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SL 5512B - X
	GRD 5791X - X
	Guo & Tanp finalised LS \$2800, 4 days.
	(Red \$3375.72, 54%)

(08/11/13) wof
ASS. REC. BY:

XML

REF: CTS

87924

(-2019)

ASSIGNMENT

From: Date: 23/8/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SL 5512 B

at Workshop m/s

Abwin Service

of No. 8 Kaki Bkt Ave 4 # 07-18

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

\$13k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SL 5512 B

Yr Regn:

14 Jan 2009

Type: M.Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 2

c.c

1498

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

148260

T/Radio:

Insured / Std / NI / NA

Eng/No:

JM0DE10Y190127156

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R16

R:

N

BS / DUN / EXNOVA / SYRFS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23-08-18

Survey held at

W/S

4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 10 OCT 2018

Date/Time, File Pass to?

11/10/18

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

W/S - TR

2800

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18015247/Gqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 21-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 5791Y	Veh. Inspected	SLL 5512B
Policy No.	DMCVSN3091831702	Coverage (\$)	0.00
Claim No.	SNM18D04048C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	21/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/08/2018	Inspection Date	23/08/2018
Survey held at	ABWIN SERVICE PTE LTD No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Aug 2018		21 Aug 2018 14:18 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	BORKAR RAKESH RAMESH		
Vehicle Reg. No.:	SLL5512B	Date of Loss:	19/08/2018 00:00 - :59
Claim Type:	TP / SNM18D04048C02	Policy/Cover Note No.:	DMCVSN3091831702
Vehicle Reg. No. (Insured):	GBD5791Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Abwin Service Pte Ltd (HQ) No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2, 415875 Kaki Bukit - Tel: 6713 9400		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/08/2018]		
Adj Asg. Remarks:	EST \$6552.38, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9792H
Vehicle Details	
Vehicle No.:	SLL5512B
Vehicle to be Exported:	No
Intended De-registration Date:	24 Aug 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 AT R
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	ZY510469
Chassis No.:	JMODE10Y190127156
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$14,359.00
Original Registration Date:	14 Jan 2009
First Registration Date:	14 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$14,359.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jan 2019
PARF Rebate Amount:	\$7,179.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jan 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$6,200.00
COE Rebate Amount:	\$239.00
Total Rebate Amount:	\$7,418.00

The information contained herein is correct as at 24 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 12:01
Date Of Accident	19/08/2018 11:00
Exact Location Of Accident	AYE CTE BEFORE CLEMENTI ROAD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL5512B
Insured/Policyholder	
Name Of Registered Owner	BORKAR RAKESH RAMESH
NRIC No	S7269792H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97284341
Alternative Phone No	OTHERS-97284341

Vehicle Particulars

Manufacturer	MAZDA
Model	2
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090659694
Cover Note Number	DRIVO CLASSIC

Driver

Name of Driver	BORKAR RAKESH RAMESH
NRIC No	S7269792H
Date Of Birth	03/04/1972
Occupation	INDOOR
Date Of Driving Pass	02/06/2015
Driving Experience	3 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97284341
Fax Number	
Contact Number	OTHERS-97284341
Email Address	NOEMAIL

Address BLK 3 #03-06
JURONG EAST STREET 32

Postcode 609478

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 3

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Passenger 1 NAME: : PASSENGER
GENDER: : FEMALE

Passenger 2 NAME: : PASSENGER
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I was travelling along lane 2. Suddenly the vehicle in front of me stopped. Upon seeing this, I also stopped and came to a complete stop without hit into this mentioned vehicle. Just then, vehicle B hit into the rear of my vehicle A. After collision, I alighted from my vehicle A then realised that vehicle C had hit into the rear of vehicle B. Thus in total, there were 3 vehicles involved in this chain collision, including my vehicle A.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD5791Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver AMIN MOHAMMED KHAIRUL

NRIC/Passport Number G8300132T

Contact Number 84220362

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBD9263D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

WOON TIAN PENG

NRIC/Passport Number

G7821573D

Contact Number

90040519

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

INCOME MOTOR SERVICE CENTRE

Report Date & Start Time: 20-08-2018 / 12:00

Report No: MT/

D.O.A: 19-08-2018
Time: 11:00 hrs

Vehicle No: S115512B Reporting Type:


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


20-08-18 / 12:00
Policyholder's Signature / Date & Time


20-08-18 / 12:00
Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along lane 2. Suddenly the vehicle in front of me stopped. Upon seeing this, I also stopped and came to a complete stop without hit into this mentioned vehicle. Just then, vehicle B hit into the rear of my vehicle A. After collision, I alighted from my vehicle A then realised that vehicle C had hit into the rear of vehicle B. Thus in total, there were 3 vehicles involved in this chain collision, including my vehicle A.

Declaration

I/We declare the foregoing particulars are true in every respect.

re Bull
20-08-18 / 12:00
Policyholder's Signature / Date & Time

20-08-18 / 12:00
Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre
AT
Witnessed by Reporting Centre Personnel

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Date : 20/08/2018
TP Vehicle No. : GBD-5791-Y
To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Attn : Motor Claim Department

Owner : BORKAR RAKESH RAMESH
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5090659694
Vehicle No. : SLL-5512-B
Make & Model : MAZDA 2 1.5 VVT (A)

Accident Date: 19/08/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAILGATE / <i>Panel</i>	\$1,500.00	
1	TAILGATE LOGO / <i>NSC</i>	\$65.00	
1	EMBLEM MAZDA 2 / <i>NSC</i>	\$75.00	
1	TAILGATE LOCK / <i>BT.</i>	\$138.50	
1	REAR WINDSCREEN MOULDING / <i>NSC</i>	\$128.60	
1	REAR BUMPER / <i>RE</i>	\$856.70	
1	REAR BUMPER SIDE RETAINER RH X	\$65.90	
1	REAR BUMPER SIDE RETAINER LH X	\$65.90	
1	END PANEL ?	\$389.00	
1	END PANEL TOP GARNISH ?	\$167.40	
1	WEATHER STRIP ?	\$246.40	
	Sub Total	\$3,698.40	
	Discount 20% on Parts	(\$739.68)	
		\$2,958.72	

Special Nett

1	REVERSE CAMERA ?	\$250.00	
1	REVERSE SENSOR ?	\$250.00	
1	REAR NUMBER PLATE & CASING / <i>Get.</i>	\$45.00	
	Sub Total	\$545.00	

Labour & Misc

LABOUR TO FACILITATE REPAIR	\$1,200.00	<i>400-600</i>
TO SPRAY PAINTING ON AFFECTED AREAS	\$1,000.00	<i>600</i>
TO RUST PROOF ON AFFECTED AREAS	\$100.00	<i>50</i>
TO REFIX REAR WINDSCREEN	\$120.00	<i>100</i>
TO TRANSFER TAILGATE COMPONENTS	\$120.00	<i>60</i>
TO CHECK ALL NECESSARY WIRINGS	\$80.00	<i>30.</i>
Sub Total	\$2,620.00	

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Date : 20/08/2018
TP Vehicle No. : GBD-5791-Y
To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Attn : Motor Claim Department

Owner : BORKAR RAKESH RAMESH
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5090659694
Vehicle No. : SLL-5512-B
Make & Model : MAZDA 2 1.5 VVT (A)

Accident Date: 19/08/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Sub Total	\$6,123.72	
	GST 7%	\$428.66	
	Total	\$6,552.38	

4-5 Days.

lumpsum repair.

After repair photos.

Eno Qiang - 8288 0282

23/8/18.

[Signature]
27/8/18

LKK Auto Co. warrants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

~~80626~~

ABWIN 諭輝

Date : 20/08/2018
TP Vehicle No. : GBD-5791-Y
To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Attn : Motor Claim Department

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Owner : BORKAR RAKESH RAMESH
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5090659694
Vehicle No. : SLL-5512-B
Make & Model : MAZDA 2 1.5 VVT (A)

Accident Date: 19/08/2018

Imodeloy

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAILGATE / <i>Part</i>	\$1,500.00	1347.3
1	TAILGATE LOGO / <i>MSC</i>	\$65.00	35.4
1	EMBLEM MAZDA 2 / <i>MSC</i>	\$75.00	41
1	TAILGATE LOCK / <i>BT</i>	\$138.50	/
1	REAR WINDSCREEN MOULDING / <i>MSC</i>	\$128.60	/
1	REAR BUMPER / <i>RE</i>	\$856.70	/
1	REAR BUMPER SIDE RETAINER RH X <i>NN</i>	\$65.90	X
1	REAR BUMPER SIDE RETAINER LH X <i>NN</i>	\$65.90	X
1	END PANEL <i>X Repair</i>	\$389.00	X
1	END PANEL TOP GARNISH <i>X</i>	\$167.40	X
1	WEATHER STRIP <i>X</i>	\$246.40	X
	Sub Total	\$3,698.40	2547.5
	Discount 20% on Parts	(\$739.68)	2038
		\$2,958.72	

Special Nett

1	REVERSE CAMERA <i>X DM</i>	\$250.00	200
1	REVERSE SENSOR <i>X NN</i>	\$250.00	X
1	REAR NUMBER PLATE & CASING / <i>Got</i>	\$45.00	40
	Sub Total	\$545.00	240

Labour & Misc

LABOUR TO FACILITATE REPAIR	\$1,200.00	400 - 600
TO SPRAY PAINTING ON AFFECTED AREAS	\$1,000.00	600
TO RUST PROOF ON AFFECTED AREAS	\$100.00	50
TO REFIX REAR WINDSCREEN	\$120.00	100
TO TRANSFER TAILGATE COMPONENTS	\$120.00	60
TO CHECK ALL NECESSARY WIRINGS	\$80.00	30
Sub Total	\$2,620.00	1240

3518
20% 2800

Date : 20/08/2018
 TP Vehicle No. : GBD-5791-Y
 To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 Attn : Motor Claim Department

IVAN TEO
 ABWIN SERVICE PTE LTD
 DID: 67139416
 Fax: 67139415
 HP: 86680608

Owner : BORKAR RAKESH RAMESH
 NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Certificate No. : 5090659694
 Vehicle No. : SLL-5512-B
 Make & Model : MAZDA 2 1.5 VVT (A)

Accident Date: 19/08/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Sub Total	\$6,123.72	
	GST 7%	\$428.66	
	Total	\$6,552.38	

4-5 Days.

lumpsum repair.

After repair photos.

Eno Qiao - 8288 082

23/8/18.

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18015247/GQD3N2

Date: 11/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3091831702
Claimant Vehicle No :	SLL5512B	Insured Vehicle No :	GBD5791Y
Date of Loss:	19/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D04048C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL5512B	Engine No:	ZY510469
Make & Model:	MAZDA 2, 1.5 (A)	Chassis No:	JM0DE10Y190127156
Reg. Date:	14/01/2009 (Man. Year: 2008)	Odometer:	148260 km
Colour:	Red		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50R16	Rear Tyre Size:	195/50R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,503.72	2,278.00	1,225.72	34.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	1,240.00	1,380.00	52.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,123.72	3,518.00	2,605.72	42.55
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	6,123.72	2,800.00	3,323.72	54.28
+ GST 7.00/7.00% (\$\$)	428.66	196.00	232.66	54.28
Nett Amount (\$\$)	6,552.38	2,996.00	3,556.38	54.28

INSPECTION

Date of Assignment:	21/08/2018	
Date Inspected:	23/08/2018 Inspected At:	Abwin Service Pte Ltd (HQ) No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2 Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2018)
Parts: 143	MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLL5512B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	1,500.00 FL	*1,347.30 FL
2	1		*TAILGATE LOGO	Necessary	65.00 FL	*35.40 FL
3	1		*EMBLEM MAZDA 2	Necessary	75.00 FL	*41.00 FL
4	1		*TAILGATE LOCK	Bent	138.50 FL	*138.50 FL
5	1		*REAR WINDSCREEN MOULDING	Necessary	128.60 FL	*128.60 FL
6	1		*REAR BUMPER	Deformed	856.70 FL	*856.70 FL
7	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	65.90 FL	*- FL
8	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	65.90 FL	*- FL
9	1		*END PANEL	Repair	389.00 FL	*- FL
10	1		*END PANEL TOP GARNISH	Not Necessary	167.40 FL	*- FL
11	1		*WEATHER STRIP	Not Necessary	246.40 FL	*- FL
12	1		*REVERSE CAMERA	Damaged	250.00 FS	*200.00 FS
13	1		*REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
14	1		*REAR NUMBER PLATE & CASING	Cut	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,243.40	2,787.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	739.68	509.50
Total Parts (\$\$)	3,503.72	2,278.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	1,200.00	400.00
2	TO SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
3	TO RUST PROOF ON AFFECTED AREAS	New	100.00	50.00
4	TO REFIX REAR WINDSCREEN	New	120.00	100.00
5	TO TRANSFER TAILGATE COMPONENTS	New	120.00	60.00
6	TO CHECK ALL NECESSARY WIRINGS	New	80.00	30.00
Gross Labour Cost (S\$)			2,620.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >