

Surveyor:

PASUL

DOI:

17/8/18

Date / Time:

17/8/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

6886 6517 C

Name of Insured:

JAE Auto S/C

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

15/8/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Yap Chey Chorn

Driver Tel No.:

97838198

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Dm on 5m 30 250 917m

T. DYNA

87 YBI Ave 4

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHE 7282 X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Dm on 5m 30 250 917m



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

3/18

JAE Auto

SHE 7282 X - CS3/Fc11801/4978/624d3; 008/18/18

-CS3/Fc11700/1860/501m2; 008/18/18

-CS3/Fc11600/8093/Agbdt; 008/29/4/18

6886 6517 C - CS3/Fc11801/4978/624d3; 008/18/18

-NA/C7112014936/24; 008/18/18

STAGE	DATE / PIC	
Non-Reporting ltr (1st):		
Non-Reporting ltr (2nd):		
Non-Reporting ltr (Final):		
Notification ltr (if non-pickup):		
Call OI:	30/11/18	
After call ltr to OI:	v101m	
Documentation Check List: Handler Typist		
Notification ltr (if non-pickup)	☐	☐
After call ltr to OI:	☒	☐
Authorisation To Act:	☒	☐
Release Voucher:	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☒	☐
Towing Invoice	☐	☐
LTA / GIA :	☒	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☒	☐
LOD	☒	☐
Payment Breakdown Form:	☐	☐
Post-Repair Photos:	☐	☐
Others:	☐	☐

PRELIMINARY ADVICE

Date/Time:

ms

Sent By:

ms

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

18/4/19

Confirm with:

William

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

SS

5735.84

Loss of Rental (LOR):

SS

690.00

(

6

days)

x 115.00

Loss of Use (LOU):

SS

300.00

(\$

50

x

6

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

7.49

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

6733.33

Global Sum SS:

6700.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

6700.00

Name 1:

Comfortdelgro engineering Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REPAIR ESTIMATE*

MAKE :

MODEL : HYUNDAI i40

DATE 16/8/2018 17:06

17/08/2018 17:00
Ake

CHINA

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7282X

MAKE :

MODEL : HYUNDAI i40

LKK Auto Club. This hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

DATE 16/8/2018 17:06

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (RH)			\$ 2,020.10
	Rear Fender Inner Lining (RH)			\$ 164.40
	Rear Windscreen Moulding			\$ 60.00
	Rear Door (RH)			\$ 2,201.10
	Rear Door 1/4 Glass (RH)			\$ 109.45
	Rear Wheel Hup-Cap (RH)			\$ 150.70
	SUB TOTAL		3764.60	\$ 4,705.75
	LESS 20%			\$ 941.15
	DISCOUNTED TOTAL			\$ 3,764.60
	Rear Fender Advertisement Logo (RH)			\$ 100.00
	Rear Windscreen Sealant			\$ 46.00
	Rear Door Advertisement Logo (RH)			\$ 100.00
	Rear Door Comfortdelgro & Apps Sticker (RH)			\$ 80.00
				\$ 326.00
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Transfer of Door			\$ 120.00
	Rear Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 2,930.00
	ESTIMATE TOTAL			\$ 7,020.60

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Pby P

CHINA

No illegal modification(s) is allowed
 • Supplemental item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3764.60

326

3764.60

326.00

1270.00

5360.60

Panel
HP 90000068

6 days

P/P

17/08/18 @

1445

Resurvey by paint

540

400

30

Xm

60

Xm

60

60

REPAIR ESTIMATE*

MAKE :

MODEL : HYUNDAI i40

DATE 16/8/2018 17:06

Ake

CHINA

MODEL : HYUNDAI i40		Qty	Parts Description/ Labour	Type	Unit Price	Amount
			Rear Fender (RH)			\$ 2,020.10
			Rear Fender Inner Lining (RH)			\$ 164.40
			Rear Windscreen Moulding			\$ 60.00
			Rear Door (RH)			\$ 2,201.10
			Rear Door 1/4 Glass (RH)			\$ 109.45
			Rear Wheel Hup-Cap (RH)			\$ 150.70
			</			

Team: ARC Repair TP(CFSO)1

JOB CARD

Sales Order:

JC NO: 305200885

OMER

IS CITYCAB PTE LTD

OMER NO. 7010070

LESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188 (P) (O)

DUNT CARD NO.

REGN NO.

SHC7282X

MILEAGE

MAKE

HYUNDAI

FUEL

E 1/2 F

MODEL

I-40

DATE/TIME IN

15.08.2018 21:15

YR OF MANU.

11.08.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU092642

COMPLETION DATE/TIME:

CHINA

JOB DESCRIPTION

Accident Date: 15.08.2018
NATURE: 3P 15.08.2018

S/NO


LABOR CODE

DESCRIPTION


FRONT



LEFT SIDE



REAR



RIGHT SIDE

WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.:

SHC7282X

LKE

Vehicle No.:

SHC7282X

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305200885
 REGN NO : SHC7282X
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 11.08.2016
 DATE/TIME IN : 15.08.2018 21:15
 ACCIDENT DATE : 15.08.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0575-G	I40V2 PANEL ASSY-QUARTER	1 L	2,020.10	20.00	1,616.08
0002 04-01-0103-0595-G	I40VC PANEL ASSY-RR DR RH	1 L	2,201.10	20.00	1,760.88
0003 04-01-0103-0883-G	I40VC GLASS + MOULDING AS	1 L	109.45	20.00	87.56
0004 04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1 L	150.70	20.00	120.56
0005 04-01-0103-0745-G	I40VC MOULDING-RR WDO GLA	1 L	60.00	20.00	48.00
0006 03-01-0103-0122-G	I40VC GUARD ASSY-RR WHEEL	1 L	164.40	20.00	131.52
0007 28-01-0103-2014-A	I40V3 APP LOGO REAR DOOR	1 N	80.00	2.00-	80.00
0008 05-01-0199-0032-A	(ALL)WINDSCREEN AHESIVE-3	2 N	46.00	0.20	46.00

SUB-TOTAL : 3,890.60

JOB NATURE

0000 20-05	RENEW ADVERTISMENT STICKER-	200.00
0001 L	PANEL BEATING	540.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA	400.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 29.08.2018

Time: 12:05:50

Page: 2

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305200885
REGN NO : SHC7282X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 11.08.2016
DATE/TIME IN : 15.08.2018 21:15
ACCIDENT DATE : 15.08.2018

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0003 17-01	CHECK ALL LIGHTING	30.00				
0004 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR			60.00		
0005 20-20	REMOVE/REFIX RR W/SCREEN TO ASST R/P			120.00		
0006 20-02	REMOVE/REFIX DOOR PARTS TO ASSIST REP			60.00		
0007 20-08	ADJUST REAR WHEEL ALIGNMENT			60.00		
SUB-TOTAL :						1,470.00
TOTAL :						5,360.60

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No 305200885
Date : 29/08/18

FINALIZATION FORM

To : LKK
Attn : Mr RASUL
Vehicle Reg No. SHC7282X CCPL

Fax :

15.08.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- GBB6517C
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$3,890.60
(b) Labour Charges	\$1,470.00
Total for Part-By-Part Repair Cost	\$5,360.60
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
Final Lumpsum Repair cost	


3. Estimated normal period for repairs: 6 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : RASUL
Date : 30/08/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Mei Kwan (LKKAUTO)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 28 August, 2018 4:53 PM
To: Mei Kwan (LKKAUTO)
Cc: Lucas Lee; Vivian Lau (LKKAUTO); Thin Thin (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving GBB6517C (OI : CTI - TBA) and SHC7282X (TP : LKK REF - CC3/CTI18015268/R1wa3) on 15.08.2018
Attachments: GBB6517C.pdf
Categories: HMK

Dear Mei Kwan,

Enclosed herewith our Insured GIA report as requested by you.

Thank you.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 23 August, 2018 2:08 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Lucas Lee <lucas.lee@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>; Thin Thin (LKKAUTO) <thinthin@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving GBB6517C (OI : CTI - TBA) and SHC7282X (TP : LKK REF - CC3/CTI18015268/R1wa3) on 15.08.2018

WITHOUT PREJUDICE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18015268/R1wa3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 30-04-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 6517C	Veh. Inspected	SHC 7282X
Policy No.	DMCVSN3078091700	Coverage (\$)	0.00
Claim No.	SNM18D03996C02/7	Excess (\$)	0.00
Assign From		Assign Date	17/08/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40 1.7	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU092642	Colour	YELLOW
Odometer	354836	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	6 mm
L/H Front Tyre	205/60 R16	HANKOOK	6 mm
R/H Rear Tyre	205/60 R16	HANKOOK	6 mm
L/H Rear Tyre	205/60 R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/08/2018	Inspection Date	17/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7282X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER (RH)	BUCKLED	2,020.10	2,020.10
1	REAR FENDER INNER LINING (RH)	DEFORMED	164.40	164.40
1	REAR WINDSCREEN MOULDING	NECESSARY	60.00	60.00
1	REAR DOOR (RH)	BENT	2,201.10	2,201.10
1	REAR DOOR 1/4 GLASS (RH)	CRACKED	109.45	109.45
1	REAR WHEEL HUP-CAP (RH)	SCRATCHED	150.70	150.70
	LESS 20% DISCOUNT		-941.15	-941.15
			3,764.60	3,764.60
SPECIAL NETT ITEMS				
1	REAR FENDER ADVERTISEMENT LOGO(RH) (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR ADVERTISEMENT LOGO (RH) (SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
			326.00	326.00
LABOUR				
	PANEL BEATING.		1,200.00	540.00
	SPRAY PAINTING CHARGE.		1,000.00	400.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	60.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	120.00
	REMOVE/REFIX REVERSE SENSOR .	NOT NECESSARY	120.00	-
	TRANSFER OF DOOR .		120.00	60.00
	REAR WHEEL ALIGNMENT .		120.00	60.00
	-		-	-
	-		-	-
	-		-	-
			2,930.00	1,270.00
GRAND TOTAL			7,020.60	5,360.60

Report Ref No. CC3/CTI18015268/R1wa3n2



RECOMMENDED COST OF REPAIRS			5,360.60
-----------------------------	--	--	----------

Report Ref No. CC3/CT118015268/R1wa3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.