



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18015269/K1sb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 23-08-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 3697P	Veh. Inspected	SHC 3055L
Policy No.	5089387025-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/08/2018	Inspection Date	21/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5089387025-01		VIN'S EXCITE TOURS PRIVATE LIMITED	201537834H	GBS	Comprehensive	PC3697P	PC3697P	10/04/2018	09/04/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/1009373-001	COMFORT TRANSPORTATION PTE LTD	SHC 3055L	PC 3697P	19/8/2018	\$ 1,623.66	\$ 1,095.46
2	MT/1009185-002	COMFORT TRANSPORTATION PTE LTD	SHC 8825Z	SFE 2060R	28/8/2018	\$ 2,892.18	\$ 800.00
3	MT/1009007-002	COMFORT TRANSPORTATION PTE LTD	SH 8358Z	RD 6187X	27/8/2018	\$ 2,089.88	\$ 814.45
4	MT/1009087-002	COMFORT TRANSPORTATION PTE LTD	SHA 4428Z	SIV 6885P	24/8/2018	\$ 6,595.38	\$ 5,236.10
5	MT/1008717-002	CITYCAB PTE LTD	SHC 7877E	SUA 3866B	24/8/2018	\$ 2,219.36	\$ 950.00
6	MT/1009120-002	COMFORT TRANSPORTATION PTE LTD	SHD 3624P	SIL 6504S	26/8/2018	\$ 6,844.92	\$ 1,510.06
7	MT/1008471-002	COMFORT TRANSPORTATION PTE LTD	SH 7842Z	FBK 6778T	22/8/2018	\$ 1,473.20	\$ 1,273.20
8	MT/1008626-002	COMFORT TRANSPORTATION PTE LTD	SHA 2462L	PC 6244T	23/8/2018	\$ 1,679.16	\$ 300.00
9	MT/1009154-002	CITYCAB PTE LTD	SHA 9452U	SJE 7737S	24/8/2018	\$ 2,731.58	\$ 650.00
10	MT/1008987-002	CITYCAB PTE LTD	SHA 621H	YN 8044B	26/8/2018	\$ 4,685.68	\$ 2,950.00
11	MT/1008975-002	CITYCAB PTE LTD	SHA 881Z	YP 2006R	26/8/2018	\$ 8,248.46	\$ 1,500.00
12	MT/1008414-002	COMFORT TRANSPORTATION PTE LTD	SHC 3331P	SLK 2650K	23/8/2018	\$ 3,696.80	\$ 2,050.00
13	MT/1008095-002	COMFORT TRANSPORTATION PTE LTD	SHA 3850T	FBK 1449B	17/8/2018	\$ 2,745.13	\$ 1,282.00

Claim received from LKK Auto

Workshops

59 Loyang Drive Singapore 509965
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
220 Upper Road Singapore 110003

24 Serangoon Loop Singapore 758156
7 Sengul Kadut Way Singapore 728791
601 Yishun Industrial Park A Singapore 768732

member of COMFORTDELGRO

Date/Time: 20.08.2018 15:41 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305202190

OMER
IS COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)


REGN NO.: SHC3055L	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 20.08.2018 11:30
YR OF MANU 03.07.2018	TARGET DATE
CHASSIS CODE KMHC851CVJU103419	COMPLETION DATE/TIME:

OUNT CARD NO.

JOB DESCRIPTION

Accident Date: 19.08.2018
NATURE: 3P 19.08.18

S/NO LABOR CODE DESCRIPTION



LED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Idgement Slip

Exit Pass

o.: SHC3055L JU NTUC LKK

Vehicle No.: SHC3055L

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 14:59
Date Of Accident	19/08/2018 03:10
Exact Location Of Accident	RIVER VALLY TWDS LOWER DELTA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC3055L
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ HYBRID

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	ONG KIAN YING
NRIC No	S2021664F
Date Of Birth	08/10/1951
Occupation	OUTDOOR
Date Of Driving Pass	21/11/1970
Driving Experience	47 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	+65-87987109
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	341 09-24 CHOA CHU KANG AVENUE 3
Postcode	689874
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC3697P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	ONG KIAN YING
Approximate Age	67
Injuries Sustain	NECK,BACK
Injured person in which vehicle?	SHC3055L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

Sketch by Harey

(A) SHC 8055C

(B) PC3697P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19 Aug 2018 @ 02:10 hr I with A

was driving along the above location.

I with A stop at the X Junction

Suddenly with B from rear hit with A rear.

at the point of accident with A being

a female passenger was OK.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


COMFORT TRANSPORTATION P.A.
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)




Reporting Centre Personnel's Signature
Name:


Sketch Plan Pg. 2



Sketch by
M. Ong.
WJ

River Valley
Road





COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 3055L

DATE 20/8/2018 14:53

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			459.40
	Rear Bumper Reinforcement			22.00
	Rear Bumper Clip			
	Rear Bumper Sponge			
	Rear Bumper Under Cover			322.30
	Rear Bumper Garnish (Black)			
	SUB TOTAL			\$ -
	LESS 20%			\$ -
	DISCOUNTED TOTAL			\$ -
	Rear Bumper Reverse Sensor			\$ 135.70
	Rev Number plate			\$ 135.70
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 820.00
	ESTIMATE TOTAL			\$ 955.70
				1,623.66

Rear Bumper Reverse Sensor X 500
 Rev Number plate - 100

10% \$25

Nett 72.00

Labour Charge
 Panel Beating
 Spray Painting Charge
 Wiring Charge
 Remove/Refix Reverse Sensor

200
 \$ 400.00
 \$ 250.00
 \$ 50.00
 \$ 120.00

Kalvi Uday
 20/8/18 11:56
 2 Bn
 PIP
 Before 1st p 44

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before starting spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal no. plate changes allowed
 • Supplemental claim must be resurveyed and is subject to approval from insurance company
 Acknowledged by Repairer:
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 29.08.2018

Time: 16:19:18

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305202190
REGN NO : SHC3055L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 03.07.2018
DATE/TIME IN : 20.08.2018 11:30
ACCIDENT DATE : 19.08.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 FNPS	NO PLATE(S)	1 N	25.00	10.00	22.50	
0002 04-01-0104-2533-G	IONIQV2 MOULDING ASSY-RR	1	322.30	20.00	257.84	
0003 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52	
0004 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	
						SUB-TOTAL : 665.46

JOB NATURE

0000 L	PANEL BEATING- REAR	200.00	
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00	
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00	
		SUB-TOTAL : 430.00	
		TOTAL : 1,095.46	

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305202190

Date : 29/08/2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

: SHC3055L

Date of Accident : 19/08/2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- PC 3697P
###
2. The finalized amount shall be:

(a) Spare Parts after List discount		\$665.46	
(b) Labour Charges	###	\$430.00	
Total for Part-By-Part Repair Cost		\$1,095.46	
(c) Lumpsum Repair (if applicable)			
Total for Lumpsum repair cost after Less: 20%			
Final Lumpsum Repair cost			

3. Estimated normal period for repairs: 2 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : KALVIN

Date : 29/8/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18015269/K1sbn2			
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 05-09-2018	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PC 3697P	Veh. Inspected	SHC 3055L
Policy No.	5089387025-01	Coverage (\$)	0.00
Claim No.	MT/1009373-001	Excess (\$)	0.00
Assign From		Assign Date	21/08/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHC851CVJU103419	Colour	BLUE
Odometer	29285	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEXEN	7 mm
L/H Front Tyre	195/65 R15	NEXEN	7 mm
R/H Rear Tyre	195/65 R15	NEXEN	7 mm
L/H Rear Tyre	195/65 R15	NEXEN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/08/2018	Inspection Date	21/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3055L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER REINFORCEMENT (NPA)	SERVICEABLE	-	-
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE (NPA)	SERVICEABLE	-	-
1	REAR BUMPER UNDER COVER (NPA)	SERVICEABLE	-	-
1	REAR BUMPER GARNISH (BLACK)	CRACKED	322.30	322.30
LESS 20% DISCOUNT			-160.74	-160.74
			642.96	642.96
<u>NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (N)	SERVICEABLE	135.70	-
1	REAR NUMBER PLATE (N)	CRACKED	25.00	25.00
LESS 10% DISCOUNT			-	-2.50
			160.70	22.50
<u>LABOUR</u>				
PANEL BEATING.			400.00	200.00
SPRAY PAINTING CHARGE.			250.00	200.00
WIRING CHARGE.			50.00	-
REMOVE/REFIX REVERSE SENSOR.			120.00	30.00
			820.00	430.00
GRAND TOTAL			1,623.66	1,095.46

RECOMMENDED COST OF REPAIRS (CONFIRMED)

1,095.46

Report Ref No. NS/INC18015269/K1sbn2


KALVIN ANG WEI KUN

Automotive Assessor / Investigator


K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.