

(08/11/13)

Surveylr: Kalvin

REF:

NS/INC18015271/Kirbez

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop no/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SJW 2047MPolicy No. 5101877011 010718-300619Claims No. MT/1007961-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 2284Z Yr Regn: 17 Aug 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/A / Prime Mover /

Truck / Trailer or

Make: Hyundai Zoniq c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 976 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHCL851CVK4106558

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195 / 65 R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 19/8/18 D.O.I. 21/8/18Survey held at CHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 2284Z - 003/10017011988/mipg392 DOA: 180617 INL
	SJW 2047M - X PIP
20/9/18	Insured PIP \$2124.90 / 4 Pys.
	Red: 81042.80, 321.
	RECEIVED 04 OCT 2018

Date/Time, File Pass to?

☐ : Prel. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4Resurvey No. of Trip: 1Survey Fee: 160

Transportation: \_\_\_\_\_

S + RS, SI

Photos

Others

TOTAL

Report Format: TPLump sum / I.B.I. (\$) 2124.90

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

160

TP Claims against NTUC Income: Follow-Through Survey

Date : 03/10/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/1014163-001	COMFORT TRANSPORTATION PTE LTD	SHB 4082G	SLL 450D	01/10/2018	\$ 2,639.76	\$ 350.00
2	MT/1013171-002	CITYCAB PTE LTD	SHC 7814L	SLK 2816A	26/09/2018	\$ 565.00	\$ 375.00
3	MT/1007961-002	COMFORT TRANSPORTATION PTE LTD	SHC 2284Z	SIW 2047M	19/08/2018	\$ 3,167.00	\$ 2,124.90
4	MT/1013655-002	COMFORT TRANSPORTATION PTE LTD	SHD 3499J	SIW 6467H	30/09/2018	\$ 2,273.60	\$ 1,200.00

Claim received from LKK Auto



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18015271/K1rb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 23-08-2018

189556



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJW 2047M	Veh. Inspected	SHC 2284Z
Policy No.	5101877011	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	19/08/2018	Inspection Date	21/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

## 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="19/08/2018 09:25"/>
Vehicle No.(For Motor)	<input type="text" value="SJW2047M"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5101877011		KATHLEEN LEE CHENG HAN	S2718996B	GPC	driva CLASSIC	SJW2047M	SJW2047M	01/07/2018	30/06/2019

Team:	ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO.: 305202756
CUSTOMER	COMFORT TRANSPORTATION PTE LTD	REGN NO.: SHC2284Z	MILEAGE	
MS	7010045	MAKE: HYUNDAI	FUEL	
CUSTOMER NO.	383 SIN MING DRIVE	MODEL	DATE/TIME IN	
ADDRESS	Singapore SINGAPORE 575717	IONIQ(G2)	19.08.2018 16:55	
(R)	65508755	YR OF MANU	TARGET DATE	
(P)		17.08.2018	COMPLETION DATE/TIME:	
COUNT CARD NO.		CHASSIS CODE		
		RMHC851CVKU106558		


JOB DESCRIPTION

Accident Date: 19.08.2018

NATURE: 3P 19.08.2018

S/NO LABOR CODE DESCRIPTION

NTUC - taxi rear Right damage



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC2284Z LARRY

Vehicle No.: SHC2284Z

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/08/2018 11:06
Date Of Accident	19/08/2018 15:40
Exact Location Of Accident	ECP(CITY) BF FORD ROAD EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC2284Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ HYBRID
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	TEN AH FATT
NRIC No	S1452921G
Date Of Birth	05/07/1960
Occupation	OUTDOOR
Date Of Driving Pass	21/07/1982
Driving Experience	36 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93434952
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	939 #05-171 TAMPINES AVENUE 5
Postcode	520939
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO


#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW2047M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TIMOTHY WONG JINC ZHONG
NRIC/Passport Number	S9221240H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT LEFT

No. Of Passenger (Including Driver)



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/8/18 at about 1545hrs while I Veh A was travelling along lane 1 of the highway, ran over a pothole and slowed down a little. Veh B who was tailgating me collided on the rear of my vehicle

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303921R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Reporting Centre Personnel's Signature  
Name:

*[Signature]*  
20/8/18

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:





- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


MFORT TRANSPORTATION PTE LTD  
CO REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:







## COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHC 2284Z

DATE 21/8/2018 10:27

MAKE :

MODEL : HYUNDAI IONIQ

DOA: 19.08.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>X 1/2</i>			
	Boot Lid Rubber <i>X 5/2</i>			
	Boot Lid Lock Upper <i>X 5/2</i>			
	Boot Lid Lock Lower <i>X 5/2</i>			
	Boot Lid Hybrid Plate <i>1/2</i>			\$24.30
	Boot Lid Ioniq Plate <i>1/2</i>			\$ 31.30
	Boot Lid 'H' Emblem <i>X 1/2</i>			
	Rear Bumper <i>1/2</i>			\$459.40
	Rear Bumper Reinforcement <i>X 5/2</i>			
	Rear Bumper Clip <i>X 1/2</i>			
	Rear Bumper Garnish (Black) <i>1/2</i>			\$216.50
	Rear Bumper Sponge <i>X 5/2</i>			
	Rear Bumper Under Cover <i>X 5/2</i>			
	Rear Bumper Reflector Lamp, RH <i>1/2</i>			\$31.90
	Rear Bumper Under Side Cover, RH <i>1/2</i>			\$27.50
	Tail Lamp (RH) <i>X 5/2</i>			
	Rear Panel <i>X 1/2</i>			
	Rear Panel Garnish <i>X 5/2</i>			
	Unit Assy-BSD <i>X 5/2</i>			
	Rear Windscreen Glass <i>X 1/2</i>			
	Rear Windscreen Moulding <i>X 1/2</i>			
	Rear RH Fender <i>X 1/2</i>			
	Rear Bumper Side Bracket (RH) <i>1/2</i>			
	<b>SUB TOTAL</b>			\$33.10
	<b>LESS 20%</b>			
	<b>DISCOUNTED TOTAL</b>			
	Boot Lid Comfort Logo & Tel No. Sticker <i>1/2</i>			\$ 30.00
	Rear No. Plate <i>X 5/2</i>			\$ 25.00
	Rear No. Plate Trim Cover <i>X 5/2</i>			\$ 30.00
	Rear Bumper Reverse Sensor <i>1/2</i>			\$ 135.70
	Rear Windscreen Sealant <i>X 1/2</i>			\$ 46.00
	<b>Labour Charge</b>			\$ 268.50
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	<b>TOTAL LABOUR</b>			\$ 2,240.00
	<b>ESTIMATE TOTAL</b>			3167.70
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

# COMFORTDELGRO ENGINEERING

Our Job Ref No . 305202756

Date : 20. Sep. 2018

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHC2284Z

Date of Accident: 19. Aug. 2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SJW2047M

2. The finalized amount shall be:

(a) Spare Parts after List discount \$824.90

(b) Labour Charges \$1,300.00

**Total for Part-By-Part Repair Cost \$2,124.90**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: \_\_\_\_\_

**Final Lumpsum Repair cost** \_\_\_\_\_

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kalvin

Date : 20/9/18

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

## COMFORTDELGRO ENGINEERING PTE LTD

Date: 20.09.2018

## REPAIR ESTIMATE

Time: 16:33:43

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305202756  
REGN NO : SHC2284Z  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 17.08.2018  
DATE/TIME IN : 19.08.2018 16:55  
ACCIDENT DATE : 19.08.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	28-01-0103-0005-A	(I40/SONATA)REAR BOOT LOG	1	15.00	0.00	15.00
0002	28-01-0103-0006-A	(I40/SONATA)REAR BOOT TEL	1	15.00	0.00	15.00
0003	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52
0004	04-01-0104-2533-G	IONIQV2 MOULDING ASSY-RR	1	216.50	20.00	173.20
0005	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	135.70	0.00	135.70
0006	04-01-0104-0852-G	IONIQVC REFLECTOR/REFLEX	1	31.90	20.00	25.52
0007	04-01-0104-2270-G	IONIQ EMBLEM-HYBRID	1	24.30	20.00	19.44
0008	04-01-0104-2271-G	IONIQ EMBLEM-IONIQ	1	31.30	20.00	25.04
0009	04-01-0104-2532-G	IONIQVC BRACKET ASSY-RR B	1	33.10	20.00	26.48
0010	04-01-0104-2547-G	IONIQVC COVER-RR BUMPER S	1	27.50	20.00	22.00

SUB-TOTAL : 824.90

## JOB NATURE

0000 L	PANEL BEATING	600.00
--------	---------------	--------

## COMFORTDELGRO ENGINEERING PTE LTD

Date: 20.09.2018

## REPAIR ESTIMATE

Time: 16:33:43

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305202756  
REGN NO : SHC2284Z  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 17.08.2018  
DATE/TIME IN : 19.08.2018 16:55  
ACCIDENT DATE : 19.08.2018

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 23-502	SPRAYPAINT ON AFFECTED AREA			600.00		
0002 17-01	WIRING CHARGE			20.00		
0003 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR			50.00		
0004 L	REMOVE/REFIX REVERSE SENSOR			30.00		
				SUB-TOTAL : 1,300.00		
				TOTAL : 2,124.90		

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18015271/K1rbe2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 24-10-2018	
Code: INC4			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJW 2047M	Veh. Inspected	SHC 2284Z
Policy No.	5101877011	Coverage (\$)	0.00
Claim No.	MT/1007961-002	Excess (\$)	0.00
Assign From		Assign Date	21/08/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHC851CVKU106558	Colour	BLUE
Odometer	976	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	7 mm
L/H Front Tyre	195/65 R15	MICHELIN	7 mm
R/H Rear Tyre	195/65 R15	MICHELIN	7 mm
L/H Rear Tyre	195/65 R15	MICHELIN	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	19/08/2018	Inspection Date	21/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2284Z**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BOOT LID (NPA)	TO REPAIR SEE LABOUR	-	-
1	BOOT LID RUBBER (NPA)	SERVICEABLE	-	-
1	BOOT LID LOCK UPPER (NPA)	SERVICEABLE	-	-
1	BOOT LID LOCK LOWER (NPA)	SERVICEABLE	-	-
1	BOOT LID HYBRID PLATE	NECESSARY	24.30	24.30
1	BOOT LID IONIQ PLATE	NECESSARY	31.30	31.30
1	BOOT LID 'H' EMBLEM (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER REINFORCEMENT (NPA)	SERVICEABLE	-	-
1	REAR BUMPER CLIP (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER GARNISH (BLACK)	CRACKED	216.50	216.50
1	REAR BUMPER SPONGE (NPA)	SERVICEABLE	-	-
1	REAR BUMPER UNDER COVER (NPA)	SERVICEABLE	-	-
1	REAR BUMPER REFLECTOR LAMP, RH	CRACKED	31.90	31.90
1	REAR BUMPER UNDER SIDE COVER, RH	CRACKED	27.50	27.50
1	TAIL LAMP (RH) (NPA)	SERVICEABLE	-	-
1	REAR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR PANEL GARNISH (NPA)	SERVICEABLE	-	-
1	UNIT ASSY-BSD (NPA)	SERVICEABLE	-	-
1	REAR WINDSCREEN GLASS (NPA)	NOT NECESSARY	-	-
1	REAR WINDSCREEN MOULDING (NPA)	NOT NECESSARY	-	-
1	REAR RH FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER SIDE BRACKET (RH)	CRACKED	33.10	33.10
	LESS 20% DISCOUNT		-164.80	-164.80
			659.20	659.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	30.00	30.00
1	REAR NO. PLATE (SN)	SERVICEABLE	25.00	-

Report Ref No. NS/INC18015271/K1rbe2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NO. PLATE TRIM COVER (SN)	SERVICEABLE	30.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR WINDSCREEN SEALANT (NPA) (SN)	NOT NECESSARY	46.00	-
			266.70	165.70
	<b>LABOUR</b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOT LID, REAR PANEL AND REAR RH FENDER.		1,000.00	600.00
	SPRAY PAINTING CHARGE.		750.00	600.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	50.00
	REMOVE / REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE / REFIX REVERSE SENSOR.		120.00	30.00
			2,240.00	1,300.00
<b>GRAND TOTAL</b>			<b>3,165.90</b>	<b>2,124.90</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>2,124.90</b>

Report Ref No. NS/INC18015271/K1rbe2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.