

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0947/2018/PH
Date : 19-Aug-18

Vehicle not IN workshop. Kindly arrange for survey.

NTUC Income Insurance Co - Claims Department

73 Bras Basah Road

#05-01 NTUC Trade Union House

Singapore 189556

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Ms Ong Siok Luan
Address : Blk 954 Dunearn Road
#03-14
Singapore 589483
Telephone : HP +6596901475
Type of Claim : Own Damage Claims
Policy No. : 1700006472-01
Vehicle No : **SLN 7819 T**
Model Code : Audi A3 1.0 TFSI
Model / Year : May-17
Engine No : CHZ351321
Chassis No : WAUZZZ8V2HA122394
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Aug-18
Place of Accident : Commonwealth Avenue West

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN7819T .

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To carry out first measurement test on car o-line	S/N \$	800.00	?
2	To remove and transfer rear parking aid.Check function.	S/N \$	280.00	/
3	To renew lhs 1/4 glass and rear windscreen to facillitate fender renewal.	S/N \$	600.00	/
4	To remove and reinstall rear lid's convenience lock system,wire harness for tail lights and rear wiper assy.	S/N \$	480.00	/
5	To dislodge and reinstall rear wire harness for lights,battery manager,fuse and relay trays,electrical and audio equipment.Inspect for damage and renew where necessary.	S/N \$	1,400.00	/
6	To remove and reinstall rear seat,back rest,hatch tray,ABCD pillar trims,luggage compartment trims.Dislodge roof liner and disengagecurtain air bag etc.	S/N \$	1,400.00	/
7	To dismantle and reinstall centre console.Renew airbag control unit and both front seatbelt.	S/N \$	1,800.00	/
SUB TOTAL LABOUR CHARGES		:	\$ 6,760.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN7819T .

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
8	To remove and reinstall exhaust system and rear suspension assembly, including rear axle and propeller shaft. Renew accordingly.	S/N \$ 2,800.00	?
9	To remove and reinstall fuel tank assy.	S/N \$ 600.00	?
10	To set up vehicle on car o-liner for repair	S/N \$ 1,800.00	?
11	To dismantle and renew rear bumper and rear lid. Repair and straighten lhs rear chassis frames to specification of origin. Cut out and weld rear end panelling, spare wheel housing and lhs rear fender. Repair rhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	S/N \$ 11,400.00	4500
12	To carry out stone chip primer work on rear panelling and spare wheel housing.	S/N \$ 780.00	300
13	To respray rear bumper, rear lid, both rear fender, lhs rear door, lhs sill panel, drain panel, roof channel, door entrances, end panelling, spare wheel housing and boot floor. To carry out stone chip treatment, cavity preservation and joint sealer works.	S/N \$ 8,000.00	4400
14	To carry out wheel alignment	S/N \$ 240.00	/
15	To carry out diagnostic check	S/N \$ 384.00	/
TOTAL LABOUR CHARGES		: \$ 32,764.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 7819T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER / <i>RL</i>	\$ 1,619.00	
2	FIXING PARTS FOR REAR BUMPER / <i>RLC</i>	\$ 166.00	
3	ADAPTER WHEEL HOUSING LINER - LH/RH <i>LH/RL 2 \$ RH X NN</i>	64.00	
4	REAR BUMPER SPOILER / <i>GA</i>	\$ 206.00	
5	REAR LIGHT REFLECTOR - LH/RH <i>LH - his RH X NN</i>	2 \$ 52.00	
6	LOCKING MECHANISM - LH/RH / <i>RLC</i>	2 \$ 22.00	
7	GUIDE SECTION - LH/RH / <i>RL</i>	2 \$ 114.00	
8	BRACKET - LH/RH / <i>RLC</i>	2 \$ 48.00	
9	SENSOR - INNER/OUTER / <i>DM</i>	4 \$ 842.00	
10	SEAL RING / <i>RLC</i>	4 \$ 14.00	
11	WIRING SET FOR BUMPER ?	\$ 458.00	
12	REAR LID / <i>BT</i>	\$ 1,782.00	
13	ATTACHMENT PARTS FOR REAR LID / <i>RLC</i>	\$ 253.00	
14	LID HINGE - LH/RH / <i>BT</i>	2 \$ 269.00	
15	STOP BUFFER / <i>RLC</i>	2 \$ 32.00	
16	STOP BUFFER FOR REAR LID / <i>RLC</i>	2 \$ 35.00	
17	GAS FILLED STRUT ?	2 \$ 177.00	
18	BALL STUD / <i>RLC</i>	2 \$ 36.00	
19	GASKET FOR FLAP / <i>RLC</i>	\$ 176.00	
20	LID LOCK / <i>BT</i>	\$ 157.00	
SUB TOTAL SPARE PARTS CHARGES :		<u>\$ 6,522.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 7819T .

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
21	PUSH BUTTON FOR BOOT LOCK ACTUATOR ?	\$ 1,181.00	
22	LED LICENCE PLATE LIGHT ?	2 \$ 187.00	
23	LOCK STRIKER ?	\$ 76.00	
24	PACKING ADHESIVE /	\$ 15.00	
25	AUDI EMBLEM /	\$ 108.00	
26	A3 ' EMBLEM /	\$ 83.00	
27	TFSI' EMBLEM /	\$ 83.00	
28	REAR WINDSCREEN /	\$ 675.00	
29	PRIMER /	\$ 19.00	
30	SPOILER X NN	\$ 1,467.00	
31	1 SET OF FOAM STRIPS / MCC	\$ 123.00	
32	ADDITIONAL BRAKE LIGHT X { NN	\$ 155.00	
33	FIXING PARTS FOR SPOILER X { NN	\$ 147.00	
34	LED TAIL LIGHT - LH/RH < LH - CRA RH ?	2 \$ 1,460.00	
35	COUPLING ELEMENT BLACK /	2 \$ 45.00	
36	COUPLING ELEMENT /	2 \$ 45.00	
37	CORRUGATED PIPE /	\$ 73.00	
38	HOSE /	3 \$ 48.00	
39	1 SET:SHRINK FIT SLEEVES HOSE /	2 \$ 262.00	
40	WIPER MOTOR ?	\$ 403.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 6,655.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 7819T .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	1 SET BEARING BRUSHES / <i>del</i>	\$	46.00
42	WIPER ARM /	\$	73.00
43	WIPER BLADE /	\$	23.00
44	WATER JET /	\$	25.00
45	CAP /	\$	17.00
46	REAR LID TRIM PANEL - LOWER <i>X del</i>	\$	500.00
47	REAR LID TRIM PANEL SOUL(BLACK) ?	\$	250.00
48	COVER FOR LUGGAGE COMPARTMENT ?	\$	394.00
49	WARNING TRIANGLE ?	\$	187.00
50	REAR CROSS PANEL ?	\$	216.00
51	REINFORCEMENT FOR CROSS PANEL ?	\$	645.00
52	CONNECTING PLATE -LH/RH ?	2 \$	72.00
53	TRIM FOR REAR CROSS PANEL SOUL(BLACK) ?	\$	135.00
54	SECTIONAL PART - SIDE PANEL - LH REAR <i>del</i>	\$	1,938.00
55	C - PILLAR PLATE - LH OUTER <i>del</i>	\$	18.00
56	FILLER PLATE - LH UPPER ?	\$	330.00
57	SIDE PANEL -RH REAR <i>X repair</i>	\$	660.00
58	CONNECTING PLATE - RH OUTER <i>X</i>	\$	49.00
59	SIDE WINDOW - LH <i>del</i>	\$	225.00
60	PRIMER /	\$	19.00
SUB TOTAL SPARE PARTS CHARGES :		\$	5,822.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 7819T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	LUGGAGE COMPARTMENT TRIM - LH ?	\$ 914.00	
62	WHEEL HOUSING LINER - LH ?	\$ 215.00	
63	ATTACHMENT PARTS FOR WHEEL LINER ?	\$ 49.00	
64	LED TAIL LIGHT-LH/RH < LH - SPA ? RH ?	2 \$ 1,460.00	
65	SECURING ELEMENT	2 \$ 20.00	
66	GROMMET	4 \$ 60.00	
67	MOLDING - ROOF CHROME - LH	\$ 509.00	
68	TRIM STRIPS FOR SIDE WINDOW CHROME-LH REAR	\$ 226.00	
69	CORNER TRIM BLACK-GLOSSY - LH X	\$ 64.00	
70	WINDOW SLOT SEWAL WITH TRIM STRIP CHROME - LH REAR	\$ 234.00	
71	BOOT FLOOR PLATE ?	\$ 1,603.00	
72	CROSS MEMEBER - CENTRE ?	\$ 313.00	
73	CONNECTING PLATE - LH/RH ?	2 \$ 162.00	
74	CROSS MEMEBER - REAR ?	\$ 190.00	
75	CROSS PANEL FOR SIDE MEMBER - LH ?	\$ 58.00	
76	D-PILLAR TRIM - LH UPPER ?	\$ 141.00	
77	D-PILLAR TRIM - RH UPPER X	\$ 141.00	
78	PLASTIC TRAY ?	\$ 253.00	
79	LUGGAGE COMP.FLOOR COVERING BLACK ?	\$ 875.00	
80	FLOOR SILENCER ?	\$ 442.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 7,929.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 7819T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
81	REAR SILENCER ?	\$	556.00
82	DUAL CLIP ?	\$	53.00
83	RETAINER FOR EXHAUST SYSTEM ?	2 \$	72.00
84	3 POINT AUTOMATIC SEAT BELT WITH BELT TENSIONER - LH	\$	956.00
85	3 POINT AUTOMATIC SEAT BELT WITH BELT TENSIONER - RH	\$	956.00
86	SEAT BELT HEIGHT ADJUSTER ?	2 \$	343.00
87	CONTROL UNIT FOR AIRBAG	\$	1,525.00
88	CRASH SESNOR FOR AIRBAG	\$	239.00
89	CAR PLATE - REAR	S/N \$	25.00
90	ARCYLIC SEALANT	S/N \$	180.00
91	CAVITY WAX	S/N \$	140.00
92	STONE CHIP TREATMENT	S/N \$	180.00
93	MEATAL FILLER POWDER	S/N \$	280.00
94	REAR WINDSCREEN SEALANT	S/N \$	200.00
95	1/4 GLASS SEALANT	S/N \$	100.00
96	SUNDRIES ?	\$	1,000.00
TOTAL SPARE PARTS CHARGES		:	\$ 33,733.00
TOTAL LABOUR CHARGES		:	\$ 39,524.00
GRAND TOTAL		:	\$ 73,257.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

15 Days.
Name : before paint photos
Surveyed Date :
Authorised Date :
Excess Cost : Gao Qitup.
Liability :
Remarks : 21/8/18.
Not Authorised.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant