

KIM CHWEE AUTO PTE LTD**1 Kaki Bukit Ave 6 #01-48 Autobay****Singapore 417883****Tel No: 67452063 / 67467158 Fax No: 67458520**Not Authorized
Hbr

4/5 @ 12.000

15 day.

23/8/18

Vehicle No: **SJX687Z**

Model: Hyundai Avante

QTYDESCRIPTIONAMT SS

	<u>List Items</u>			
1	Rear boot lid	S	Buc	907.60
2	Rear boot hinges	S	n	225.40
2	Rear boot lamps	S	one	379.20
1	Rear boot lock	S	lmi	183.60
1	Rear boot logo	S	rec	22.80
1	Rear boot rubber	S	to.n	115.20
1	Rear boot "AVANTE" emblem	S	rec	30.50
2	Rear taillamps	S	bro	533.00
1	Rear end panel	S	to.n	637.90
1	Rear end panel inner garnish	S	lmi	188.60
1	Rear bumper	S	D.S	486.90
2	Rear bumper brackets	S	Bul	41.00
2	Rear bumper top brackets	S	Bul	64.00
1	Rear bumper clip (1 set)	S	rec	50.00
1	Rear bumper reinforcement	S	D.S	354.00
2	Rear bumper reinforcement stays	S	Bul	270.00
2	Rear bumper side retainers	S	Bul	89.60
1	Rear floor board	S	n	280.60
1	Rear floor panel	S	crumple/Buc	803.90
1	Rear exhaust silencer	S	D.S	693.80
2	Rear exhaust mountings	S	to.n	97.00
1	Front bonnet	S	Buc	1,102.00
1	Front bonnet lock	S	lmi	83.60
1	Front bonnet rubber	S	rec	42.00
2	Front headlamps	S	one	1,163.20
1	Front grille	S	bro	385.00
1	Front grille logo	S	rec	22.80
1	Front bumper	S	D.S	480.60
2	Front bumper brackets	S	Bul	84.00
1	Front bumper inner sponge	S	to.n	125.80
1	Front bumper lower grille	S	D.S	98.80
		S		10,042.40

212

List Items

1	Front bumper reinforcement	S	Dis	431.50	✓
2	Front bumper side retainers	S	Bul	84.40	✓
2	Front bumper side grilles	S	Dis	84.20	✓
1	Front fender	S	Bul	385.10	✓
1	Front support panel	S	Dis	985.00	✓
2	Front support panel side garnish covers	S	Yo-n	97.00	✓
1	Horn	S	11	89.60	X
1	Air con condenser	S	Dis	950.00	✓
1	Radiator assy	S	Dis	685.00	✓
1	Radiator electric fan assy	S	Bul	625.00	✓
		S		14,459.20	
		Less 20%	S	2,891.84	
		S		11,567.36	

13863.6
11090.88

Special Nott Items

1	Rear number plate with holder	S	Bul	50.00	40
1	Rear reverse sensor (1 set)	S	shut	350.00	200
1	Front bumper clip (1 set)	S	m	45.00	✓
1	Front number plate with holder	S	Bul	50.00	40
		S		495.00	

S/N. Labour Charges

1	To check wiring and reset headlamps focussing.	S		80.00	730
2	To remove, replaced damaged lamps and check up rear wiring.	S		80.00	
3	To remove and refit inner garnishes.	S		150.00	80
4	To remove and refit rear reverse sensor.	S		120.00	50
5	To transfer boot lid mechanism and wiring.	S		80.00	60
6	To remove, replace air-con, refill gas & conduct leakage test.	S		180.00	100
7	To remove, refit and replace exhaust silencer and mountings.	S		120.00	60
8	To apply tuff kote.	S		200.00	150
9	Panel beating.	S		1,800.00	✓
10	To respray painting.	S		1,600.00	✓
		S		4,410.00	

18341.88
12276

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Total Repair Cost : S 16,472.36