

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Aug-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6455 X

1 pc	Rear o/s door ✓	\$ 791.00
2 pcs	Rear o/s door hinges @ \$34.00 ✗	\$ 68.00
1 pc	o/s rocker panel garnish ✓	\$ 286.00
1 pc	Rear o/s fender @ \$1205.00 ✓	\$ 1,205.00
1 pc	Rear o/s fender inner shield @ \$120.00 ✓	\$ 120.00
		\$ 2,470.00
	Less 10%	\$ 247.00
		\$ 2,223.00

S/NETT

1 set	o/s door stickers ✓	\$ 100.00
1 set	o/s rocker panel garnish clips ✓	\$ 38.00
1 pc	Rear o/s fender sticker ✓	\$ 60.00
1 set	Rear o/s fender inner shield clips ✓	\$ 28.00
	Sundry	
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 50.00 ²⁰
	To dismantle and refit the inner component of rear o/s door into new shell door	\$ 180.00 ⁵⁰
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld cut-off the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$ 150.00 ⁶⁰⁰
	To putty and spray painting on rear o/s door, o/s rocker panel garnish, rear o/s fender	\$ 600.00 ⁵⁴⁰
	To apply rustproofing on the repaired and replaced panels.	\$ 150.00 ⁵⁰
		\$ 4,979.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to confirmation from insurance company

Acknowledged by Repairer
Signature: _____

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin (LKK)
21/8/18 1x20hrs
4 Days
4/5
After Repair photo