




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD			Ref : CS/UOI18015297/R1vbs2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date : 17-10-2018	
			Code : UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY		Veh. Inspected	PC 7159A
Policy No.	DHOL110042521302		Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From	CHAN LI SI		Assign Date	23/08/2018
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ		c.c	2143
Engine No.	HIDDEN		Year of Reg.	2018
Chassis No.	WDF44781523343210		Colour	BLACK
Odometer	16146		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	FAIR			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/65R16	HANKOOK	7 mm
	L/H Front Tyre	205/65R16	HANKOOK	7 mm
	R/H Rear Tyre	205/65R16	HANKOOK	7 mm
	L/H Rear Tyre	205/65R16	HANKOOK	7 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	16/08/2018	Inspection Date	23/08/2018
	Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	