

HUP SAN CHUAN MOTOR WORKS

1 KAKI BUKIT AVE 6 #02-30 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883

HP : 90118191

judytansm@hotmail.com

253350

DATE: 21/8/2018

M/S AXA INSURANCE SINGAPORE PTE. LTD.

TYPE : TP

8 SHENTON WAY

#27-01 AXA TOWER

ACCIDENT : 18/08/2018

SINGAPORE 068811

RE: ESTIMATED REPAIR COST OF SGS1549U VIOS

1	1PCE FRONT GRILLE / CPA	\$	254.00 /
2	1PCE FRONT GRILLE NET / RE	\$	55.00 /
3	2PCS HEAD LAMP @\$315.00 < LH - CPA RH - CPA	\$	630.00 /
4	1PCE FRONT BUMPER / RE	\$	236.00 /
5	1PCE FRONT BUMPER BEAM / BT	\$	258.00 /
6	2PCS FRONT BUMPER SIDE BRACKET @\$48.50 < LH X m RH - RE	\$	97.00 48.5
7	6PCS FRONT BUMPER CLIPS @\$3.00 / mcl	\$	18.00 /
8	1PCS FRONT BUMPER CENTRE GARNISH LOWER X	\$	84.50
9	1PCE FRONT BUMPER SIDE GARNISH @\$38.50 X } NN	\$	77.00
10	1PCE FRONT BONNET LOCK X	\$	50.50
11	1PCE FRONT BONNET LOCK BRACKET X	\$	23.00
12	1PCE REAR BOOTLID / BT	\$	555.00 /
13	1PCE REAR BOOTLID LOGO / mcl	\$	34.00 /
14	1PCE REAR BOOTLID MOULDING X } NN	\$	84.50
15	1PCE REAR BOOTLID TOP SPOILER X	\$	394.00
16	1PCE REAR BOOTLID LOCK TOP / BT	\$	55.00 /
17	1PCE REAR BOOTLID LOCK LOWER X } NN	\$	32.00
18	2PCS REAR BOOTLID HINGE @\$68.00 X	\$	136.00
19	1PCE REAR BOOTLID RUBBER	\$	68.00 /
20	2PCS RER LAMP @\$232.00 / CPA	\$	464.00 /
21	1PCE REAR BUMPER / RE X NN	\$	236.20 /
22	1PCE REAR BUMPER BEAM	\$	55.00
23	2PCS REAR BUMPER SIDE BRACKET @\$38.00 / mcl	\$	76.00 /
24	6PCS REAR BUMPER CLIPS @\$3.00 / mcl	\$	18.00 /
25	1PCE REAR PANEL TOP GARNISH / RE	\$	78.40 /
26	1PCE REAR FENDER LH / mcl	\$	559.00 /
27	2PCS REAR FENDER INNER TRIM COVER @\$274.00 / TN	\$	548.00 /
28	1PCE REAR FENDER LOWER AIR COWLING X	\$	88.00
29	2PCS REAR FENDER COVER @\$66.00 X } NN	\$	132.00
30	1PCE REAR EXHAUST BOX MOUNTING X	\$	32.40
31	2PCS REAR NUMBER PLATE LAMP @\$48.50 X	\$	97.00
32	1PCE REAR SPARE TYRE TOP BOARD / CPA	\$	188.00 /
33	1PCE REAR SPARE TYRE FLOOR PANEL / mcl	\$	557.00 /
34	1PCE REAR SPARE TYRE SCREW X NN	\$	84.50
35	1PCE REAR WINDSCREEN GLASS MOULDING / mcl	\$	78.50 /
36	1PCE REAR WINDSCREEN INNER SEAL	\$	65.80 /
		\$	6,499.30
		\$	1,299.86
		\$	5,199.44

5786.5

25%
- ADD 20%

25% * 4360.18

PARTS A

37 1PCE REAR EXHAUST BOX X NN
 38 1SET REVERSE SENSOR - PM
 39 1PCE REAR TYRE LH X NN
 40 1PCE FRONT NUMBER PLATE - CPH
 41 1PCE FRONT NUMBER PLATE FRAME - Cut
 42 1PCE REAR NUMBER PLATE X NN
 43 1PCE REAR NUMBER PLATE FRAME - SUR.

S/NETT	\$	680.00	
S/NETT	\$	280.00	200
S/NETT	\$	195.00	
S/NETT	\$	25.00	/
S/NETT	\$	25.00	/
S/NETT	\$	25.00	
S/NETT	\$	25.00	-15
PARTS B	\$	1,255.00	265
TOTAL PARTS	\$	6,454.44	

LABOUR :

44	TOWING FEE.	\$	80.00	/
45	WIRING (FRONT & REAR).	\$	80.00	30
46	KNOCKING AND WELDING FRONT PORTION	\$	450.00	200
47	REMOVE AND REFIX LUGGAGE COMPARTMENT.	\$	180.00	60
48	REMOVE AND RFX REAR EXHAUST BOX AND PIPE.	\$	90.00	60
49	REMOVE AND INSTALL REAR WINDSCREEN GLASS.	\$	150.00	100
50	REMOVE AND REFIX REAR CUSHION SEAT	\$	135.00	60
51	SPRAY AUTI RUST UNDER COAT.	\$	90.00	60
52	KNOCKING AND WELDING , REAR UNDER CARRIAGE.	\$	1,750.00	1200
	REPLACING DAMAGED PARTS.			
53	SPRAY PAINT ALL NECESSARY PARTS AND AREAS.	\$	1,800.00	1400

LABOUR TOTAL	\$	4,850.00
TOTAL COST	\$	11,259.44

3250

7855.18

Gino Ciani - 82880282

20%: 500

lump sum repair.

After repair photos.

21/8/18.

10 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: