



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

EA 9817 L

Parts	(a) Cost / List Price Items	\$	5,765.97
	Plus/Less 25%	\$	1,441.49
	Total of Cost / List	\$	4,324.48
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	1,145.00
Total Parts Cost		\$	5,469.48
Labour		\$	3,340.00
Total		\$	8,809.48

Finalised

Not Authorized

Recurring Repair

4790.34

1072.59

3717.75

740

3457.75

1850

5307.75

✓ ok

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

CKK

Survey conducted on

23/8/18

at 13:40

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / Not Required

(d) Excess

\$

(e) Signature of surveyor

Le

Date: 23/8/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **EA 9817 L**
Make & Model : **TOYOTA SIENTA**
Chassis No. : **NHP1707121803**

Submit By : **Carmen Lim**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1	\$70.22	✓	✓
2	Rear windscreen sealant	1	\$50.00	✓ S.N	401m
3	Reverse sensor	2	\$400.00	✓ S.N	200m
4	Rear number plate	1	\$45.00	S.N	X
5	Rear bumper	1	\$377.80	✓	✓
6	Rear bumper lower centre	1	\$242.40	✓	✓
7	Rear bumper lower garnish LH	1	\$172.40	✓	✓
8	Rear bumper lower garnish RH	1	\$172.40		X
9	Rear bumper reflector LH	1	\$68.20		X
10	Rear bumper reflector RH	1	\$68.20		X
11	Rear bumper clip	10	\$40.00	✓	✓
12	Rear bumper side retainer LH	1	\$78.02		X
13	Rear bumper side retainer RH	1	\$78.02		X
14	Tail door	1	\$1,276.30	✓	✓
15	Tail door lock	1	\$478.30	✓	✓
16	Tail door emblem	1	\$69.74	✓	✓
17	Wording "hybrid synergy drive"	1	\$48.37	✓	✓
18	Tail door reflector LH	1	\$195.60		X
19	Tail door reflector RH	1	\$195.60		X
20	Tail door trim	1	\$167.80		X
21	Tail door trim clip	10	\$40.00		X
22	Tail end panel	1	\$678.40	✓	✓
23	Tail end panel garnish	1	183.41	✓	✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

24037-24
240 (S.N)

Spare Parts

Vehicle No. :

EA 9817 L

Submit By :

Carmen Lim

Make & Model :

TOYOTA SIENTA

Year Manufacture :

2018

Chassis No. :

NHP1707121803

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish clip <i>nn</i>	10	\$40.00		X
25	Boot weatherstrip <i>dis/nd</i>	1	\$397.60	✓	X
26	Tail lamp LH <i>Sn</i>	1	\$387.60		X
27	Tail lamp RH <i>Sn</i>	1	\$387.60		X
28	Reverse sensor cover LH <i>Ref</i>	1	\$35.40	✓	✓
29	Reverse camera <i>Sn</i>	1	\$650.00	S.N	X
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

433

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

EA 9817 L

TOYOTA SIENTA

NHP1707121803

Submit By :

Year Manufacture :

Engine No. :

Cost / List

CARMEN LIM

2018

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	TAIL DOOR HANDLE PULL <i>Ref</i>	1	\$55.00		✓
2	TAIL DOOR KEY ANTENA <i>cm</i>	1	\$165.00		✓
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

270



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 256, 669536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : EA 9817 L Submit By : Carmen Lim
Make & Model : TOYOTA SIENTA Year of Manufacture : 2018

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,400.00	700
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	600
3	To check wiring	\$50.00	20
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
5	To remove & refit rear windscreen.	\$120.00	✓
6	To tuff coat.	\$180.00	60
7	To transfer boot mechanism to new boot	\$120.00	60
8	To conduct water leakage tests to ensure proper air and sealing	\$120.00	30

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.