

(08/11/13) wef

ASS. REC. BY:

REF: AXA

ASSIGNMENT

2023 Aug
COE: 2008

From:

Date:

27/8/18

Estimated Cost:

OD ☒ TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKT 6403X

at Workshop m/s

Lim Siang Chow

of

81K19 #01-01 Sin Ming Ind. Sec. A

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

Before 1pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

933K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKT6403X

Yr Regn:

2008 / Sep.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Sream

c.c

1799

Colour

172071

A/C: Insured / Std / NI / NA

Sp. Reading

white

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRN 68408. S204850

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

27/8/18

Survey held at

160 Sin Ming Dr #05-20

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

S + RS, SI

Photos

Others

TOTAL

Report Format :

Imp Sum / I.B.I: (\$