

LIM SIANG CHOW AUTO SERVICE

BLOCK 160 SIN MING DRIVE, SIN MING AUTOCITY
#05-20 SINGAPORE 575722 HP: 92712214

MS LE THI DUNG
FIN: G5246086M
BLK748 JURONG WEST STR 73
S640748

DRIVER: CHUA ENG SENG

IC: S7519209F

Accident date:

2/8/2018

Estimated repair cost for Vehicle :

SKT6403X

S/N	DESCRIPTION	U/PRICE	AMOUNT
1	REAR BOOT LID		\$ 1,259.00
1	REAR BOOT LID STREAM LOGO		\$ 36.00
1	REAR BOOT LID EMBLE LOGO		\$ 45.00
1	REAR BOOT LID INNER LOCK		\$ 220.00
1	REAR BOOT LID INNER TRIM BOARD		\$ 260.00
1	REAR BOOT LID CAMERA		\$ 620.00
1	REAR BOOT LID WINDSCREEN SEAL		\$ 150.00
1	REAR BOOT LID WINDSCREEN MOULDING TOP		\$ 86.00
2	REAR BOOT LID WINDSCREEN MOULDING SIDE	67	\$ 134.00
1	REAR BOOT LID NUMBER PLATE		\$ 50.00
2	REAR BOOT LID NUMBER PLATE LUMP	50	\$ 100.00
1	REAR BOOT LID NUMBER PLATE GARNISH		\$ 450.00
1	REAR BOOT LID LOWER COVER		\$ 650.00
10	REAR BOOT LID LOWER COVER CLIPS	5	\$ 50.00
2	REAR BOOT LID HINGES	68	\$ 136.00
2	REAR BOOT LID SHOCK ABSORBER	155	\$ 310.00
2	REAR BOOT LID REFLECTOR	600	\$ 1,200.00
1	REAR TAIL LAMP RH		\$ 420.00
2	REAR BUMPER SIDE MOULDING	85	\$ 170.00
1	REAR BUMPER		\$ 1,377.00
2	REAR BUMPER SIDE BRACKET	68	\$ 136.00
2	REAR BUMPER REINFORCEMENT BRACKET	65	\$ 130.00
1	REAR BUMPER REINFORCEMENT		\$ 270.00
1	REAR BUMPER BEAM		\$ 197.00
1	REAR BUMPER REVERSE SENSOR		\$ 300.00
8	REAR BUMPER CLIPS	4	\$ 40.00
1	REAR END PANEL		\$ 413.40
1	REAR END PANEL TOP GARNISH		\$ 220.00
1	REAR SPARE TIRE PANEL TOP COVER		\$ 429.70
2	REAR FENDER INNER TRIM BOARD	653	\$ 1,306.00
1	REAR EXHAUST		\$ 970.00
1	REAR EXHAUST CHOME PIPE		\$ 116.70
	TOTAL		\$ 12,251.80
	LABOUR AND MISC		
1	LABOUR CHARGE TO REMOVE REFIT		
	REAR CUSHION		
	EXHAUST		
	REVERSE SENSOR		\$ 880.00
2	SPRAY AND PANTING CHARGE		\$ 1,200.00
3	OTHER REMOVING PART		\$ 150.00
4	TOWING FEES		\$ 60.00
	SUBTOTAL		\$ 14,541.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ht ✓

nei ✓

nei ✓

ht ✓

7

x

x

nei ✓

nei ✓

nei ✓

x

x

x

x

x

x

x

Cray ✓

ht-x 12H-nei ✓

nei ✓

x

x

7

200 mm ✓

nei ✓

7

7

7

x

x

7

Cut ✓

700

700

60

7

office → 62563561

Tan Jiah 97495749

'wp'

27/8/18 @ 1230pm

Resurvey after repair

sure@lkkauto.com

6 days