

# 萬汽車服務

## MILLION AUTO SERVICE

No. 4 Penjuru Place #01-12, 2.8 Penjuru Tech Hub, Singapore 608782  
Website: <http://www.millionauto.com> Email: [wendy@millionauto.com](mailto:wendy@millionauto.com)  
Tel: 6567 0817, 6264 9091 Fax: 6791 4716  
Reg No: 317413/00-K GST Reg No: M90363176A

25-Aug-17

AXA Insurance Singapore Pte Ltd  
143 Cecil Street  
#01-01 GB Building  
Singapore 069542

Attention: Motor Claim Department

WITHOUT PREJUDICE

### ESTIMATE COST FOR REPAIR GBB2377R NISSAN CABSTAR - 2.0 (M)

|                                                                                               |                    |
|-----------------------------------------------------------------------------------------------|--------------------|
| Side mirror <i>round</i>                                                                      | 105.61 <i>mis</i>  |
| Side mirror arm                                                                               | 550.80 X           |
| Corner panel                                                                                  | 440.96 X           |
| Front head lamp LH                                                                            | 554.65 ?           |
| Front side lamp                                                                               | 213.80 X           |
| Front signal lamp                                                                             | 294.64 <i>Car</i>  |
| Fuso wording                                                                                  | 75.32 X            |
| Front grille                                                                                  | 1,102.08 <i>RY</i> |
| Front grille clips                                                                            | 28.00 X            |
| Front bumper centre                                                                           | 1,117.59 <i>bt</i> |
| Front bumper side LH                                                                          | 328.29 <i>ent</i>  |
| Front reinforcement                                                                           | 256.00 ?           |
| To dismantle & replace side lamp, head lamp, side mirror arm, bumper, grille & reinforcement. | 680.00 <i>300</i>  |
| To spray paint front bumper, grille, side panel & dented parts                                | 550.00 <i>300</i>  |

Subtotal : 6,297.74  
GST 7% : 440.84  
Total : 6,738.58

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*office.*  
*Tanpin 97495749 / 62563561*  
*wp*  
*24/8/18 @ 3:15 pm.*  
*3 days*  
*Resurvey after repair*  
*surellkkauto.com*