

Print Received Message

This mail is associated with :

***SLR7996T (C0474239)**

[SHD328P]

TP

GOH HOCK WAH

Aug 17 2018 10:00AM

[TRANS-CAB SERVICES PTE LTD]

Zoom Autowerks Pte Ltd - Bedok

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 21/11/2018 17:42 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$19500.00) - SLR7996T - Claim Handler: Richard Ang

Approved:19500.00:Please propose global sum at \$19,500.

Hsiao Tong (LKKAUTO)

From: Zoom Autowerks <zoomautowerks@gmail.com>
Sent: Friday, 30 November 2018 9:42 AM
To: Hsiao Tong (LKKAUTO)
Subject: Re: Letter of Claim for SLR 7996 T *LKK REF: CC4/AXA18015308/Upa3

Dear Hsiao Tong,

We accept the offer, kindly send us DV.

Warmest Regards,
Elin Cai

Zoom Autowerks Pte Ltd
130 Bedok Reservoir Road
#08-1339 Singapore 470130
☎9450 7920
✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

On Fri, Nov 30, 2018 at 8:08 AM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

(save as to costs)

Hi Elin,

We refer to your below email.

Our principal had reviewed the matter and we have our instruction to maintain our offer at a global sum of **\$19,500.00(all-in).**

Kindly re-consider our offer.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zoom Autowerks <zoomautowerks@gmail.com>

Sent: Saturday, 24 November 2018 11:49 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: Letter of Claim for SLR 7996 T *LKK REF: CC4/AXA18015308/Upa3

Dear Hsiao Tong,

Kindly consider \$20,000(all-in) for a swift settlement.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

On Sat, Nov 24, 2018 at 8:05 AM Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

(save as to costs)

Hi Elin,

We refer to your below email.

Our principal had reviewed the matter and we have our instruction to improve our offer at a global sum of **\$19,500.00(all-in)**.

Please confirm settlement.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zoom Autowerks <zoomautowerks@gmail.com>

Sent: Friday, 23 November 2018 9:31 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: Letter of Claim for SLR 7996 T *LKK REF: CC4/AXA18015308/Upa3

Dear Hsiao Tong,

Kindly revert with offer, thank you.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

On Mon, Oct 8, 2018 at 7:02 PM Zoom Autowerks <zoomautowerks@gmail.com> wrote:

Dear Hsiao Tong,

Considering the accident was on 17/08/2018, and repair works was over 2 weekends, kindly accept our counter offer for a swift settlement.

1) Vehicle Repair Costs	\$17,600.00
2) Loss of Rental (SGD\$120.00 x 20Days)	\$2,400.00
3) LTA Search Fee	\$7.45
4) Towing Fee	\$120.00

Total : **\$20,127.45**

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

On Mon, Oct 8, 2018 at 2:37 PM Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

Hi Elin,

We refer to your below email.

We have our principal instruction to improve our offer at a global sum of **\$18,630.00(all-in).**

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zoom Autowerks <zoomautowerks@gmail.com>

Sent: Thursday, 4 October 2018 10:58 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: Letter of Claim for SLR 7996 T *LKK REF: CC4/AXA18015308/Upa3

Dear Hsiao Tong,

Decline offer.

Please consider our counter offer:

1) Vehicle Repair Costs	\$17,600.00
2) Loss of Rental (SGD\$140.00 x 24Days)	\$3,360.00
3) LTA Search Fee	\$7.45
4) Towing Fee	\$120.00

Total : **\$21,087.45**

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

09450 7920

zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

On Thu, Oct 4, 2018 at 9:40 AM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

Hi Elin,

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$18,000.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vivian Lau (LKKAUTO)

Sent: Monday, 17 September 2018 8:09 AM

To: zoomautowerks@gmail.com; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>

Subject: RE: Letter of Claim for SLR 7996 T

WITHOUT PREJUDICE

Dear Elin,

Thank you for the email.

Dear Hsiao Tong,

Kindly assist CC4/AXA18015308/Upa3

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zoom Autowerks [<mailto:zoomautowerks@gmail.com>]
Sent: Saturday, 15 September, 2018 1:13 AM
To: Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>
Subject: Letter of Claim for SLR 7996 T

Dear Vivian,

- Without Prejudice -

Enclosed please find Letter of Claim for your kind attention.

Look forward to your favorable reply.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2018		23 Aug 2018 09:14 Edit Adj Rpt	S\$17,600.00 Edit Estimates	S\$17,600.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Main Claimant:	GOH HOCK WAH, ID: S1595443D		
Vehicle Reg. No.:	SLR7996T	Date of Loss:	17/08/2018 10:00 - :59 [11 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0474239	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHD328P	Policy No. (Claimant):	D18MPC0000750
		Excess:	S\$5,000.00
Repairer:	Zoom Autowerks Pte Ltd (HQ) 130 Bedok Reservoir Road, Eunos Spring, #08-1339, 470130 Bedok - Tel: 94507920		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Richard Ang]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/09/2018]		
Driver/Custodian (Insured):	NG HOCK SOON (60 / Male), NRIC: S1279766D, Tel: +6588188926		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (21/11/2018): Alert - Adj Mandate Approved (S\$19500.00) - SLR7996T - Claim Handler: Richard An...
- AXA_SG (02/10/2018): Alert - Adj Mandate Approved (S\$18630.00) - SLR7996T - Claim Handler: Richard An...
- AXA_SG (23/08/2018): TP settlement - C0474239/P1680520

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLR7996T (C0474239)**
[SHD328P]
TP
GOH HOCK WAH
Aug 17 2018 10:00AM
[TRANS-CAB SERVICES PTE LTD]
Zoom Autowerks Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼
Letters/Correspondences					1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	
Documentation					1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	20/08/18 09:11	EMAIL		Load PDF	
2	20/08/18 09:11	SHD328P INS GIA		Load PDF	
3	20/08/18 09:11	SLR7996T TP GIA		Load PDF	
4	21/08/18 09:23	Email list of SJE to TP		Load PDF	
5	23/08/18 09:15	Email from TP - Marcus of LKK as SJE		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/09/18 08:47	LKK Survey Photos		Load PDF	
2	19/09/18 16:12	LKK Resurvey Photos 1		Load PDF	
3	19/09/18 16:12	LKK Resurvey Photos 2		Load PDF	
4	19/09/18 16:12	TP ESTIMATE_MARKED		Load PDF	
5	19/09/18 16:30	PARF_COE REBATE		Load PDF	
6	19/09/18 16:31	IA (with mandate) dd 190918		Load PDF	
7	10/01/19 10:50	AUTHORISATION TO ACT		Load PDF	
8	10/01/19 10:50	DISCHARGE VOUCHER		Load PDF	
9	10/01/19 10:50	LETTER TO OI		Load PDF	
10	10/01/19 10:50	LOD		Load PDF	
11	10/01/19 10:50	LTA SEARCH		Load PDF	
12	10/01/19 10:50	RENTAL RECEIPT		Load PDF	
13	10/01/19 10:50	TOWING FEE		Load PDF	
14	10/01/19 10:50	WORKSHOP INVOICE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHD328P (Insd veh)	Model:	HONDA FREED 1.5 G (A)
	SLR7996T (TP veh)		
Date of Accident:	17/08/2018		

Global Sum Settlement	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No
Repair Estimate	: \$	34,474.88
Final Repair Cost	: \$	17,600.00
Loss of Use	: \$	days at \$0.00 per day
Rental (if any)	: \$	2,000.00 20 days
LTA / GIA Search Fee	: \$	7.45
Towing Fee:	: \$	120.00
	: \$	
Final Settlement Sum (GLOBAL SUM)	: \$	19,500.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> [] YES <input checked="" type="checkbox"/> [X] NO (Kindly indicate below)		
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability _____ 100 _____ (%)		
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks _____		

Payment Instruction: Payee's Breakdown		
1)	Zoom Autowerks Pte Ltd	: \$ 19,500.00
2)		: \$
3)		: \$
4)		: \$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

10 Jan
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18015308/UPA3S2
Date: 10/01/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1680520
Claimant Vehicle No: SLR7996T Insured Vehicle No: SHD328P
Date of Loss: 17/08/2018 Nature of Claim: TP Claim No: C0474239

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR7996T
Make & Model: HONDA FREED, 1.5 G (A) Engine No: LEB5560453
Reg. Date: 29/08/2017 (Man. Year: 2017) Chassis No: GB71033631
Colour: White Odometer: 20975 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15
Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,864.88	18,377.84	9,487.04	34.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,610.00	3,630.00	2,980.00	45.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,474.88	22,007.84	12,467.04	36.16
Approved Total (Overridden) (S\$)		17,600.00		
Nett Amount (S\$)	34,474.88	17,600.00	16,874.88	48.95
+ Car Rental (20.0 x S\$100.00/day) (S\$)		2,000.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		19,727.45		
Global Sum Settlement (S\$)		19,500.00		

INSPECTION

Date of Assignment: 23/08/2018
Date Inspected: 23/08/2018 Inspected At: Zoom Autowerks Pte Ltd (HQ)
Estimated Period of Repair: 14.0 days 130 Bedok Reservoir Road, Eunus Spring, #08-1339
Singapore 470130

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2019)
Parts:	M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR7996T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (CONSISTENT)	Repair	720.80 FL	*- FL
2	1		*FRONT BONNET HINGE (CONSISTENT)	Repair	45.60 FL	*- FL
3	1		*FRONT HEADLAMP O/S (CONSISTENT)	Cracked	1,980.40 FL	*1,980.40 FL
4	1		*FRONT BUMPER (CONSISTENT)	Distorted	1,050.40 FL	*1,050.40 FL
5	1		*SET FRONT BUMPER CLIP (CONSISTENT)	Necessary	55.00 FL	*55.00 FL
6	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Not Necessary	295.40 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER (CONSISTENT)	Bent	29.50 FL	*29.50 FL
8	1		*FRONT BUMPER TOW HOOK COVER (CONSISTENT)	Not Necessary	25.40 FL	*- FL
9	1		*FRONT FENDER O/S (CONSISTENT)	Distorted	440.60 FL	*440.60 FL
10	1		*FRONT FENDER INNER SHIELD (CONSISTENT)	Torn	120.80 FL	*120.80 FL
11	1		*SET FRONT FENDER INNER SHIELD CLIP (CONSISTENT)	Necessary	55.00 FL	*55.00 FL
12	1		*FRONT FENDER HYBRID EMBLEM (CONSISTENT)	Necessary	80.10 FL	*80.10 FL
13	1		*FRONT WHEEL HUB (CONSISTENT)	Bent	200.40 FL	*200.40 FL
14	1		*FRONT WHEEL BEARING (CONSISTENT)	Necessary	186.40 FL	*186.40 FL
15	1		*FRONT SHOCK ABSORBER (CONSISTENT)	Bent	420.80 FL	*325.00 FL
16	1		*FRONT KNUCKLE ARM (CONSISTENT)	Bent	350.80 FL	*350.80 FL
17	1		*FRONT LOWER ARM (CONSISTENT)	Bent	300.30 FL	*300.30 FL
18	1		*FRONT TIE ROD (CONSISTENT)	Twisted	89.60 FL	*89.60 FL
19	1		*POWER STEERING RACK (CONSISTENT)	Bent / Jammed	1,480.20 FL	*1,480.20 FL
20	1		*POWER STEERING RACK CROSS MEMBER (CONSISTENT)	Dented / Twisted	990.60 FL	*990.60 FL
21	1		*FRONT DRIVESHAFT (CONSISTENT)	Not Necessary	1,350.20 FL	*- FL
22	1		*FRONT DOOR - R/H (CONSISTENT)	Badly Dented	1,725.90 FL	*1,120.00 FL
23	1		*FRONT DOOR CHECKER (CONSISTENT)	Twisted	950.80 FL	*141.00 FL
24	1		*FRONT DOOR GLASS OUTER MOULDING (CONSISTENT)	Not Necessary	75.60 FL	*- FL
25	1		*FRONT DOOR HINGES (CONSISTENT)	Lower Bent	91.60 FL	*45.00 FL
26	1		*FRONT DOOR INNER BOARD (CONSISTENT)	Deformed / Cracked	780.20 FL	*780.20 FL
27	1		*FRONT DOOR LOCK (CONSISTENT)	Not Necessary	262.80 FL	*- FL
28	1		*FRONT DOOR OUTER HANDLE (CONSISTENT)	Not Necessary	342.80 FL	*- FL
29	1		*FRONT DOOR REGULATOR (CONSISTENT)	Bent	364.50 FL	*364.50 FL
30	1		*FRONT DOOR REGULATOR MOTOR (CONSISTENT)	Shorted	355.80 FL	*355.80 FL
31	1		*FRONT DOOR RUBBER (CONSISTENT)	Necessary	110.80 FL	*110.80 FL
32	1		*FRONT DOOR SIDE MIRROR (CONSISTENT)	Cut	674.50 FL	*520.00 FL
33	1		*FRONT DOOR BLACK TAPE (CONSISTENT)	Necessary	56.90 FL	*56.90 FL
34	1		*FRONT DOOR OUTER PILLAR (CONSISTENT)	Badly Dented	1,150.20 FL	*866.00 FL
35	1		*FRONT DOOR PILLAR INNER GARNISH (CONSISTENT)	Not Necessary	129.80 FL	*- FL
36	1		*CENTRE PILLAR (CONSISTENT)	Repair	1,400.30 FL	*- FL
37	1		*ROCKER PANEL (CONSISTENT)	Badly Dented	289.40 FL	*289.40 FL
38	1		*FRONT DASHBOARD (CONSISTENT)	Burst	854.20 FL	*854.20 FL
39	1		*STEERING AIR BAG (CONSISTENT)	Activated	2,480.60 FL	*2,165.00 FL
40	1		*FRONT PASSENGER AIR BAG (CONSISTENT)	Activated	3,012.40 FL	*2,880.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	2		*FRONT SAFETY BELTS (CONSISTENT)	Activated	1,196.80 FL	*1,196.80 FL
42	1		*AIG BAG CONTROL UNIT (CONSISTENT)	Activated	981.40 FL	*981.40 FL
43	1		*AIR BAG CLOCK SENSOR (CONSISTENT)	Activated	278.80 FL	*278.80 FL
44	1		*REAR SLIDING DOOR (CONSISTENT)	Dented / Bent	1,105.80 FL	*1,105.80 FL
45	1		*REAR SLIDING DOOR INNER BOARD (CONSISTENT)	Not Necessary	672.40 FL	*- FL
46	1		*REAR SLIDING DOOR OUTER HANDLE (CONSISTENT)	Not Necessary	74.90 FL	*- FL
47	1		*REAR SLIDING DOOR LOWER ROLLER (CONSISTENT)	Not Necessary	155.00 FL	*- FL
48	1		*REAR SLIDING DOOR CENTRE ROLLER (CONSISTENT)	Not Necessary	160.00 FL	*- FL
49	1		*REAR SLIDING DOOR REGULATOR (CONSISTENT)	Not Necessary	389.40 FL	*- FL
50	1		*REAR SLIDING DOOR REGULATOR MOTOR (CONSISTENT)	Not Necessary	355.80 FL	*- FL
51	1		*REAR SLIDING DOOR RUBBER (CONSISTENT)	Cut	129.80 FL	*129.80 FL
52	1		*REAR SLIDING DOOR BLACK TAPE (CONSISTENT)	Necessary	45.80 FL	*45.80 FL
53	1		*REAR WHEEL HUB WITH BEARING (CONSISTENT)	Not Necessary	321.40 FL	*- FL
54	1		*REAR SHOCK ABSORBER (CONSISTENT)	Not Necessary	336.40 FL	*- FL
55	1		*FRONT TYRE (LOCAL PURCHASE) (@ \$200.00 DISC 80%) (CONSISTENT)	Cut	450.00 FS	*160.00 FS
56	1		*FRONT SPORT RIM (CONSISTENT)	Dented / Bent	850.00 FS	*300.00 FS
57	1		*REAR TYRE (CONSISTENT)	Serviceable	450.00 FS	*- FS
58	1		*REAR SPORT RIM (CONSISTENT)	Cut	850.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **34,181.10** **22,782.30**
 - List Item Discount on L Items 20.00/20.00% (\$\$) 6,316.22 4,404.46

Total Parts (\$\$) 27,864.88 18,377.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING.	New	80.00	30.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.	New	450.00	300.00
3	TO REMOVE AND REFIT REAR UNDERCARRIAGE.	New	350.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT.	New	180.00	60.00
5	TO REMOVE, REPLACE DOOR DAMAGED PARTS AND TRANSFER ALL FITTINGS.	New	400.00	120.00
6	TO APPLY UNDERCOATING.	New	250.00	120.00
7	PANEL BEATING.	New	2,500.00	1,400.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.	New	2,400.00	1,600.00
Gross Labour Cost (S\$)			6,610.00	3,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >