



ZOOM AUTOWERKS PTE LTD

832 Sims Avenue, Eunosville

#12-884 Singapore 400832

Tel: 9450 7920

* zoomautowerks@gmail.com

D.O.A: 17 AUGUST 2018

20 AUGUST 2018

OWNER: GOH HOCK WAH

REG NO.: SLR 7996 T

MAKE/MODEL: HONDA FREED

Not Authorized
2 hrs
1/5 @ 17.600
1407.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front bonnet	\$ 2 720.80 X
1	Front bonnet hinge	\$ 2 45.60 X
1	Front headlamp 0/3	\$ 2 1,980.40 ✓
1	Front bumper	\$ 1.5 1,050.40 ✓
1	Front bumper clip (1 set)	\$ 2 55.00 ✓
1	Front bumper reinforcement	\$ 1.1 295.40 X
1	Front bumper side retainer	\$ 2 29.50 ✓
1	Front bumper tow hook cover	\$ 1.1 25.40 X
1	Front fender 0/5	\$ 1.5 440.60 ✓
1	Front fender inner shield	\$ 10 120.80 ✓
1	Front fender inner shield clip (1 set)	\$ 2 55.00 ✓
1	Front fender "HYBRID" emblem	\$ 2 80.10 ✓
1	Front wheel hub	\$ 2 200.40 ✓
1	Front wheel bearing	\$ 2 186.40 ✓
1	Front shock absorber 3 2.5	\$ 2 420.80 ✓
1	Front knuckle arm	\$ 2 350.80 ✓
1	Front lower arm	\$ 2 300.30 ✓
1	Front tie rod	\$ 2 89.60 ✓
1	Power steering rack	ref \$ 1,480.20 ✓
1	Power steering rack cross member	\$ 2 990.60 ✓
1	Front drive shaft	\$ 1.1 1,350.20 X
1	Front door - R/H 1120	\$ 1.5 1,725.90 ✓
1	Front door checker 141.20	\$ 2 950.80 ✓
1	Front door glass outer moulding	\$ 1.1 75.60 X
2	Front door hinges 45	lower \$ 2 91.60 1PC
1	Front door inner board	\$ 2 780.20 ✓
1	Front door lock	\$ 1 262.80 X
1	Front door outer handle	\$ 1 342.80 X
1	Front door regulator	\$ 2 364.50 ✓
1	Front door regulator motor	\$ 2 355.80 ✓
1	Front door rubber	\$ 2 110.80 ✓
1	Front door side mirror 520	\$ 2 674.50 ✓
1	Front door black tape	\$ 2 56.90 ✓
1	Front door outer pillar 866.	\$ 1.5 1,150.20 ✓
1	Front door pillar inner garnish	\$ 1 129.80 X
		\$ 17,340.50

c/f:

\$ 17,340.50

LIST ITEMS

1	Centre pillar
1	Rocker panel
1	Front dashboard
1	Steering air bag 2165.00
1	Front passenger air bag 2880
2	Front safety belts
1	Air bag control unit
1	Air bag clock sensor
1	Rear sliding door
1	Rear sliding door inner board
1	Rear sliding door outer handle
1	Rear sliding door lower roller
1	Rear sliding door centre roller
1	Rear sliding door regulator
1	Rear sliding door regulator motor
1	Rear sliding door rubber
1	Rear sliding door black tape
1	Rear wheel hub with bearing
1	Rear shock absorber

Less 20%

\$ R	1,400.30	X
\$ R	289.40	✓
\$ BUS	854.20	✓
\$ Actual	2,480.60	✓
\$ Actual	3,012.40	✓
\$ Actual	1,196.80	✓
\$ Actual	981.40	✓
\$ Actual	278.80	✓
00/ \$ bel	1,105.80	✓
\$ 11	672.40	X
\$ 11	74.90	X
\$ 11	155.00	X
\$ 11	160.00	X
\$ 11	389.40	X
\$ 11	355.80	X
\$ 117	129.80	✓
\$ 11	45.80	✓
\$ 11	321.40	X
\$ 11	336.40	X
\$	31,581.10	
\$	6,316.22	
\$	25,264.88	

SPECIAL NETT ITEMS

1	Front tyre LP 200
1	Front sport rim
1	Rear tyre
1	Rear sport rim

\$ 117	450.00	80%
\$ 117	850.00	300
\$ 11	450.00	X
\$ 117	850.00	300
\$	2,600.00	

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.
2	To remove and refit front undercarriage.
3	To remove and refit rear undercarriage.
4	To conduct wheel alignment.
5	To remove, replace door damaged parts and transfer all fittings.
6	To apply undercoating.
7	Panel beating.
8	To re-spray painting on the affected areas.

\$	80.00	30
\$	450.00	300
\$ 11	350.00	X
\$	180.00	60
\$	400.00	120
\$	250.00	120
\$	2,500.00	1400
\$	2,400.00	1600
\$	6,610.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damage before/after resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be referred to the Repairer and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

22022-3
202
17617.84
S.N 760
1660-3630

\$ 34,474.88

Total 22007.84
202
17606.27