

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 68P**AAD1808-149***Not Authorised
11/8/18*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 68P

VF1ABL15AUC283195

RENAULT

LATITUDE

18.8.2018

III

PART		LIST	
1	BUMPER COVER FRT	\$	1,259.42
1	BUMPER SPOILER FRT	\$	181.75
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT RH	\$	150.77
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER UNDERTRAY FRT	\$	472.83
1	BUMPER GRILLE LOWER FRT	\$	266.80
1	BUMPER FOG LAMP GRILLE RH	\$	207.21
1	BUMPER BEAM FRT	\$	914.08
1	HEADLAMP RH	\$	1,184.43
1	HEADLAMP PANEL FRT RH	\$	152.15
1	HEADLAMP LH	\$	1,184.43
1	HEADLAMP PANEL FRT LH	\$	152.15
1	FENDER PANEL FRT RH	\$	783.83
1	WHEELARCH FRT RH	\$	278.84
1	FENDER BRACKET LOWER RH	\$	15.79
1	FENDER INSULATOR RH	\$	130.84
1	DOOR PANEL FRT RH	\$	2,844.66
1	RADIATOR GRILLE	\$	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36
1	RADIATOR GRILLE FRAME	\$	1,353.75
1	RADIATOR FAN COWLING	\$	820.54
1	RADIATOR FAN MOTOR LH	\$	967.36
1	RADIATOR FAN MOTOR RH	\$	1,479.46
1	FRAME FULL SUPPORT PANEL	\$	615.90
1	FRAME FULL SUPPORT BRACKET	\$	89.79
1	DOOR MIRROR ASSY RH	\$	1,483.40
1	DOOR PANEL FRT RH	\$	2,844.66
1	BONNET	\$	1,941.63
1	BONNET INSULATOR	\$	405.73

X

Trans-cab Auto Services Pte Ltd

AAD1808-149

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 68P

1	BONNET STRUT LH	\$	S _h 88.61	}	X
1	BONNET STRUT RH	\$	S _h 88.61		
1	BONNET HINGE LH	\$	h 348.31		
1	BONNET HINGE RH	\$	h 348.31		
1	BONNET LOCK	\$	h 305.48		
1	BONNET CABLE	\$	S _h 119.19		
1	BONNET CABLE COVER	\$	S _h 161.03		
1	BONNET SEAL OUTER	\$	S _h 92.36		
1	BONNET SEAL INNER	\$	S _h 157.28		
1	SUBFRAME OUTER FRT	\$	h 2,652.45		
1	SUBFRAME BRACKET OUTER LH	\$	h 92.36		
1	SUBFRAME BRACKET OUTER RH	\$	h 92.36		
1	ENGINE UNDERTRAY	\$	S _h 564.98		
1	A/C CONDENSER	\$	S _h 2,020.37		
1	A/C CONDENSER GARNISH LH UPPER	\$	S _h 39.67		
1	A/C CONDENSER GARNISH RH UPPER	\$	S _h 39.67		
1	A/C CONDENSER GARNISH LH	\$	S _h 58.81		
1	A/C CONDENSER GARNISH RH	\$	S _h 59.60		
1	LOWER ARM RH	\$	S _h 685.76		
1	KUNCKLE ARM RH	\$	S _h 846.98		
1	ABSORBER FRT RH	\$	S _h 360.54		
1	STABILIZER BAR FRT	\$	S _h 604.65		
1	DRIVESHAFT RH	\$	h 1,747.45		
1	WIPER RESERVOIR	\$	S _h 348.25		
1	WIPER RESERVOIR NECK	\$	S _h 136.11		
1	WIPER RESERVOIR MOTOR	\$	S _h 270.06		

TOTAL	\$	36,963.11
10%	\$	3,696.31
	\$	33,266.80

Specical Nett

1SET	BUMPER CLIP FRT	\$	an 66.00	}	X
1	BUMPER BRACKET CLIP FRT RH	\$	an 12.00		
1	BUMPER SUPPORT CLIP FRT RH	\$	an 10.50		
1SET	BUMPER GRILLE LOWER CLIP	\$	an 69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	an 70.00		

Trans-cab Auto Services Pte Ltd

AAD1808-149

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 68P

2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	} X
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
1SET	WHEELARCH CLIP FRT RH	\$	30.50	
6	BONNET INSULATOR CLIP L70Y	\$	7.30	
2	BONNET STRUT L70Y	\$	88.61	
2	BONNET CABLE CLIP L70Y	\$	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	10.85	
1	WINDSCREEN SEALANT	\$	253.80	
1	FRONT WINDSCREEN MOULDING	\$	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	100.00	
1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	80.00	
1	FRONT RIGHT DOOR STICKER '6555-3333'	\$	50.00	
1	FRONT RIGHT TYRE	\$	330.00	} X
1	FRONT RIGHT TYRE RIM	\$	380.00	

TOTAL	\$	1,734.88
--------------	-----------	-----------------

TOTAL PARTS	\$	35,001.68
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	3000
Putty and spray painting of the affected portion.	\$	4,000.00	6600
To rust-proofing of the affected areas.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X

Trans-cab Auto Services Pte Ltd

AAD1808-149

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 68P

To Check Electrical Lighting Concerned.	\$	170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	X
To transfer of front windscreen fittings and conduct water seepage test	\$	170.00	X

TOTAL	\$	11,090.00
--------------	-----------	------------------

Over All Total	\$	46,091.68
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~15 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: