

SJR 19408 TOYOTA VIOS

MR053HY9305116007

Rear boot	\$695 ✓	665.	Buckled
Rear boot centre logo	\$50.80 ✓		New
Rear boot "VIOS" emblem	\$52 ✓		New
Rear boot "G" emblem	\$45 ✓		New
Rear boot lock	\$135 ✓		Damaged
Rear boot inn rubber	\$213.20 ✓		Lt.
Rear bumper	\$538 ✓	459.	Dishbed
2pc Rear bumper retainers	\$102.30 × 2 = 204.60 ✓		new
12pc Rear bumper clips	\$5 × 12 = 60.30 ✓		new
2pc Rear bumper bracket	\$86.10 × 2 = 172.20 ×		new
3pc Rear bumper reflector	\$145.80 × 2 = 291.60 ✓		ould
2pc Rear tail lamp	\$330 × 2 = 660 ✓		ould
3pc Rear tail lamp panel	\$185 × 2 = 370 ×		Repair
Rear end panel	\$675 ✓		Dented
Rear end panel top garnish	\$265 ✓		returned 213.50.
6pc Rear end panel top garnish clips	\$5 × 6 = 30		10. New
Rear spare tyre board cover	\$165 ✓		torn
Rear spare tyre tools sponge centre	\$203.50 ×		new
Rear spare tyre tools sponge LH	\$192 ✓		returned
Rear LH fender	\$930 ×		Repair
Rear windscreen moulding	\$146.50 ×		new

Reverse Sensor ~~\$250~~ 200 Damaged.

Rear windscreen gum \$60 X

To check wiring ~~\$50~~ 30

To remove and refix rear windscreen ~~\$120~~ X

To remove and refix rear ~~boot~~ upholstery to facilitate repair ~~\$150~~ 60.

Cavity protection on all affected areas ~~\$150~~ 50

To replace reverse sensor ~~\$100~~ 50

To cut, weld, straighten and realign all affected parts ~~\$1500~~ 800

To spray paint on all affected areas ~~\$1500~~ 800.

List: 4061.70

Labour 1790

and 25%: 3046.27.

total: 5036.27.

S.N: 200

L/S: 4K.

06 Days.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: