




SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	S8M00QB1
Reference	CS/ASM18015321/Nsd3e2 
Loss Date	28 July 2018
Request Date	26 September 2018
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated workshop survey

Actions

Next Step

Wait for: Approve invoice

[Add Invoice](#)

Vehicle Information

Incident Vehicle SKP3053M
Registration #

Make HONDA ODYSSEY

Model 2.4 EXV-S 14YM (EURO 4)

Service Address

51 Ubi Avenue 1 #01-25 Paya Ubi, , 408933

Primary Contact/Insured

HSU SHIH-FAN STEPHEN
35 JURONG EAST AVE 1, #13-01, 609774,
Singapore
96611228
drstephenhsu@gmail.com

Claim Handler

Additional Instructions

Wkshop: Kah Motor Excess: \$300 To survey WP due to large estimate.

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Add

REFERENCE #	DESCRIPTION	TOTAL AMOUNT	SUBMITTED	STATUS	PAID DATE	WITHDRAW
AC1812118	Final Invoice	\$267.50	26/11/18 12:15 PM	Waiting for Approval		<div></div>

Totals

Outstanding Invoices	\$267.50	Rejected and Withdrawn	\$0.00
Payments Made	\$0.00		
Total	\$267.50		