

ASS. REC. BY:

REF: as/fce/18015350/Krd3ct

Special Instruction:

Surveyor: Kemeth
ews

ASSIGNMENT (Office)

From (Person): May Chuen

of PEI

Date/Time: 23/8/18 @ 8:28am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJ06444E

Insured: SHC 8180A

at Workshop m/s Lei Huet (Meng Kee)

Tel: 6453 8110

of Blk 213 8th Ming Ind. Est # 0156/58

Policy No:

Claim No: D18006196MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 16/08/2018

CA / REV / REP. / REV 24 HRS Cap

H.O.D. Endorsement:

Date/Time: 10:23am 23/8/18

Person Contacted: Debra

Vehicle IN (OUT)

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<u>SJ06444E-CC7/AIG/2008182/Km/b3g D.O.A: 25/4/12</u>
	<u>SHC8180A-NS/INC/5020580/M/1+bc2 D.O.A: 30/11/15</u>

ASS. REC. BY:

REF: FCZ /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s L1 Ink

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 872/c

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: STQ 6444E Yr Regn: 05, 0P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: hit canon Gux.c 1584

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 1996P2 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSTC S3A 9400 5324

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm

Rear R/Bal. 7 mm

L/Bal. 6 mm

D.O.A. 16/8/18 D.O.I. 27/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
28/8	File pass to Catherine
17/10/18	Kenneth continued LR 28007 with Jenny. (Red 869.66, 28%)
	MV: \$12K, LTA: \$7,816.00, NV: \$4184

RECEIVED 22 OCT 2018

Date/Time, File Pass to? : Prell. Report : Final Report

Date/Time, File Return to?

1) _____

Report Format: TP

Lump Sum / I.B.I: (\$) 28007

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S - RS - SI _____

Photos _____

Others _____

130
50
50450
22
TOTAL 302



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18015350/Krd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-08-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8180A	Veh. Inspected	SJQ 6444E
Policy No.		Coverage (\$)	0.00
Claim No.	D18006196MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	23/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/08/2018	Inspection Date	27/08/2018
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

MOTOR SURVEY ASSIGNMENT

Date	17-08-2018	Our Ref No. D18006196MFSH
Accident Date	16-08-2018	Claim Type. Third Party
Insured Vehicle	SHC8180A	Third Party Vehicle. SJQ6444E
Survey Location	SECTOR A, BLK 21, SIN MING INDUSTRIAL ESTATE#01-56/58/60	
Contact Person.	JENNY LIM	
Contact No.	6453 8110/ 0	Fax No. 6459 6267
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LAI HUAT (MENG KEE) MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0252F

Vehicle Details

Vehicle No.: SJQ6444E

Vehicle to be Exported: No

Intended De-registration Date: 16 Aug 2018

Vehicle Make: MITSUBISHI

Vehicle Model: LANCER 1.6 CVT SPORTS GLX AIRBAG
2WD 4DR

Primary Colour: White

Manufacturing Year: 2009

Engine No.: 4G18KB9537

Chassis No.: JMYSTCS3A9U005324

Maximum Power Output: 79.0 kW (105 bhp)

Open Market Value: \$14,558.00

Original Registration Date: 20 May 2009

First Registration Date: 20 May 2009

Transfer Count: 0

Actual ARF Paid: \$14,558.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 May 2019

PARF Rebate Amount: \$7,279.00

Intended COE Rebate Details

COE Expiry Date: 19 May 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$7,090.00

COE Rebate Amount: \$537.00

Total Rebate Amount: \$7,816.00

The information contained herein is correct as at 16 Aug 2018

OK

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SHC8180A	16 Aug 2018 / 11:10:00	Successful	F03	MS FIRST CAPITAL INSURANCE LIMITED

[Previous](#)

[OK](#)



Thank you

Lai Mei Ling Deborah has successfully logged out.
Your last login date and time was 16 Aug 2018, 14:17:40.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)
1	Vehicle	SHC8180A	-	18.32 Insurance Enquiry (GIRO Payment)	7.49
• Log Date/Time 16 Aug 2018 / 14:20:27					

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8010252F



Name
TOH YEW KWANG
(ZHUO YOUGUANG)
卓猷光
Race
CHINESE
Date of birth Sex
10-04-1980 M
Country of birth
SINGAPORE

S8010252F

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8010252F
Name:
TOH YEW KWANG
(ZHUO YOUGUANG)
Birth Date: 10 Apr 1980
Issue Date: 09 Dec 2008



4559200



NRIC No. S8010252F

Date of issue
13-04-2010

Address
APT BLK 357 ADMIRALTY DRIVE
#03-178
SINGAPORE 750357

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 09 Dec 2008



NP 428A



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Toh Yew Kwang (Zhuo YouGuang)
Period of Insurance : 20 May 2018 To 19 May 2019
Engine No. : 4G18KB9537
Chassis No. : JMYSTCS3A9U005324

Vehicle No. : SJQ6444E
Policy No. : 2100138763-09
Endorsement No. : 000000000198931
Issued Date : 07 May 2018

ABOUT THE COVER

Make/Model : MITSUBISHI LANCER 1.6 GLX S
Engine Capacity/Tonnage : 1,584.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2009
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Toh Yew Kwang (Zhuo YouGuang) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 5200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0160002000

KHOR BOON KEE
 66 SENGKANG SQUARE #10-36 LA FIESTA
 SINGAPORE 544703

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSPJSG

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/08/2018 14:26
Date Of Accident	16/08/2018 11:10
Exact Location Of Accident	SLIP RD FROM CTE INTO ANG MO KIO AVENUE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ6444E
Insured/Policyholder	
Name Of Registered Owner	TOH YEW KWANG (ZHUO YOUGUANG)
NRIC No	S8010252F
Email Address	INITIAL80@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96776161
Alternative Phone No	OTHERS-96776161

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER 1.6 GLX S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100138763-09
Cover Note Number	

Driver

Name of Driver	TOH YEW KWANG (ZHUO YOUGUANG)
NRIC No	S8010252F
Date Of Birth	10/04/1980
Occupation	INDOOR
Date Of Driving Pass	09/12/2008
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96776161
Fax Number	
Contact Number	OTHERS-96776161
EEmail Address	INITIAL80@HOTMAIL.COM

Address	BLK 357 ADMIRALTY DRIVE #03-178
Postcode	750357
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I (Toh Yew Kwang, S8010252F) was driving my vehicle (SJQ 6444E), white Mitsubishi GLX sedan from CTE (towards AYE) onto slip road towards Ang Mo Kio Ave 3 on 16/8/2018 1110 hours. As I stopped on the slip road exit to look out for cars along Ang Mo Kio Ave 3, a Comfort Delgro taxi (SHC 8180A) blue Hyundai Sedan driven by Mr Ching Chang Chye (S6909260H) rear ended onto my vehicle. This accident happened before lamp post 113 along Ang Mo Kio Ave 3. Both mr Ching and I got off our vehicles and Mr Ching asked me to report the accident and I agreed. We took photos of both vehicles' damage status and exchanged particulars.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8180A
Vehicle Make/Model/Colour	HYUNDAI/BLUE
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	CHING CHANG CHYE
NRIC/Passport Number	S6909260H
Contact Number	81330546
Address	
Postcode	
Insurance Company Name	MS FIRST CAPITAL INSURANCE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 160818 1353hr

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: Deborah Lai
 NRIC/FIN No.: S7332811Z

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I (Toh Yew Kwang, S8010252F) was driving my vehicle (SJQ 6444E, white Mitsubishi GTX sedan), exiting from CTE (towards AYE) onto slip road towards Ang Mo Kio Ave 3, on 16 August 2018, 1110 hrs. As I stopped on the slip road exit to look out for cars along Ang Mo Kio Ave 3, a Comfort Velo taxi (SHC 8180A, Blue Hyundai Sedan) driven by Mr Chimy Chay Chye (S6909260H) rear-ended onto my ~~vehicle~~ vehicle. This accident happened before lamp post 113 along Ang Mo Kio Ave 3.

Both Mr Chimy and I got off our vehicles and Mr Chimy asked me to report the accident and I agreed. We took photos of ~~the~~ both vehicles' damage status and exchanged particulars.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 16/8/18 1400 hrs.

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: Deborah Lai
 NRIC/FIN No.: S7332811Z

Kr

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0020067
Toh Yew Kwang (Zhou Youguang)

Page 1 of 2
Your ref TP-SHC 8180A MS FC
Job No 69751
Our ref 18.08.22
Payment
Date 21/8/2018

Attn

Vehicle No: SJQ 6444E
Vehicle Model .: Mitsubishi Lancer
Accident on ...: 16/8/2018

*NOT Authorized
11 Sep @ 2nd side ✓ ok
Resurvey After Pain (today)*

Quantity	Unit	Description	Unit price	Disc pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear bumper	689.00	10.00	<i>Pr</i> 620.10
1.00	Pc	Rear bumper side beam LH	50.00	10.00	<i>Dii</i> 45.00
1.00	Pc	Rear bumper side beam RH	50.00	10.00	<i>Dii</i> 45.00
1.00	Pc	Rear bumper centre beam PHOTO	<i>Pr</i> 209.00	10.00	188.10
3.00	Pcs	Rear bumper lower clips	3.80	10.00	<i>Pr</i> 10.26
1.00	Pc	Rear tail lamp LH	<i>MJM</i> 421.00	10.00	378.90
1.00	Pc	Rear tail lamp side clip, top LH	7.50	10.00	<i>Pr</i> 6.75
1.00	Pc	Rear tail lamp side clip, top RH	7.50	10.00	<i>Pr</i> 6.75
1.00	Pc	Rear tail lamp side clip, lower LH	7.50	10.00	<i>Pr</i> 6.75
1.00	Pc	Rear tail lamp side clip, lower RH	7.50	10.00	<i>Pr</i> 6.75
1.00	Pc	Rear Lancer emblem	38.00	10.00	<i>Pr</i> 34.20
1.00	Pc	Rear logo emblem	55.00	10.00	<i>Pr</i> 49.50
1.00	Pc	Rear GLX emblem	29.00	10.00	<i>Pr</i> 26.10
Special nett item.					1424.16
1.00	Set	Rear reversing sensor with installation	200.00		<i>CM</i> 200.00 ✓
					200

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和快捷修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



来發 (明记) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
 RCB No: 199407592C

ESTIMATE

EST. No EST0020067
 Toh Yew Kwang (Zhou Youguang)

Page 2 of 2
 Your ref. TP-SHC 8180A MS FC
 Job No 69751
 Our ref 18.08.22
 Payment
 Date 21/8/2018

Attn

Vehicle No SJQ 6444E
 Vehicle Model : Mitsubishi Lancer
 Accident on ... 16/8/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Labour & Misc.			
1.00		To straighten rear body including cutting and welding, to knock dents on rear luggage panel, rear fender LH & RH, rear boot lid and renew of parts	700.00		700.00 <i>650</i>
1.00		To spray paint	900.00		900.00 <i>800</i>
					1450

Sub-Total	3,224.16
GST 7.00%	225.69
Total	S\$ 3,449.85

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。
 "Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0020067
Toh Yew Kwang (Zhou Youguang)

Page 1 of 2
Your ref TP-SHC 8180A MS FC
Job No 69751
Our ref 18.08.22
Payment
Date 21/8/2018

Attn

Vehicle No SJQ 6444E
Vehicle Model Mitsubishi Lancer
Accident on 16/8/2018

NOT Authorized
L1 Lp @?
Resurvey After Paint
6 days

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear bumper	689.00	10.00	620.10 <i>Am</i>
1.00	Pc	Rear bumper side beam LH	50.00	10.00	45.00 <i>DiY</i>
1.00	Pc	Rear bumper side beam RH	50.00	10.00	45.00 <i>DiY</i>
1.00	Pc	Rear bumper centre beam	209.00	10.00	188.10 <i>Buc</i>
3.00	Pcs	Rear bumper lower clips	3.80	10.00	10.26 <i>Me</i>
1.00	Pc	Rear tail lamp LH	421.00 <i>Mg/Mz</i>	10.00	378.90
1.00	Pc	Rear tail lamp side clip, top LH	7.50	10.00	6.75 <i>Me</i>
1.00	Pc	Rear tail lamp side clip, top RH	7.50	10.00	6.75 <i>Me</i>
1.00	Pc	Rear tail lamp side clip, lower LH	7.50	10.00	6.75 <i>Me</i>
1.00	Pc	Rear tail lamp side clip, lower RH	7.50	10.00	6.75 <i>Me</i>
1.00	Pc	Rear Lancer emblem	38.00	10.00	34.20 <i>Me</i>
1.00	Pc	Rear logo emblem	55.00	10.00	49.50 <i>Me</i>
1.00	Pc	Rear GLX emblem	29.00	10.00	26.10 <i>Me</i>
Special nett item:					
1.00	Set	Rear reversing sensor with installation	200.00		200.00 <i>CM</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的身车及给于快速与准确的测量方式和和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
 RCB No: 199407592C

ESTIMATE

EST. No EST0020067
 Toh Yew Kwang (Zhou Youguang)

Page 2 of 2
 Your ref. TP-SHC 8180A MS FC
 Job No. 69751
 Our ref. 18.08.22
 Payment
 Date 21/8/2018

Attn

Vehicle No SJQ 8444E
 Vehicle Model : Mitsubishi Lancer
 Accident on ... 16/8/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Labour & Misc.			<i>650</i>
1.00		To straighten rear body including cutting and welding, to knock dents on rear luggage panel, rear fender LH & RH, rear boot lid and renew of parts	700.00		700.00
					Buc <i>800</i>
1.00		To spray paint	900.00		900.00
Sub-Total					3,669.66
GST 7.00%					225.69
Total					S\$ 3,449.85

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
 "Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
 RCB No: 199407592C

ESTIMATE

SUPPLEMENTARY

EST. No EST0020067
 Toh Yew Kwang (Zhou Youguang)

Page: 1 of 1
 Your ref.: TP-SHC 8180A MS FC
 Job No.: 69751
 Our ref: 18.08.22
 Payment:
 Date: 29/8/2018

Attn

Vehicle No: SJQ 6444E
 Vehicle Model . Mitsubishi Lancer
 Accident on ..: 16/8/2018

Quantity	Unit	Description	Unit price	Disc. pct	Amount
		Supply of Parts - Nett item:			
		SUPPLEMENTARY ITEM.			
1.00	Pc	Rear end panel	495.00	10.00	<i>B</i> 445.50 ✓

Sub-Total 445.50
 GST 7.00% 31.19
 Total S\$ 476.69

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015350/Krd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-11-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8180A	Veh. Inspected	SJQ 6444E
Policy No.		Coverage (\$)	0.00
Claim No.	D18006196MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	23/08/2018
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI LANCER (A)	c.c	1584
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JMYSTCS3A9U005324	Colour	WHITE
Odometer	199692	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/60 R15	YOKOHAMA	7 mm
L/H Rear Tyre	195/60 R15	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/08/2018	Inspection Date	27/08/2018
Survey held at	BLK 21, SIN MING IND EST #01-56/58		
Repairer	LAI HUAT (MENG KEE) MOTOR PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 6444E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED	689.00	689.00
1	REAR BUMPER SIDE BEAM LH	DISTORTED	50.00	50.00
1	REAR BUMPER SIDE BEAM RH	DISTORTED	50.00	50.00
1	REAR BUMPER CENTRE BEAM	BUCKLED	209.00	209.00
3	REAR BUMPER LOWER CLIPS @\$3.80	NECESSARY	11.40	11.40
1	REAR TAIL LAMP LH	MTG CRACKED	421.00	421.00
1	REAR TAIL LAMP SIDE CLIP, TOP LH	NECESSARY	7.50	7.50
1	REAR TAIL LAMP SIDE CLIP, TOP RH	NECESSARY	7.50	7.50
1	REAR TAIL LAMP SIDE CLIP, LOWER LH	NECESSARY	7.50	7.50
1	REAR TAIL LAMP SIDE CLIP, LOWER RH	NECESSARY	7.50	7.50
1	REAR LANCER EMBLEM	NECESSARY	38.00	38.00
1	REAR LOGO EMBLEM	NECESSARY	55.00	55.00
1	REAR GLX EMBLEM	NECESSARY	29.00	29.00
1	REAR END PANEL (ADDITIONAL)	BENT	495.00	495.00
	LESS 10% DISCOUNT		-207.74	-207.74
			1,869.66	1,869.66
<u>SPECIAL NETT ITEMS</u>				
1	SET REVERSING SENSOR WITH INSTALLATION (SN)	CRACKED	200.00	200.00
			200.00	200.00
<u>LABOUR</u>				
	TO STRAIGHTEN REAR BODY INCLUDING CUTTING AND WELDING TO KNOCK DENTS ON REAR LUGGAGE PANEL, REAR FENDER LH & RH, REAR BOOT LID AND RENEW OF PARTS.		700.00	650.00
	TO SPRAY PAINT.		900.00	800.00
			-	-
			-	-
			-	-
			1,600.00	1,450.00
GRAND TOTAL			3,669.66	3,519.66

Report Ref No. CS/FC118015350/Krd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00
---	--	--	----------

Report Ref No. CS/FCI18015350/Krd3e2

MARKET VALUE: \$12,000.00(EST)-LTA REIMBURSEMENT VALUE: \$7,816.00=NETT VALUE: \$4,184.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.