

23/03/2002

ASS. REC. BY:

REF: CS/FCI18015351/Ksd3

Special Instruction:

Surveyor:

CWS

From (Person):

Lurene JW

ASSIGNMENT (Office)

of FCI

Date/Time: 22/8/18 @ 1:15pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 6203Y

Insured:

SHB 22274

at Workshop m/s

Est. ecom performance

Tel:

87990066

of

Blk 5033 Amk Ind. park 2 #01-251

Policy No:

Claim No:

D18006229 MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/8/18

24/8/18 @

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(ps)

Date/Time:

10:21am @ 23/8/18

Person Contacted:

Carmen

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	My met call carmen. case Kenneth over call buel.
	SH 6203Y - X
	SHB 22274 - CS/FCI15021966/Gqh3c2 DOA: 4/12/15
27/08/18	@ 16:41 p.m. received PA to Lurene via email.
26/11	82682.89 Car hunt.

(08/11/13) wef

REF: FCI

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: 24/8/18

Estimated Cost: _____

On ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ 6203Y

at Workshop m/s: Esteem Performance

of: 385 Sin Ming drive

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record) 10am @ owner waiting

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 892k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1-B, 1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ 6203Y Yr Regn: 12, 16

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius C.C. 1798

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 133592 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3F46 03538831

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / ☒ Jammed / Leaked / Burnt or

Brake: In order / ☒ Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 16/8/18

Rear

R/Bal. 5 mm

L/Bal. 5 mm


D.O.I. 24/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S Rm

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

27/8 File pass to Corrine

04/01/19 Confirmed P/P \$2,682.89 @ 5 days with Kenneth

(\$1,059.52 Red - 28%)

MC - \$92kLTA

RECEIVED 04 JAN 2019

Date/Time, File Pass to?

04/01/191) Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS, \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ 2,682.89 P/P)

130

50

50

15

245

4/1/2019



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18015351/Ksd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-08-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2227U	Veh. Inspected	SLJ 6203Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18006229MFSH	Excess (\$)	0.00
Assign From	CWS(LURENE JAW)	Assign Date	23/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/08/2018	Inspection Date	24/08/2018
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006229MFSH

Date: 27 August 2018

Our Ref: CS/FCI18015351/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLJ 6203Y .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 24/08/2018 at the premises of M/s Esteem Performance Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,742.41</u> .
Revised Estimate Amount	: S\$ <u>2,682.89</u> .
"Check" Items Amount	: S\$ <u>65.55</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,

Kenneth Kong

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-08-2018	Our Ref No.	D18006229MFSH
Accident Date	16-08-2018	Claim Type.	Third Party
Insured Vehicle	SHB2227U	Third Party Vehicle.	SLJ6203Y
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259		
Contact Person.	CARMEN LIM		
Contact No.	87990066/ 87990066	Fax No.	64847829
Survey Type	DIRECT SETTLEMENT:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	LURENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 27 August 2018 4:41 PM
To: LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18006229MFSH/1
Attachments: SLJ 6203Y - Preli Advise.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SLJ 6203Y.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 23 August 2018 10:23 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18006229MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 22 August 2018 1:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006229MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLJ 6203 Y

Parts	(a) Cost / List Price Items	\$	3,323.21
	Plus/Less 25%	\$	830.80
	Total of Cost / List	\$	2,492.41
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	2,492.41
Labour		\$	1,250.00
Total		\$	3,742.41

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 24/8/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required Required

(d) Excess : \$ _____

(e) Signature of surveyor : Lc Date: 24/8/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLJ 6203 Y

TOYOTA PRIUS

JTDKB3FU603538831

Submit By :

Carmen Lim

Year Manufacture :

2016

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH wing mirror (arm)	1			
2	RH wing mirror (signal lamp) <i>CM</i>	1	\$1,374.20		✓
3	RH wing mirror (glass)	1			
4	RH wing mirror (cover) <i>SC</i>	1	\$87.40		X
5	RH front door <i>SC</i>	1	\$1,226.70		✓
6	RH front door hinge top <i>SC</i>	1	\$78.34		X
7	RH front door hinge bottom <i>SC</i>	1	\$78.34		X
8	RH front door checker <i>SC</i>	1	\$156.79		X
9	RH front door weatherstrip <i>SC</i>	1	\$198.49		X
10	RHF door glass outer moulding <i>SC</i>	1	\$122.95		✓
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829

Company Reg No. 200005485N / GST No. 20-0005485-N




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015351/Ksd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-01-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2227U	Veh. Inspected	SLJ 6203Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006229MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	22/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKB3FU603538831	Colour	METALLIC SILVER	
Odometer	133592	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/08/2018	Inspection Date	24/08/2018	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 6203Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RH WING MIRROR (SIGNAL LAMP) }	CRACKED	1,374.20	1,374.20
1	RH WING MIRROR (ARM) }		-	-
1	RH WING MIRROR (GLASS) }		-	-
1	RH WING MIRROR (COVER)	SERVICEABLE	87.40	-
1	RH FRONT DOOR	BENT	1,226.70	1,226.70
1	RH FRONT DOOR HINGE TOP	TO REPAIR SEE LABOUR	78.34	-
1	RH FRONT DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	78.34	-
1	RH FRONT DOOR CHECKER	TO REPAIR SEE LABOUR	156.79	-
1	RH FRONT DOOR WEATHERSTRIP	SERVICEABLE	198.49	-
1	RHF DOOR GLASS OUTER MOULDING	CUT	122.95	122.95
	LESS 25% DISCOUNT		-830.80	-680.96
			2,492.41	2,042.89
LABOUR				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(RH SIDE MIRROR,RHF DOOR).INCLUSIVE OF THE REPAIR OF RH FRONT DOOR HINGE TOP,RH FRONT DOOR HINGE BOTTOM AND RH FRONT DOOR CHECKER.		500.00	250.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(RH SIDE MIRROR,RHF DOOR).		500.00	280.00
	TO CHECK WIRING.		50.00	20.00
	TO TUFF COAT.		50.00	30.00
	TO REMOVE & REFIT DOOR TRIM,DOOR GLASS,WINDOW REGULATOR,DOOR LOCK TO ASSIST WORK LOAD.		150.00	60.00
	-		-	-
	-		-	-
	-		-	-
			1,250.00	640.00
GRAND TOTAL			3,742.41	2,682.89



RECOMMENDED COST OF REPAIRS			2,682.89
-----------------------------	--	--	----------

Report Ref No. CS/FCI18015351/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.