

ASS. REC. BY:

REF:

es/FCI18015357/Grd3

Special Instruction:

Surveyor

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Joanne Yang

of

FCI

Date/Time:

23/8/18 @ 12:32pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8JU1217G

Insured:

SHD3027M

at Workshop m/s

Success United

Tel:

67461515

of

8/K 1065 Euros Ave 4 # 01-150

Policy No:

Claim No:

D18006278MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:32pm @ 23/8/18

Person Contacted:


Sookie

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	8JU1217G-X
	SHD3027M-ec3/FCI17013838/M/cb3g2 DOA: 13/7/17
	Revert thru Email IA 9223 6288
	51h na
20/11/18.	Confirm with L/s \$6500 @ 7 days (Ref: \$12,028.82, 65%.) Sinha

ASSIGNMENT

From: Date: Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: at Workshop m/s Success united of Insured Policy No: Claims No: Sum Insured: Excess: (Client's Record) Make of Veh:



(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: \$16k IDAC Accident Rpt.: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Est. Repairs: 7 days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT

Veh No: 53U 12176 Yr Regn: 18 Nov 2009 Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: Chevrolet cruze cc 1598 Colour: white A/C: Insured / Std / NI / NA Sp. Reading: 252305 T/Radio: Insured / Std / NI / NA Eng/No: C/No: KL1JA6961AK562699 Gen. Cond: Good / Fair / Poor / Burnt Steering: In order / Jammed / Leaked / Burnt or Brake: In order / Jammed / Leaked / Burnt or Modi: Nil / S/Rim / STD A/Rim or Tyre Size: F: 205/60R16 R: 11 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or FIRENZA Front R/Bal: 6 mm L/Bal: 6 mm D.O.A. Survey held at w/s Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or 5230pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV: \$16,000.00, LTA: \$8,886.00, NV: \$7,114.00
	RECEIVED 20 NOV 2018

Date/Time, File Pass to? ☐ : Preli. Report ☒ : Final Report Days Of Repair: 1 Resurvey No. of Trip: 2 Survey Fee: 8x152 120 170+120 50 50+50 83 523

Date/Time, File Return to? 2) Add Fee: ☐ : Site Insp (\$ ☐ : Interview (\$ ☐ : Tech. Invs (\$ ☐ : Weekend (\$ Report Format: TP Lump Sum / LTA (\$ 6500 TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18015357/Grd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-08-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3027M	Veh. Inspected	SJU 1217G
Policy No.		Coverage (\$)	0.00
Claim No.	D18006278MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	23/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/08/2018	Inspection Date	23/08/2018
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006278MFSH

Date: 19 November 2018

Our Ref: CS/FCI18015357/Grd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJU 1217G.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23/08/2018 at the premises of M/s SUCCESS UNITED PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>18,528.82</u>
Revised Estimate Amount	: S\$ <u>11,624.77</u>
"Check" Items Amount	: S\$ _____
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear and front portion.



Yours faithfully

XING GUO QIANG
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	21-08-2018	Our Ref No. D18006278MFSH
Accident Date	18-08-2018	Claim Type. Third Party
Insured Vehicle	SHD3027M	Third Party Vehicle. SJU1217G
Survey Location	BLK 1065 EUNOS AVE 4 #01-150/152	
Contact Person.	SOOKIE	
Contact No.	67461515/ 0	Fax No. 67485015
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SUCCESS UNITED PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, November 19, 2018 7:11 PM
To: 'CWS Motor Claims'
Cc: 'Eileen Lee'
Subject: RE: SURVEY ASSESSMENT - D18008191MFSH/1
Attachments: SJU 1217G.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for SJU 1217G

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, November 19, 2018 5:39 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008191MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 19 November, 2018 5:33 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008191MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Janice Lee (LKKAuto)

From: sirina@successunited.com.sg <sirinassk@gmail.com>
Sent: Tuesday, November 20, 2018 11:00 AM
To: Janice Lee (LKKAuto)
Cc: Guo Qiang (LKKAuto); sirina@successunited.com.sg
Subject: Re: SJU 1217G - Check items, after paint

Morning Janice

OK, confirmed.

Thank You.

Best Regards,

Sirina Soon

Senior Claims Executive
Mobile: +65 9223 6288

SUCCESS UNITED PTE LTD
2 Kaki Bukit Ave 2
#01-33 / #02-29
Kaki Bukit AutoHub
Singapore 417921
Tel: 6746 1515 Fax: 6748 5015

On Mon, Nov 19, 2018 at 6:58 PM Janice Lee (LKKAuto) <JaniceLee@lkkauto.com> wrote:

Dear Sirina,

Kindly confirm L/S \$6,500.00 @ 7 DAYS

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/07/2018 13:13
Date Of Accident	22/07/2018 20:00
Exact Location Of Accident	T-JUNCTION OF BEDOK RESERVOIR RD/BEDOK NRTH AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ3070B
Insured/Policyholder	
Name Of Registered Owner	MUTHUMANI SIVAKUMAR
NRIC No	S7285202H
Email Address	MUTHUMANISIVAKUMAR@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94244070
Alternative Phone No	OTHERS-94244070

Vehicle Particulars

Manufacturer	SYM
Model	COMBIZ 125-125CC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5064719487
Cover Note Number	

Driver

Name of Driver	KARUPPAIAH MANIK ANDAN
Passport No/FIN	G3284486W
Date Of Birth	20/05/1985
Occupation	OUTDOOR
Date Of Driving Pass	31/08/2016
Driving Experience	1 YEAR AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84240511
Fax Number	
Contact Number	
EMail Address	NOEMAIL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1259E

Vehicle Details

Vehicle No.: SJU1217G
Vehicle to be Exported: No
Intended De-registration Date: 21 Aug 2018
Vehicle Make: CHEVROLET
Vehicle Model: CRUZE 1.6L AUTO ABS D/AB 2WD 4DR
Primary Colour: White
Manufacturing Year: 2009
Engine No.: F16D34818261
Chassis No.: KL1JA6961AK562699
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$12,527.00
Original Registration Date: 18 Nov 2009
First Registration Date: 18 Nov 2009
Transfer Count: 0
Actual ARF Paid: \$12,527.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Nov 2019
PARF Rebate Amount: \$6,889.00

Intended COE Rebate Details

COE Expiry Date: 17 Nov 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$16,201.00
COE Rebate Amount: \$2,010.00
Total Rebate Amount: \$8,899.00

The information contained herein is correct as at 20 Aug 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1259E
Vehicle Details	
Vehicle No.:	SJU1217G
Vehicle to be Exported:	No
Intended De-registration Date:	24 Aug 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	F16D34818261
Chassis No.:	KL1JA6961AK562699
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,527.00
Original Registration Date:	18 Nov 2009
First Registration Date:	18 Nov 2009
Transfer Count:	0
Actual ARF Paid:	\$12,527.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Nov 2019
PARF Rebate Amount:	\$6,889.00
Intended COE Rebate Details	
COE Expiry Date:	17 Nov 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$16,201.00
COE Rebate Amount:	\$1,997.00
Total Rebate Amount:	\$8,886.00

The information contained herein is correct as at 24 Aug 2018

OK



聯成汽車維修

SUCCESS UNITED PTE LTD.

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921
Tel: 6746 1515 / 6747 1787 Fax: 6748 5015
www.successunited.com.sg Co. / GST Reg: 200402570G

Estimate : **TP/18-092**

M/s **MS First Capital Insurance Ltd**
36 Robinson Road
#16-01 City House
Singapore 068877

Date : 21st August 2018

Vehicle No : **SJU 1217G**
Make/ Model : Chev Cruze
Chassis No : KL1JA6961AK562699
Acc. Date : 18.08.18
Policy No :

Attn : Motor Claim

Tel: 65073848

Fax: 65073849

Email : icwsmotorclaims@msfirstcapital.com.s

Your Ref : SHD 3027M

S/n.	Qty	Particulars	Unit Price	Amount
Materials				
1	1 pc	Frt Bumper Assy <i>re</i>		\$ 1,250.00 <i>895</i>
2	1 pc	Frt Bumper No. Plate Garnish <i>CRA</i>		\$ 68.00 <i>/</i>
3	1 pc	Frt Bumper Inner Sponge <i>CRA</i>		\$ 158.00 <i>/</i>
4	1 pc	Frt Bumper Reinforcement <i>X NN</i>		\$ 847.00 <i>X</i>
5	2 pc	Frt Bumper Side Holder L/R <i>re.</i>	\$ 55.00	\$ 110.00 <i>29</i>
6	1 pc	Frt Bumper Logo <i>scr.</i>		\$ 152.00 <i>65</i>
7	1 pc	Frt Top Grille Assy <i>X NN</i>		\$ 352.40 <i>X</i>
8	1 pc	Frt Center Grille <i>Cut</i>		\$ 284.10 <i>263</i>
9	1 pc	Frt Bonnet <i>DD</i>		\$ 1,554.00 <i>1455</i>
10	1 pc	Frt Bonnet Lock <i>X NN</i>		\$ 115.00 <i>X</i>
11	1 pc	Centre Brace Panel <i>X</i>		\$ 398.00 <i>X</i>
12	1 pc	Rear Bumper Assy <i>re</i>		\$ 1,515.20 <i>1291</i>
13	2 pc	Rear Bumper Side Holder L/R <i>re.</i>	\$ 58.00	\$ 116.00 <i>100</i>
14	1 pc	Rear Bumper Tow Hook Cover <i>an's</i>		\$ 48.00 <i>30</i>
15	1 pc	Rear Bumper Reinforcement <i>BT</i>		\$ 944.80 <i>736.25</i>
16	2 pc	Rear Lamp L/R <i>Cut.</i>	\$ 655.80	\$ 1,311.60 <i>/</i>
17	2 pc	Rear Boot Lamp L/R <i>CRA</i>	\$ 350.00	\$ 700.00 <i>/</i>
18	1 pc	Rear Boot Lid <i>BT</i>		\$ 1,264.00 <i>/</i>
19	1 pc	Rear Boot "Chevrolet" Emblem <i>/</i>		\$ 108.00 <i>65</i>
20	1 pc	Rear Boot "Cruze" Emblem <i>/</i>		\$ 54.00 <i>/</i>
21	1 pc	Rear Boot Logo <i>/</i>		\$ 54.00 <i>/</i>
22	1 pc	Rear Boot Mechanism Lock <i>BT</i>		\$ 284.00 <i>/</i>
23	1 pc	Rear Boot Weatherstrip <i>Turni</i>		\$ 168.00 <i>/</i>
24	2 pc	Rear Lamp Lower Bracket L/RH <i>PH</i>	\$ 55.00	\$ 110.00 <i>55</i>
25	1 pc	Rear Bumper Center Bracket <i>Cut.</i>		\$ 110.00 <i>75</i>
26	1 pc	Rear End Panel <i>X Panel</i>		\$ 988.70 <i>906</i>
27	1 pc	Rear End Panel Inner Top Garnish <i>re</i>		\$ 185.00 <i>139</i>
28	1 pc	Rear Spare Tyre Panel <i>X repair.</i>		\$ 1,080.00 <i>X</i>
				\$ 14,329.80
				Less 10% : \$ 1,432.98
				Total : \$ 12,896.82

		<u>Special Nett</u>			
29	1 pc	Rear No Plate w/frame	\$	45.00	/
30	1 pc	Frt No Plate w/frame	\$	45.00	/
30	4 pc	Rear Bumper Reverse Sensor	\$	632.00	200
			Special Nett	\$	722.00

		<u>Labour</u>			
1	To remove, rearrange electrical wirings, check lightings		\$	80.00	30
2	To remove, replace rear exhaust silencer & re-align.		\$	180.00	x m
3	To remove, reinstall inner trim, garnishes & upholstery.		\$	250.00	60
4	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.		\$	2,600.00	1000
5	To putty and respray painting on affected area.		\$	1,800.00	1100
			Total Labour :	\$	4,910.00

Total Parts & Labour : \$ 18,528.82


Success United Pte Ltd

No of Days 7

Re-Survey Before/After Paint
Part By Part/Lump Sum

Surveyed By Gino Que Contact No. 8288 0282

Date of Survey 23/8/18 Fax No. _____

NOTE: LUMP SUM WILL BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015357/Grd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-11-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3027M	Veh. Inspected	SJU 1217G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006278MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	23/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET CRUZE	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KL1JA6961AK562699	Colour	WHITE	
Odometer	252305	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	FIRENZA	6 mm	
L/H Front Tyre	205/60 R16	FIRENZA	6 mm	
R/H Rear Tyre	205/60 R16	FIRENZA	6 mm	
L/H Rear Tyre	205/60 R16	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/08/2018	Inspection Date	23/08/2018	
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 1217G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER ASSY	DEFORMED	1,250.00	895.00
1	FRT BUMPER NO PLATE GARNISH	CRACKED	68.00	68.00
1	FRT BUMPER INNER SPONGE	CRACKED	158.00	158.00
1	FRT BUMPER REINFORCEMENT	NOT NECESSARY	847.00	-
2	FRT BUMPER SIDE HOLDER L/R @\$55.00	DEFORMED	110.00	24.00
1	FRT BUMPER LOGO	SCRATCHED	152.00	65.00
1	FRT TOP GRILLE ASSY	NOT NECESSARY	352.40	-
1	FRT CENTER GRILLE	CUT	284.10	263.00
1	FRT BONNET	DENTED	1,554.00	1,455.00
1	FRT BONNET LOCK	NOT NECESSARY	115.00	-
1	CENTRE BRACE PANEL	NOT NECESSARY	398.00	-
1	REAR BUMPER ASSY	DEFORMED	1,515.20	1,291.00
2	REAR BUMPER SIDE HOLDER L/R @\$58.00	DEFORMED	116.00	100.00
1	REAR BUMPER TOW HOOK COVER	MISSING	48.00	30.00
1	REAR BUMPER REINFORCEMENT	BENT	944.80	736.25
2	REAR LAMP L/R @\$655.80	CUT	1,311.60	1,311.60
2	REAR BOOT LAMP L/R @\$350.00	CRACKED	700.00	700.00
1	REAR BOOT LID	BENT	1,264.00	1,264.00
1	REAR BOOT "CHEVROLET" EMBLEM	NECESSARY	108.00	65.00
1	REAR BOOT "CRUZE" EMBLEM	NECESSARY	54.00	54.00
1	REAR BOOT LOGO	NECESSARY	54.00	54.00
1	REAR BOOT MECHANISM LOCK	BENT	284.00	284.00
1	REAR BOOT WEATHERSTRIP	TWISTED	168.00	168.00
2	REAR LAMP LOWER BRACKET L/RH @\$55.00	N/S CRACKED / O/S NOT NECESSARY	110.00	55.00
1	REAR BUMPER CENTER BRACKET	CUT	110.00	75.00
1	REAR END PANEL	BUCKLED	988.70	906.00
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	185.00	139.00
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,080.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,432.98	-1,016.08
			12,896.82	9,144.77
	SPECIAL NETT ITEMS			
1	REAR NO PLATE W/FRAME (SN)	SCRATCHED	45.00	45.00
1	FRT NO PLATE W/FRAME (SN)	CRACKED	45.00	45.00
4	REAR BUMPER REVERSE SENSOR @\$158.00 (SN)	DAMAGED	632.00	200.00
			722.00	290.00
	LABOUR			
	TO REMOVE,REARRANGE ELECTRICAL WIRINGS,CHECK LIGHTINGS.		80.00	30.00
	TO REMOVE,REPLACE REAR EXHAUST SILENCER & RE-ALIGN.	NOT NECESSARY	180.00	-
	TO REMOVE,REINSTALL INNER TRIM,GARNISHES & UPHOLSTERY.		250.00	60.00
	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL.		2,600.00	1,000.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA.		1,800.00	1,100.00
			4,910.00	2,190.00
GRAND TOTAL			18,528.82	11,624.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,500.00

Report Ref No. CS/FCI18015357/Grd3n2

MARKET VALUE: \$16,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$8,886.00=NETT VALUE: \$7,114.00

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.