

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0963/2018/PH  
**Date** : 23-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.  
Your insured vehicle : SKV 9755 A

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**  
**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Liu Li Yun  
**Address** : Blk 11 Woodland Dr 72  
: #08-33  
Singapore 738094  
**Telephone** : HP +65 98525337  
**Type of Claim** : THIRD PARTY CLAIM  
**Policy No.** : 2100385297-04  
**Vehicle No** : **SKQ 8886 M**  
**Model Code** : Audi A8L D4 3.0 TFSI QU  
**Model / Year** : Feb-14  
**Engine No** : CGW 045147  
**Chassis No** : WAUZZZ4H2CN037511  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 19-Aug-18  
**Place of Accident** : Along SLE towards Woodlands Ave 12

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKO 8886 M.

FRONT

S/n	Nature of Jobs	Estimated Charges	Remarks
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00	
3	To respray rear bumper and bumper lower spoiler	\$ 1,400.00	
4	To carry out diagnostic check	S/N \$ 192.00	
<b>TOTAL LABOUR CHARGES - FRONT</b>		<b>: \$ 3,152.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKQ 8886 M.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 3,211.00	
2	FIXING PARTS FOR REAR BUMPER	\$ 125.00	
3	RETAINING STRIP - LH/RH	2 \$ 58.00	
4	SECURING PIN	6 \$ 63.00	
5	DOUBLE COLLARD STUD	2 \$ 61.00	
6	CHROME STRIPS FOR BUMPER CHROME	\$ 781.00	
7	REAR BUMPER SPOILER	\$ 584.00	
8	SECURING STRIP	\$ 44.00	
9	SECURING STRIP	\$ 135.00	
10	RETAINER FOR CONTROL UNIT	\$ 22.00	
11	BUMPER CARRIER	\$ 1,315.00	
12	RETAINING BRACKET - OUTER	2 \$ 83.00	
12	GUIDE SECTION - CENTER	\$ 61.00	
13	GUIDE SECTION - LH UPPER	\$ 20.00	
14	GUIDE SECTION - RH UPPER	\$ 18.00	
15	GUIDE SECTION - LH OUTER	\$ 28.00	
16	GUIDE SECTION - RH OUTER	\$ 26.00	
17	SENSOR - PRIMED	2 \$ 421.00	
	<b>TOTAL SPARE PARTS CHARGES</b>	<b>\$ 7,056.00</b>	
	<b>TOTAL LABOUR CHARGES</b>	<b>\$ 3,152.00</b>	
	<b>GRAND TOTAL</b>	<b>\$ 10,208.00</b>	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

---

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

---

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

---