

Soon Bee Vehicle & Bodywork Maintenance

10 Anson Road #33-17 International Plaza Singapore 079903.

GST Registration No: 53076555A Email: paul@soonbee-vm.com.sg

Quotation No. : SB-GA-TCC18011

Date: 18-Aug-18

Lonpac Insurance Bhd.
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Dear Sir/Mdm,

Estimated Cost of Repair Job for:

Accident on 26/07/2018, along HOUGANG AVE 2 X HOUGANG AVE 3 involving SG5542H and GBC1163S

- the Repairer:**
- To resurvey before/after spray painting
 - To display damaged parts during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

SG5542H

Date:

We are pleased to submit the below estimated quotation for your consideration.

1)	Vehicle No : SG5542H Model : B9TL-9.4 D (A)	<i>cost price.</i>	
2)	List Item:	(S\$)	(S\$)
	Lower deck front dome with sealant <i>CPA.</i>	\$2,463.64	
	Near side front bumper corner	\$278.81	
	Near side front light bezel	\$172.69	
	Near side front deflector	\$140.48	
	Main beam headlamp	\$173.62	
	Dipped beam headlamp	\$187.16	
	Front indicator	\$221.90	
	Water pump electric <i>X</i>	\$110.26	<i>X</i>
	Water bottle	\$218.50	
	Water bottle mounting bracket	\$276.69	
	Water bottle fill bracket	\$136.59	
	Paint (Green/ White/ Grey)	\$670.00	
Parts Total Sum:			\$5,050.34
Labour:			<i>4940.08</i>
	Labour charges to remove and refit lower deck front dome		
	Labour charges to remove and refit both side front quarter glass, windscreen <i>580</i>	\$3,500.00	<i>2900</i>
	Labour charges to remove and refit near side front parts and lighting fitting		
	Labour charges to repair damaged protection unit, bumpers and bracket holders		
	Labour charges to remove and refit water bottle, parts and connection		
	Labour charges to check and rectify wiring	\$180.00	<i>40</i>
	Labour charges to re-spray and polishing affected area	\$600.00	<i>500</i>
Labour Total Sum:			\$4,280.00
Parts and Labour Total Cost:			\$9,330.34
GST (7%) :			\$653.12
Total :			\$9,983.46
<i>part by ref.</i>			
<i>before and after repair photos.</i>			
<i>paint photos.</i>			
<i>Guo Qiang - 8288 0282</i>			
Repair Duration: <i>6</i> Working Day			
Term of Payment: 30 Days Upon Invoice			

Appointed Surveyor confirmation & agreed:

Surveyor Name: Guo Qiang

Surveyor NRIC: 5797793E

1st Signature /Date : Guo Qiang 23/8/18

2nd Signature / Date: _____

3rd Signature / Date: _____

Regards,



Paul