

INS CASE OWNER

Choo Hong

CC6, AIG 180

15378

Apr 3 4

LKK  
IDAC

Surveyor:

(WP)

KAR

DOI:

ASSIGNMENT

21/8/2018

Date / Time:

21/8/2018

Registered in Merimen:

23/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II :SS

Is driver the owner?

SLA 63895  
PRISCILLA TAN Lany Hong

HP: 90686332

D.O.A: 18/8/18 (SGT)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.

Policy No.

Make / Model:

Place of Accident:

21082406

M-BENT CLAP

Tampines Expressway

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

m7706R → SHD4504X →

SLA63895 →

SLA9696A →

SLJ 8181M



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

Flying High

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

28/8  
CH1

SLA9696A - 15/10/18 15378/62447; 20/10/18  
- 15/10/18 15378/62447; 20/10/18  
SLA63895.

STAGE DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

24/5/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Minute/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. 28(5cc.013rd)

If NO or B 28, Ass. Lit. OK

Repair Cost:

S\$

15600.00

Loss of Rental (LOR):

S\$

21W-W

( 14 days)

X \$160.W

Loss of Use (LOU):

S\$

-

( \$ x days)

Loss of Income (LOI):

S\$

-

( \$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$

-

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost:

S\$

-

Total:

S\$

172W-W

Global Sum S\$:

17000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

17000.00

Name 1:

Flying High Spray Painting

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

20/12/18

Signature

Adrian

REF:

ALH

1503J

# ASSIGNMENT

From

Date

21/08/2018

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Blk 1 Kaki Bukit <sup>Flying High</sup> Apt 6 #01-29

insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

11

days

Res.: Yes or No

Lump Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle IN / OUT

Veh No:

5659696A

Yr Reg:

24 Jun 2011

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prima Mover /

Truck / Trailer or

Make:

BMW 523i

<< 2497

Colour:

black

A/C

Insured / Std / NI / NA

Sp. Reading

136956

T/Radio

Insured / Std / NI / NA

Eng No:

WBAFP32020C 866962

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

225/45 R17

R:

11

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.J.

21-08-18

Survey held at

w/s

1pm

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

42 # 15600 (Red) 13924.w/ 4742

Date/Time: File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1. S + R = \$

2. Photo

3. Other

4.

TOTAL

Report Format:

Lump Sum / L.B.1 (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Insp (\$)

☐

Weekend (\$)

SGS9696A 2011 Inc.

BMW 523i

WBAFP32020C866962

Rear Number Plate	30(SN) x
Rear Number Plate Holder	30(SN) x
Rear Bumper Distorted	1532 ✓
Rear Bumper Clips	50 ✓
Rear Bumper Side Holder x 02	135 x 2 = 270 x
Rear Bumper Reinforcement	698 ✓
Rear Bumper Centre Guide	195 ✓
Rear Bumper Reflector x 02	54 x 1 = 108 x
Rear Bumper Under Cover	168 ✓
Rear Bumper Under Cover Clips	20 ✓
Rear Bumper Side Under Cover	98 ✓
Rear Bumper Side Under Cover Clips	10 ✓
Rear Bumper Lanes Cover	285 ✓
Reverse Sensor x 04 2 pieces damaged	250 x 4 = 1000 750
Rear End Panel Dented	978 ✓
Rear End Panel Top Garnish	211 ✓
Rear End Panel Sealant	60(SN) ✓
Taillamp x 02 cracked	530 x 2 = 1060 ✓
Bootlid Dented	1563 ✓
Bootlid Lock	195 ✓
Bootlid Weatherstripe	283 ✓
Bootlid Reflector x 02 cracked	305 x 2 = 610 ✓
Bootlid Hinge x 02	118 x 2 = 236 x
Bootlid Lower Trim Cover	149 x
Bootlid Lower Trim Cover Clips	30 x
BMW Logo	69 ✓
523i Emblem	85 ✓
Spare Tyre Panel Top Cover	390 x
Rear Exhaust Pipe Repair	1379 x
Rear Exhaust Manifold	59 x
Rear Exhaust Heat Shield	135 x

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1503J
Vehicle Details	
Vehicle No.:	SG59696A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Sep 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	11957800N52B25AF
Chassis No.:	WBAFP32020C866962
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$44,497.00
Original Registration Date:	24 Jun 2011
First Registration Date:	24 Jun 2011
Transfer Count:	1
Actual ARF Paid:	\$44,497.00
PARF Eligibility Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jun 2021
PARF Rebate Amount:	\$26,698.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jun 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$67,700.00
COE Rebate Amount:	\$18,576.00
Total Rebate Amount:	\$45,274.00

The information contained herein is correct as at 26 Sep 2018

2018-18/08/18

OK

MV 62K

PV : 46K.

Nett : 16K.

**SEARCH** 
 Price Range 
 Depreciation 
 2011 
 Vehicle Type

## Used Car Comparison

— Comparing 4 Vehicles —

BMW 5 Series 523i Highline



Clear All

[Back to search result](#)

BMW 5 Series 523i



BMW 5 Series 523i



BMW 5 Series 523i



### CAR DETAILS

Price	\$60,800	\$61,800	\$63,800	\$65,800
Instalment	\$1,524	\$1,503	<b>\$1,464</b>	\$1,469
Registration Date	15-Apr-2011	27-Apr-2011	11-Jul-2011	22-Aug-2011
Manufactured	2011	2011	2011	2011
Mileage	76,000 km	93,173 km	103,000 km	-
Transmission	Auto	Auto	Auto	Auto
Engine Cap	2,497 cc	2,497 cc	2,497 cc	2,497 cc
Road Tax	\$1,796 /yr	\$1,796 /yr	\$1,796 /yr	\$1,796 /yr
Power	150.0 kW (201 bhp)	150.0 kW (201 bhp)	150.0 kW (201 bhp)	150.0 kW (201 bhp)
Curb Weight	1,650 kg	1,650 kg	1,650 kg	1,725 kg
Features	2.5L Inline 6 Mated With 8 Speeds Steptronic Via E-Gear Produced 2018hp And 250Nm Of Torque And Raw Power, Dual Zone Auto Climate, Keyless Entry	2.5L 6 Cylinders Inline 24 Valves Engine, 2018hp, 250Nm Torque, 8 Speed Auto Transmission, Cruise Control, Multi Function Steering, Traction Control.	Powerful And Fuel Efficiency 6 Cylinder Engine, 8 Speed Transmission, i-drive, Cruise Control, Xenon LED Lights, Comfort Access, Electric Tailgate.	2.5L 6 Cylinders In 2018hp, 250Nm Tc Transmission, Multi Cruise Control, Tra
Accessories	i-Drive, Bluetooth Connectivity, Navigation, Multi Function Steering Wheel, Park Assist, Auto Tailgate, Comfort Access, Cruise Control, Fog Lamps.	Factory Fitted Audio System, Bluetooth, Auto-Hold, Xenon Headlights, Park Assist, Sports Rims, Keyless Entry And Push Start, Auto Tailgate.	Brown Leather Seats, Auto-tailgate, Solar Film, Navigation, GPS, Reverse Camera, Sports/comfort Mode, Paddle Shifters.	Factory Fitted CD / Control, Auto Tailg Display, Sports Rim Start.
Description	Yes You Are Right! Downpay Merely \$6500. With A Most Refine Drive On A Six Cylinders, This Car Is Well Known For Sheer Pleasure Drive, Fully Maintained And Serviced, Completely Stock With No Modifications, Priced To Sell, Low Depreciation! 10% Drive Away, Trade In Welcome, Evaluation Welcomed, Call Us For No Obligation Viewing Now.	\$7K Down Payment With The Lowest Instalment Of \$1.5k Only! In House Loan/Balloon Scheme Available With 100% Fast Approval Rate! BMW Signature Inline 6 Engine! PML Unit! A Lot Of Wear And Tear Replaced! New Runflat Tyres. Low Mileage Done! Servicing Done At PML Authorized Workshop Regularly! Call Now For Viewing!	Front Soft Doors Plus M-body Kit, PML Unit, Road Tax Till Jan 2019, Arrange For Viewing This Amazing Unit Before It Is Gone.	\$0 Down Payment House Loan Option By Jack Cars Servicing You! White With Premium Unbelievable Good Friendly Salesperson! Viewing With No O
COE	\$62,001	\$62,010	\$65,490	\$67,000
OMV	\$47,342	\$41,275	<b>\$49,428</b>	\$43,265
ARF	\$47,342	\$41,275	<b>\$49,428</b>	\$43,265
Depreciation	\$14,560 /yr	\$15,930 /yr	\$14,010 /yr	\$15,210 /yr
No. of Owners	3	2	3	2
Type of Vehicle	Luxury	Luxury	Luxury	Luxury
Category	PAIF Car, Premium Ad Car	PAIF Car, Direct Owner Sale	PAIF Car, Direct Owner Sale	PAIF Car
Availability	Available	Available	Available	Available

### SELLER INFORMATION

26/09/18

## Hsiao Tong (LKKAUTO)

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Saturday, 1 December 2018 2:52 PM  
**To:** 'Loh, Chee-Heng'  
**Subject:** <Seek Mandate> Your Ref: 3913894308SG \*Our Ref: CC6/AIG18015378/Apa3  
[ACCIDENT INVOLVING SLA 6389S(OI) /SGS 9696A(TP)/ OTHERS ON 18/08/2018]

Your Ref: **3913894308SG**  
Our Ref: CC6/AIG18015378/Apa3

**Without Prejudice**

Dear Sirs,

### ACCIDENT INVOLVING SLA 6389S(OI) /SGS 9696A(TP)/ OTHERS ON 18/08/2018

We refer to the above matter.

The said chain collision involved 5 vehicles whereby our insured was the 3<sup>rd</sup> vehicle.  
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.  
We did clarify with insured the nature of the accident and she is aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, "FLYING HIGH SPRAY PAINTING" is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair	\$ 29,524.00	\$ 15,600.00
2. Loss of Rental (14days x \$200.00)	\$ 2,800.00	\$ 2,100.00 (14days x \$150.00)
<b>TOTAL</b>	<b>\$ 32,324.00</b>	<b>\$ 17,700.00</b>

Total amount of claim (**Liability 100%**) **\$ 17,700.00**

\*\*11 days recommendation for repair + 1PRS + 1PH + 1Sunday = 14days

Market Value	: \$ 62,000.00 (est)
LTA Rebate	: \$ 45,274.00 (est)
Nett Value	: <b>\$ 16,726.00 (est)</b>

**For your approval in Merimen please.**

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Hsiao Tong (LKKAuto)

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Thursday, 13 December 2018 9:10 AM  
**To:** 'Loh, Chee-Heng'  
**Cc:** Adrian Ling (LKKAuto); Admin A  
**Subject:** RE: <Seek Mandate> Your Ref: 3913894308SG \*Our Ref: CC6/AIG18015378/Apa3 [ACCIDENT INVOLVING SLA 63895(OI) /SGS 9696A(TP)/ OTHERS ON 18/08/2018]

Hi Chee Heng,

This is a chain collision accident. The damages to third party vehicle was on the front & rear portion.

Kindly refer to the below for your perusal: -

Particulars:	Photo in Merimen:
Rear end panel top garnish	67 - 68
Taillamp	71 - 75
Bootlid reflector	78 - 81
Headlamps	114 - 117

Particulars:	Photo in Merimen:
Front Bumper Lower Grille	93 - 95 

Labour:	Breakdown:
Panel Beating	Front - \$400.00 Rear - \$1,200.00
Spray Painting	Front - \$300.00 Rear - \$1,100.00

Kindly let us have your instruction after review the file.

## Hsiao Tong (LKKAUTO)

---

**From:** Loh, Chee-Heng <Chee-Heng.Loh@aig.com>  
**Sent:** Tuesday, 4 December 2018 9:31 AM  
**To:** Hsiao Tong (LKKAUTO)  
**Subject:** RE: <Seek Mandate> Your Ref: 3913894308SG \*Our Ref: CC6/AIG18015378/Apa3 [ACCIDENT INVOLVING SLA 63895(OI) /SGS 9696A(TP)/ OTHERS ON 18/08/2018]

Dear Hsiao Tong,

Kindly assist to verify damages highlighted by our in-house surveyor.

Not consistent:

- 1) No.16 Rear end panel top garnish
- 2) No.18 Taillamp
- 3) No.22 Bootlid reflector
- 4) No.45 Headlamps

67-68.

71-75

78-81

114-117

No Damage:

- 1) No.37 Front bumper lower grille

93-95

Labour too high:

- 1) Panel beating - \$800
- 2) Spray painting - \$1,000

Thank you.

Best regards,

**Loh Chee Heng**

**AIG**

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1881 | Fax +(65) 6835 7416

[Chee-Heng.Loh@aig.com](mailto:Chee-Heng.Loh@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

Follow us:



IMPORTANT NOTICE:

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Hsiao Tong (LKKAUTO) [mailto:[chewht@lkkauto.com](mailto:chewht@lkkauto.com)]

**Sent:** Saturday, December 01, 2018 2:52 PM

**To:** Loh, Chee-Heng

**Subject:** <Seek Mandate> Your Ref: 3913894308SG \*Our Ref: CC6/AIG18015378/Apa3 [ACCIDENT INVOLVING SLA 63895(OI) /SGS 9696A(TP)/ OTHERS ON 18/08/2018]

Your Ref: **3913894308SG**

Our Ref: CC6/AIG18015378/Apa3

**Without Prejudice**

Dear Sirs,



**ACCIDENT INVOLVING SLA 6389S(OI) /SGS 9696A(TP)/ OTHERS ON 18/08/2018**

We refer to the above matter.

The said chain collision involved 5 vehicles whereby our insured was the 3<sup>rd</sup> vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured the nature of the accident and she is aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, **"FLYING HIGH SPRAY PAINTING"** is as follows: -

	Amount <u>Claimed</u>	Amount <u>Revised</u>
1. Cost of Repair	\$ 29,524.00	\$ 15,600.00
2. Loss of Rental (14days x \$200.00)	\$ 2,800.00	\$ 2,100.00 (14days x \$150.00)
<b>TOTAL</b>	<b>\$ 32,324.00</b>	<b>\$ 17,700.00</b>

Total amount of claim (**Liability 100%**) **\$ 17,700.00**

\*\*11 days recommendation for repair + 1PRS + 1PH + 1Sunday = 14days

Market Value	: \$ 62,000.00 (est)
LTA Rebate	: \$ 45,274.00 (est)
Nett Value	: <b>\$ 16,726.00 (est)</b>

**For your approval in Merimen please.**

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## Print Received Message

This mail is associated with :

**\*SGS9696A (3913894308SG)**  
**[SLA6389S]**

TP

TAN TEVK SAI

Aug 18 2018 1:00PM

[PRISCILLA TAN LAY HONG (PRISCILLA CHEN LIFENG)]

Flying High Spray Painting

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 18/12/2018 09:54 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$17000.00) - SGS9696A - Claim Handler: Loh, Chee-Heng

Approved:17000.00:Kindly settle at best up to \$17,000 global.



Auto  
Consultants  
Pte Ltd

31 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18015378/Apa3

07 SEPT 2018

**PRISCILLA TAN LAY HONG**  
APR BLK 273B COMPASSVALE LINK  
#08-154  
SINGAPORE 542273

Dear Sir/Madam,

**ACCIDENT INVOLVING SLA 6389S / SGS 9696A/ OTHERS ON 18/08/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SGS 9696A against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG  
Case Handler  
DID: 6742 3197  
FAX: 6741 4108  
Email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

**AUTHORIZATION TO ACT**  
**(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)**

I, Tan Teck Sai, "the third party claimant",  
 of BLK 263 Tampines St 21 #10-136 (S) 520263 (address),  
 owner of SGS 9696A (vehicle no.) hereby authorize  
Flying High Spray Painting  
 ("the workshop") to act for me with respect to my claim or repair costs and/or  
 rental and/or loss of use "claim" for my vehicle no. SGS 9696A that was  
 damaged pursuant to the accident which occurred on 18.08.2018 (date) along  
TPE towards SLE before Punggol Exit (location)  
 Involving vehicle no/s SLA6389S ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
 manner that they deem fit and the workshop is further authorized to receive  
 payment further to settlement of my claim with payment or cheque/s being made in  
 favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
 behalf is on a without prejudice and without admission of liability basis insofar  
 as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 21 day of 08 month 2018 (year)



Signed by "the third party claimant"

**FLYING HIGH SPRAY PAINTING**

BLK 1 KAKI BUKIT AVE 6  
 #01-29 SINGAPORE 417883  
 (AUTO BAY @ KAKI BUKIT)  
 TEL: 6749 2997 FAX: 6744 2942

Signed by "the workshop"

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, FLYING HIGH SPRAY PAINTING ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SG\$17,000.00 (Global Sum) for vehicle no. SGS 9696A that was damaged pursuant to the accident which occurred on 18/08/2018 (date) along TPE TWDS SLE BEFORE PUNGGOL EXIT involving vehicle no/s SLA 6389S.

This is pursuant to the inspection conducted on 21/08/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN TECK SAI ("the third party claimant") of vehicle no. SGS 9696A make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGS 9696A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 19 (day) of 12 (month) 2018 (year)



Signed by appointed surveyor

**FLYING HIGH SPRAY PAINTING**

BLK 1 KAKI BUKIT AVE 6  
#01-29 SINGAPORE 417883  
(AUTO BAY @ KAKI BUKIT)  
TEL: 6749 2997 FAX: 6744 2942

Signed by "the workshop" (with chop)

SIGNED WITHOUT PREJUDICE FC  
ONLY PROPERTY CLAIM

# 高 飛 汽 車 噴 漆 廠

## FLYING HIGH SPRAY PAINTING

Blk 1, Kaki Bukit Ave 6, #01-29 Singapore 417883 (AutoBay@Kaki Bukit)

Tel: 6749 2997 Fax: 6744 2942 Email: fhs\_painting@singnet.com.sg

Business Reg. No. 42523200

### INVOICE

Vehicle no: SGS 9696A

Model: BMW 523I

Name: TAN TECK SAI

Date of accident: 18/08/2018

Address: C/O No 1 kaki bukit ave 6

#01-29 AutoBay@kaki bukit

S (417883)

### FINAL REPAIR BILL FOR VEHICLE NO SGS 9696A

QTY	ITEM	AMOUNT
1	LUMP SUM REPAIR COST	\$15,600.00
	Total	\$15,600.00
Dollars	FIFTEEN THOUSAND SIX HUNDRED ONLY	



# DAWN ENTERPRISES

21 Seletar West Farmway 1

Singapore 798125

Tel: 63832661 Fax: 64842836

Reg No. 430058/000

No 35963

## RENTAL AGREEMENT

DATE

18/8/18

### HIRER'S PARTICULARS

Name

Tan Teck Sai

Address

263 Tampines St. 21

#10-136

S520212

I/C or Passport No.

17115035

Country

Occupation

Date of Birth

Age

Driving Licence No.

96838885

Date Passed

Tel: (H/P)

(Residence)

### DRIVER'S PARTICULARS

Name

Address

I/C or Passport No.

Country

Occupation

Date of Birth

Age

Driving Licence No.

Date Passed

Tel: (Office)

(Residence)

### IMPORTANT NOTES:

1. No Insurance Coverage if the driver is below 24yrs old or less than 2 years driving licence.
2. This vehicle is licensed to carry <sup>8</sup> passengers only.
3. Hirer is liable to pay first \$2000 as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
4. For usage to Malaysia subject to higher excess all claims of \$55,000.00 and different rental rate.
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle.
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only.
10. No Service on Public Holiday and Sunday.

### SCHEDULE

### MODEL

SLE 9102 L

T/Carry

Date

Time

Mileage

18/8/18

1/9/18

### CHARGES

14 Day at \$200.00 per days

\$2800.00

Day at \$ per week

Day at \$ per month

TOTAL AMOUNT

\$2800.00

AMOUNT PAID

\$2800.00

BALANCE DUE

Days Extension From

To

Amount Deposit (refundable) \$

FROM

18/8/18

TO

1/9/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

Hirer's Signature

Driver/Guarantor's Signature

DAWN ENTERPRISES

**DAWN ENTERPRISES**

21 SELETAR WEST FARMWAY 1  
SINGAPORE 798125  
TEL: 6383 2661 FAX: 6484 2836  
REG. NO. 430058/000

No. 19482

Date, 1/9/18

**OFFICIAL RECEIPT**

Received from Tan Tek Sai  
the sum of Dollars two thousand eight hundred only

being Payment Of SLE 9102 L C18/8/18 - 1/9/18

DAWN ENTERPRISES

\$ 2800/-  
Cash/Cheque No.



# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2018 <a href="#">Edit Reg</a>		21 Aug 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$15,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$15,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>PRISCILLA TAN LAY HONG (PRISCILLA CHEN LIFENG)</b> , ID: 57601710G								
Main Claimant:	<b>TAN TECK SAI</b> , ID: S17115033								
Vehicle Reg. No.:	<b>SGS9696A</b>	Date of Loss:	18/08/2018 13:00 - :59 [85 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 3913894308SG</b>	Policy/Cover Note No.:	2100454906 (Comprehensive) Coverage: 10/03/2018 - 09/03/2019						
Vehicle Reg. No. (Insured):	<b>SLA6389S</b>	Policy No. (Claimant):	A28867776QMX						
		Excess:							
Repairer:	<b>Flying High Spray Painting (HQ)</b> BLK 1 Kaki Bukit Ave 6, #01-29 Auto Bay, 417883 Kaki Bukit - Tel: 67492997								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loh, Chee-Heng</b> ] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 03/09/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (18/12/2018): Alert - Adj Mandate Approved (S\$17000.00) - SGS9696A - Claim Handler: Loh, Chee-...</li> <li>AIG_SG_EXPRESS (04/12/2018): Alert - Adj Mandate Maintained - SGS9696A - Claim Handler: Loh, Chee-Heng</li> <li>AIG_SG (24/08/2018): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGS9696A (3913894308SG)

[SLA6389S]

TP



















































TAN TECK SAI



















































Aug 18 2018 1:00PM











[PRISCILLA TAN LAY HONG (PRISCILLA CHEN LIFENG)]

Flying High Spray Painting

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Letters/Correspondences</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	[Draft]	Third Party Express Settlement - Payment Breakdown		Edit
<b>Assessment Reports</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	24/08/18 10:25	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> <b>Accident Statement</b> <small>From: OD - Reg. No: SLA6389S, Claimant: PRISCILLA TAN LAY HONG</small>		Load HTM
<b>Photos/Images</b>				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)				
1	05/09/18 14:08	General View		Load JPG
2	05/09/18 14:08	General View		Load JPG
3	05/09/18 14:08	General View		Load JPG
4	05/09/18 14:08	General View		Load JPG
5	05/09/18 14:08	General View		Load JPG
6	05/09/18 14:08	General View		Load JPG
7	05/09/18 14:08	General View		Load JPG
8	05/09/18 14:08	General View		Load JPG
9	05/09/18 14:08	General View		Load JPG
10	05/09/18 14:08	General View		Load JPG
11	05/09/18 14:08	General View		Load JPG
12	05/09/18 14:08	General View		Load JPG
13	05/09/18 14:08	General View		Load JPG
14	05/09/18 14:08	General View		Load JPG
15	05/09/18 14:08	General View		Load JPG
16	05/09/18 14:08	General View		Load JPG
17	05/09/18 14:08	General View		Load JPG
18	05/09/18 14:08	General View		Load JPG
19	05/09/18 14:08	General View		Load JPG
20	05/09/18 14:08	General View		Load JPG
21	05/09/18 14:08	General View		Load JPG
22	05/09/18 14:08	General View		Load JPG
23	05/09/18 14:08	General View		Load JPG
24	05/09/18 14:08	General View		Load JPG
25	05/09/18 14:08	General View		Load JPG
26	05/09/18 14:08	General View		Load JPG
27	05/09/18 14:08	General View		Load JPG
28	05/09/18 14:08	General View		Load JPG
29	05/09/18 14:08	General View		Load JPG
30	05/09/18 14:08	General View		Load JPG

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
32	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
33	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
34	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
35	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
36	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
37	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
38	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
39	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
40	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
41	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
42	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
43	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
44	05/09/18 14:08	Odometer Reading		<input checked="" type="checkbox"/>
45	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
46	05/09/18 14:08	General View		<input checked="" type="checkbox"/>
47	05/09/18 14:08	Chassis Number		<input checked="" type="checkbox"/>
48	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
49	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
50	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
51	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
52	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
53	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
54	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
55	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
56	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
57	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
58	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
59	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
60	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
61	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
62	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
63	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
64	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
65	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
66	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
67	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
68	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
69	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
70	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
71	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
72	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
73	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
74	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
75	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
76	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
77	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
78	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
79	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
80	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
82	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
83	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
84	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
85	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
86	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
87	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
88	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
89	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
90	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
91	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
92	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
93	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
94	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
95	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
96	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
97	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
98	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
99	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
100	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
101	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
102	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
103	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
104	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
105	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
106	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
107	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
108	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
109	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
110	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
111	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
112	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
113	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
114	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
115	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
116	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
117	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
118	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
119	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
120	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
121	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
122	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
123	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
124	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
125	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
126	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
127	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
128	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
129	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>
130	16/10/18 16:05	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
131	16/10/18 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	16/10/18 16:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/08/18 10:40	TP GIA REPORT	 Load PDF	
2	17/10/18 13:46	TP ESTIMATE MARKED	 Load PDF	
3	21/11/18 17:05	LETTER TO OI	 Load PDF	
4	21/11/18 17:05	RENTAL RECEIPT	 Load PDF	
5	01/12/18 14:50	PARF_COE_REBATE	 Load PDF	
6	21/12/18 09:41	WORKSHOP INVOICE	 Load PDF	
7	21/12/18 09:41	AUTHORISATION TO ACT FORM	 Load PDF	
8	21/12/18 09:41	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	24/08/18 16:22	TP GIA	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLA6389S (Insd veh)	Model:	BMW 523I 2.5 (A)
	SGS9696A (TP veh)		
Date of Accident:	18/08/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	29,524.00
Final Repair Cost	:	\$	17,000.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	14 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	17,000.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Flying High Spray Painting	:	\$ 17,000.00
2)		:	\$

\_\_\_\_\_  
JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
21 Dec  
2018

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18015378/APA3Q2

Date: 21/12/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100454906  
**Claimant Vehicle No :** SGS9696A **Insured Vehicle No :** SLA6389S  
 Date of Loss: 18/08/2018 Nature of Claim: TP Claim No: 3913894308SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SGS9696A**  
 Make & Model: BMW 523i, 2.5 (A) Engine No: 11957800N52B25AF  
 Reg. Date: 24/06/2011 (Man. Year: 2011) Chassis No: WBAFP32020C866962  
 Colour: Black Odometer: 136956 km  
 Engine Capacity: 2497 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,234.00	15,896.65	8,337.35	34.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,290.00	3,620.00	1,670.00	31.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>29,524.00</b>	<b>19,516.65</b>	<b>10,007.35</b>	<b>33.90</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>15,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>29,524.00</b>	<b>15,600.00</b>	<b>13,924.00</b>	<b>47.16</b>
<b>+ Car Rental (14.0 x S\$150.00/day) (S\$)</b>		2,100.00		
<b>Nett Liability (S\$)</b>		<b>17,700.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>17,000.00</b>		

## INSPECTION

Date of Assignment: 21/08/2018  
 Date Inspected: 21/08/2018 Inspected At: Flying High Spray Painting (HQ)  
 BLK 1 Kaki Bukit Ave 6, #01-29 Auto Bay  
 Singapore 417883  
 Estimated Period of Repair: 11.0 days

---

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Distorted	1,532.00 F	*1,532.00 FL
4	1		*REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	2		*REAR BUMPER SIDE HOLDER	Not Necessary	270.00 F	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	698.00 F	*698.00 FL
7	1		*REAR BUMPER CENTRE GUIDE	Cracked	195.00 F	*195.00 FL
8	2		*REAR BUMPER REFLECTOR	Not Necessary	108.00 F	*- FL
9	1		*REAR BUMPER UNDER COVER	Deformed	168.00 F	*168.00 FL
10	1		*REAR BUMPER UNDER COVER CLIPS	Necessary	20.00 F	*20.00 FL
11	1		*REAR BUMPER SIDE UNDER COVER	Deformed	98.00 F	*98.00 FL
12	1		*REAR BUMPER SIDE UNDER COVER CLIPS	Necessary	10.00 F	*10.00 FL
13	1		*REAR BUMPER INNER COVER	Deformed	285.00 F	*285.00 FL
14	4		*REVERSE SENSOR	Damaged (3 PCS ONLY)	1,000.00 F	*750.00 FL
15	1		*REAR END PANEL	Dented	978.00 F	*978.00 FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	211.00 F	*211.00 FL
17	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
18	2		*TAILLAMP	Cracked	1,060.00 F	*1,060.00 FL
19	1		*BOOTLID	Dented	1,563.00 F	*1,563.00 FL
20	1		*BOOTLID LOCK	Damaged	195.00 F	*195.00 FL
21	1		*BOOTLID WEATHERSTRIPE	Cut	283.00 F	*283.00 FL
22	2		*BOOTLID REFLECTOR	Cracked	610.00 F	*610.00 FL
23	2		*BOOTLID HINGE	Not Necessary	236.00 F	*- FL
24	1		*BOOTLID INNER TRIM COVER	Not Necessary	149.00 F	*- FL
25	1		*BOOTLID INNER TRIM COVER CLIPS	Not Necessary	30.00 F	*- FL
26	1		*BMW LOGO	Necessary	69.00 F	*69.00 FL
27	1		*513I EMBLEM	Necessary	85.00 F	*85.00 FL
28	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	390.00 F	*- FL
29	1		*REAR EXHAUST PIPE	Repair	1,379.00 F	*- FL
30	1		*REAR EXHAUST MOUNTING	Not Necessary	59.00 F	*- FL
31	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	135.00 F	*- FL
32	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
33	1		*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
34	1		*FRONT BUMPER	Deformed	1,432.00 F	*1,432.00 FL
35	1		*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
36	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	158.00 F	*- FL
37	1		*FRONT BUMPER LOWER GRILLE	Deformed	109.00 F	*109.00 FL
38	1		*FRONT BUMPER REINFORCEMENT	Bent	669.00 F	*669.00 FL
39	1		*FRONT BUMPER SPONGE	Deformed	135.00 F	*135.00 FL
40	2		*FRONT BUMPER LOWER SIDE GRILLE	Not Necessary	178.00 F	*- FL
41	2		*FRONT BUMPER LOWER SIDE GRILLE MOULDING	Not Necessary	70.00 F	*- FL
42	2		*FRONT BUMPER FOG LAMP	Not Necessary	540.00 F	*- FL
43	1		*FRONT BUMPER LOGO	Necessary	68.00 F	*68.00 FL
44	4		*FRONT BUMPER SENSOR	Not Necessary	1,000.00 F	*- FL
45	2		*HEADLAMP	Cracked	4,974.00 F	*4,974.00 FL
46	2		*HEADLAMP LOWER BRACKET	Not Necessary	164.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*BONNET	Repair	2,225.00 F	*- FL
48	1		*BONNET LOCK	Not Necessary	106.00 F	*- FL
49	2		*FRONT GRILLE	Cracked	310.00 F	*310.00 FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					<b>Sub Total (\$\$)</b>	<b>24,234.00 16,727.00</b>
					<b>- List Item Discount on L Items 0.00/5.00% (\$\$)</b>	<b>0.00 830.35</b>
					<b>Total Parts (\$\$)</b>	<b>24,234.00 15,896.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,000.00	1,600.00
2	SPRAY PAINTING	New	2,000.00	1,400.00
3	WIRING	New	100.00	60.00
4	TO UNDERSEAL	New	150.00	80.00
5	TO REMOVE REVERSE SENSOR	New	120.00	80.00
6	TO REMOVE UPHOLSTERY	New	150.00	60.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
8	TO REMOVE EXHAUST PIPE	New	150.00	80.00
9	TO REMOVE FRONT BUMPER SENSOR	New	120.00	80.00
10	TO PERFORM DIANODSLIC TEST AND TO DOOR FAULT CODE	New	350.00	100.00
Gross Labour Cost (S\$)			<b>5,290.00</b>	<b>3,620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >