

NO.:

TPA 16.
Xiao TongDOA: 18/08/18
1503J

Date:

SGS9696A. 2011 Jue.

BMW 523i

WBAFP32020C866962.

Rear Number Plate	2 new	30(SN) x
Rear Number Plate Holder	1 new	30(SN) x
Rear Bumper	Distorted.	1532 ✓
Rear Bumper Clips	new	50 ✓
Rear Bumper Side Holder x 02	new	135 x 2 = 270 x
Rear Bumper Reinforcement	Set	698 ✓
Rear Bumper Centre Guide	crushed	195 ✓
Rear Bumper Reflector x 02	new	54 x 2 = 108 x
Rear Bumper Under Covers	Def d	168 ✓
Rear Bumper Under Covers Clips	new	20 ✓
Rear Bumper Side Under Covers	Def d	98 ✓
Rear Bumper Side Under Covers Clips	new	10 ✓
Rear Bumper Lanes Cover	Def d	285 ✓
Reverse Sensor x 04	2 pieces damaged	250 x 4 = 1000 750
Rear End Panel	Dented	978 ✓
Rear End Panel Top Garnish	Def d	211 ✓
Rear End Panel Sealant	new	60(SN) ✓
Taillamp x 02	crushed.	530 x 2 = 1060 ✓
Bootlid	Dented	1563 ✓
Bootlid Lock	Damaged	195 ✓
Bootlid Weatherstripe	new	283 ✓
Bootlid Reflector x 02	crushed	305 x 2 = 610 ✓
Bootlid Hinge x 02	new	118 x 2 = 236 x
Bootlid Inner Trim Cover	new	149 x
Bootlid Inner Trim Cover Clips	new	30 x
BMW Logo	2 new	69 ✓
523i Emblem	new	85 ✓
Spare Tyre Panel Top Cover	new	390 x
Rear Exhaust Pipe	Repair	1379 x
Rear Exhaust Manifold	new	59 x
Rear Exhaust Heat Shield	new	135 x

NO.:

Date:

SG89696A.

Front Number Plate Best	30(SN) ✓
Front Number Plate Holder Del	30(SN) ✓
Front Bumper Del	1432 ✓
Front Bumper Clips New	50 ✓
Front Bumper Side Holders x 02 new	79 x 2 = 158 x
Front Bumper Lower Grille Del	109 ✓
Front Bumper Reinforcement Best	669 ✓
Front Bumper Sponge Del	135 ✓
Front Bumper Lower Side Grille x 02	89 x 2 = 178 x
Front Bumper Lower Side Grille Moulding x 02 ^{2 part} new	35 x 2 = 70 x
Front Bumper Fog Lamp x 02 new	270 x 2 = 540 x
Front Bumper Logo new	68 -
Front Bumper Sensor x 04 new	250 x 4 = 1000 x
Headlamp x 02 Cracked	2487 x 2 = 4974 ✓
Headlamp Lower Bracket x 02 new	82 x 2 = 164 x
Bonnet Repr	2225 x
Bonnet Lock new	106 x
Front Grille x 02 cracked	16607 155 x 2 = 310 ✓
	1577665 SN 120

Panel Beating	2000 1600
Spray Painting	2000 1400
Wiring	100 60
To underseal	150 80
To remove reverse sensor	122 80
To remove upholstery	150 60
To transfer bootlid fittings	150 80
To remove exhaust pipe	150 80
To remove front bumper sensor	122 80
To perform diagnostic tests and to clear fault code	250 100

Consulate is hence notified

The trailer of the vehicle is hence notified

To remove front bumper sensor

To perform diagnostic tests and to clear fault code

Particulars are as follows:

- Third party survey is done on a "No Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Total 19516.65

H/S. 15.6K. 14 Days