

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5318X
Ref. No : TAX/08/18/2075
Reg. Date : 30/11/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : JEREMY TAN KIM HAI
Type of Accident : HEAD TO REAR
Date / Time of Accident : 19/08/2018 10:00:00 PM
Accident Reported Date / Time : 20/08/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097621
Special Instruction to ARC,if any :
TOS / SJT1586X - CHINA TAIPING - LKK
Prepared Date : 21/08/2018 09:35:32 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU803575427

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 507.00	0.00
Total Spray Painting Charges	: 738.00	0.00
Total Material Charges	: 2,001.85	2,001.85
Other Charges	: 460.00	0.00
TOTAL	: 3,706.85	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 4.00 3.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 21/08/2018 11:19:44 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/08/2018 11:19:44 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	507.00	0.00
Total Labour	507.00 300	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00 200	0.00
TO RESPRAY FILLER RR BUMPER RH	180.00 100	0.00
TO RESPRAY BUMPER BEAM	180.00 ?	0.00
Total Spray Painting & Panel Beating	738.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00 20	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00 x n n	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00 20	0.00
TO REPLACE SUNDRY PARTS	100.00 x n n	0.00
TO WASH AND VACUUM	60.00 x n n	0.00
Total Other Costs	460.00	0.00

NAZ LKK
 21/8/18 1100
 P/P.
 BEFORE PAINT PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No <i>CEA</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>ne</i>
52462470 30			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace	No <i>g ne</i>
52462470 20			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace	No <i>g ne</i>
52462470 10			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace	No <i>g ne</i>
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No <i>g ne</i>
52575470 40			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace	No <i>?</i>
52591470 50			SEAL, RR BUMPER , RH	1	85.20	25.00	63.90	Replace	Replace	No <i>?</i>
81581470 10			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	10.00	438.12	Replace	Replace	No <i>scr</i>
52565479 00			FILLER, RR BUMPER , RH	1	119.90	25.00	89.92	Replace	Replace	No <i>scr?</i>
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No <i>DD</i>
52169470 20			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No <i>scr</i>
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No <i>? cr</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>X JV</i>
52461470 10			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace	No <i>ne</i>
TOTAL MATERIALS								2,001.87	2,001.85	
TOTAL MATERIALS(Discounted)							2,001.85	2,001.85		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									